



600 E. Baseline Rd.
Evansville, IN 47725

www.AmericanRVCenter.com

812.867.5200
FAX 812.868.1012

W/O: 76809
Promised Date:
22 MAY 25

CUSTOMER WORK ORDER

WO #: 76809

Customer: 55823 - BLAKE, ZACHARY -
812-217-3361

Tag:

Author: BH

Location: 0602 BH TO CLOSE

Stock #: 11583

Stock Desc: 2025 TT KEYSTONE

SPRINGDALE 1800BH

Chassis #: 4YDTSGG13S7103659

Serial #: 4YDTSGG13S7103659

Mileage: 0

Licence:

Invoice #:

Date In: 21 MAY 25

Promised: 23 MAY 25

Date Sched:

Completed: 30 MAY 25

Warr. Date:

Job #FPDINTT - Internal

COMPLAINT: FINAL PDI ON NEW TRAVEL TRAILERS

CAUSE: Final pdi

CORRECTION: Lug nuts torqued to spec. Air pressure correct in all 3 tires.all running lights and brake lights and brakes and Emergency Brakes work properly. After roof inspection I found a couple voids in the sealer. Filled with black Dicor non sag. Had to adjust the striker on the entry door it wasn't closing properly. Awning work properly and fabric is good. Hooked to city water flushed lines. Water heater works properly. Heater works properly ac works properly. Stove works properly and the refrigerator works properly. And the microwave works properly. Put water in fresh tank and cleared lines. After inspection of inside i found that the paper trim is coming off front wall. I fixed the issue onthe front wall by bed. Did my lp drop test on the stove. Had to adjust my regulator down. At 50% it's was running at 12.5 i dropped it to running at 50% to 11. And it held at 8 for 5 minutes. New battery installed.

Labor

Code	Description	Mechanic	Total
PDINTT	PDI - NEW TRAVEL TRAILER	JTW	N/C
PDINTT	PDI - NEW TRAVEL TRAILER	JTW	N/C
PDINTT	PDI - NEW TRAVEL TRAILER	JTW	N/C
PDINTT	PDI - NEW TRAVEL TRAILER	JTW	N/C

Parts

Part #	Description	Qty	Price	Total
DC-24	ADVANCE GROUP 24 DEEP CYCLE BATTERY	1.00	N/C	N/C

Subtotal for Job #FPDINTT: 0.00

Job #1 - Internal

CUSTOMER PULLING ON BALL

Subtotal for Job #1: 0.00

Job #2 - Warranty

COMPLAINT: SEAM TAPE IS LOOSE RIGHT IN FRONT OF THE BATTERY

CAUSE: Final pdi

CORRECTION: Final pdi interior inspection found that the seal tape was coming off front wall by bed. I fixed it the issue.

Labor

Code	Description	Mechanic	Total
Z990	MISCELLANEOUS REPAIR	JTW	18.00



Customer #: 55823
BLAKE, ZACHARY

W/O: 76809
Promised Date: 23 MAY 25



Customer #: 55823
BLAKE, ZACHARY



Subtotal for Job #2: 18.00

Parts Total: 0.00
Labour Total: 18.00
Sublet Total: 0.00
Extras Total: 0.00

WORK ORDER TOTAL: 18.00

Thank you for being a valued customer. We appreciate your business.

All labor is guaranteed for 90 days from invoice date. Guarantee is limited to work performed. Consequential damages are not covered. All guaranteed work must be completed in our service department.

Customer Signature : _____

Date: 02 Jun 2025

