

FOREST RIVER WARRANTY CLAIM FORM

DEALER ACCOUNT #	0005106	CLAIM STATUS	Authorized
BASDEN RV CENTER INC		CLAIM	2313875
DBA AMERICAN RV CENTER		CLAIM ORIGIN	WEB
600 E BASELINE ROAD		ORIGINAL CLAIM ID	
EVANSVILLE, IN 47725		VIN	5ZT2CXR8SS047845
USA		CHASSIS VIN	
		MILEAGE	0
Labor rate:	\$185.00	SITE/WAREHOUSE	220 / 220A
OWNER INFORMATION		ITEM #	APTT264RKS
JESSICA F JOHNSON		DEALER RO #	76813
10211 OLEANDER DR		CLAIM START DATE	05/28/2025
Port Richey, FL 34668		CLAIM END DATE	01/01/1900
USA			
Retail Date of Purchase	05/23/2025	WARRANTY EXPIRATION DATE	05/23/2026

Claim Line Details

Labor

Line# 1	Operation Code	Operational Description		
	30-101-24-00-001079	Sliding, Pocket Door Track - Interior/Interior Doors/Repair/No Tread Code		
	Complaint, Cause, Correction			
	Original Note : bhoffman@americanrvcenter.com, 2025-05-28 13:32:29 :: BATHROOM DOOR TRACK IS FALLING OFF Screws are no holding in the ceiling panel. Unscrewed the trim cover and further investigated, found that there is nothing but ceiling panel holding the track up. Unhinged the door from the track. Unscrewed the track and wood from the ceiling. Measured and cut a longer piece of wood to hold the track. Set the new piece of wood in place and screwed the track to it. Now the track feels more firm to the ceiling. Put the door back on the hinges and checked for clearance. Adjusted the hinges so the door closes with no gap.			
Model#	Dlr Sub Hrs	0.60	Sub Labor Amt	\$111.00
Serial#	Appr Hrs	0.40	Appr Labor Amt	\$74.00
	Notes			
	Dealer has requested more time than what is normally approved for this repair. Forest River will allow .40 hr for this repair. If you have questions about the approved time, please contact me directly to discuss.			

Labor

Line# 2	Operation Code	Operational Description		
	30-100-01-00-001035	Cabinet Door - Interior/Cabinetry/Replace/No Tread Code		
	Complaint, Cause, Correction			
	Original Note : bhoffman@americanrvcenter.com, 2025-05-28 13:33:28 :: CABINET DOOR IN THE BEDROOM IS PEELING Cabinet door peeling Put in po for a new cabinet door NEED TO REPLACE THE DOOR			
Model#	Dlr Sub Hrs	0.40	Sub Labor Amt	\$74.00
Serial#	Appr Hrs	0.40	Appr Labor Amt	\$74.00
	Notes			
	vcv patrick			

Submitted	Labor Amt	\$185.00	Approved	Labor Amt	\$148.00
	Parts & Freight	\$0.00		Parts & Freight	\$0.00
	Total	\$185.00		Total	\$148.00

DEALER _____ DATE _____
SIGNATURE _____
I certify that I have performed these repairs consistent with Forest River Policies.

CUSTOMER _____ DATE _____
SIGNATURE _____
All repairs described have been inspected and are satisfactory.