



600 E. Baseline Rd.
Evansville, IN 47725

www.AmericanRVCenter.com

812.867.5200
FAX 812.868.1012

W/O: 76839
Promised Date:
20 MAY 25

CUSTOMER WORK ORDER

WO #: 76839

Customer: 55833 - MCCORMICK, PAUL - Stock #: 11592

812-205-5940

Tag:

Author: BH

Location: DELIVERY 0530

Stock Desc: 2025 TT COACHMEN
CATALINA SUMMIT SERIES 134RKX
Chassis #: 5ZT2CABCXSK011204
Serial #: 5ZT2CABCXSK011204
Mileage:
Licence:

Invoice #:
Date In: 23 MAY 25
Promised: 30 MAY 25
Date Sched:
Completed: 30 MAY 25
Warr. Date: 30 MAY 25



Job #FPDINTT - Internal

COMPLAINT: FINAL PDI ON NEW TRAVEL TRAILERS

CAUSE: Final pdi

CORRECTION: Torqued lug nuts to spec. Installed new battery. Air pressure correct spec. Running lights work properly tail lights work properly and brakes and Emergency Brakes work properly. Awning fabric is good Awning lights work properly. Smoke alarm and Ip detector work properly. Furnace and ac works properly. Stove and microwave works properly found water leak under shower at the drain. Cold water lines under sink that goes through the wall really vibrates when using water pump. I used a sip tie to tie the cold and the hot lines together to stop the vibration sound antenna works. Did my Ip drop test on stove and everything worked properly. Mini blind over the sink was missing the adjustment rod. I got a new one. Had to adjust the brackets on the stairs they hit the door when folding them up. And put some clear silicone on the table on the grab handle.

Customer #: 55833
MCCORMICK, PAUL

Labor

Code	Description	Mechanic	Total
PDINTT	PDI - NEW TRAVEL TRAILER	JTW	N/C
PDINTT	PDI - NEW TRAVEL TRAILER	JTW	N/C
PDINTT	PDI - NEW TRAVEL TRAILER	JTW	N/C
PDINTT	PDI - NEW TRAVEL TRAILER	JTW	N/C
PDINTT	PDI - NEW TRAVEL TRAILER	JTW	N/C
PDINTT	PDI - NEW TRAVEL TRAILER	JTW	N/C

Parts

Part #	Description	Qty	Price	Total
DC-24	ADVANCE GROUP 24 DEEP CYCLE BATTERY	1.00	N/C	N/C
A303	A303 MINI BLIND WAND	1.00	N/C	N/C

Subtotal for Job #FPDINTT: 0.00

Job #BCWT - Internal

COMPLAINT: INSTALL DIGITAL, PROPORTIONAL BRAKE CONTROL IN TRUCK/SUV

CAUSE: Van needs a brake controller installed

CORRECTION: I ran wiring for the trailer brake controller under the dash to the battery. Then I ran the trailer brake wiring to the rear of the van. I wired in the brake wire and the trailer charge wire to the 7-way on the rear of the van. I added a breaker under the hood for the brake controller and trailer charge wire.

Labor

Code	Description	Mechanic	Total
BCWT	BRAKE CONTROL & WIRING - PICKUP	GAH	N/C



Parts

Part #	Description	Qty	Price	Total
14636	7WAY PLASTIC CAR END	1.00	N/C	N/C
19-1441	16-3030 30A CIRCUIT BREAKER	1.00	N/C	N/C
42225	WIRING KIT - CARAVAN	1.00	N/C	N/C
72-2535	58000 CURT RECEIVER 7 WAY BRKT	1.00	N/C	N/C
17-0081	DISCOVERY "NEXT" BRAKE CONTROLLER	1.00	N/C	N/C

Other Services

Code	Description	Qty	Price	Total
SS	SHOP SUPPLIES	1.00	N/C	N/C

Subtotal for Job #BCWT: 0.00

Job #E2 - Internal

COMPLAINT: 10K E2 EQUALIZER HITCH

CAUSE: E2 hitch
 New hitch setup and adjustment

CORRECTION: Installed the brackets to the camper for a E2 hitch
 Leveled the camper then checked the height and matched the van. Had to get a different hitch bar for proper tow. Connected the camper to the van and adjusted as needed. Connected the 7-way, coupler, breakaway cable and safety chains. Tightened all hardware.

Labor

Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	SAR	N/C
Z990	MISC LABOUR CODE (EXTERNAL)	JTW	N/C
Z990	MISC LABOUR CODE (EXTERNAL)		N/C

Parts

Part #	Description	Qty	Price	Total
14-1641	1000# E2 TRUNION HITCH W/BALL	1.00	N/C	N/C
14-2931	90-02-4300 EQUALIZER ADJ HITCH SHANK	1.00	N/C	N/C

Subtotal for Job #E2: 0.00

Job #3001 - Internal

COMPLAINT: RECEIVER - UNIVERSAL VAN

CAUSE: Unit needs receiver and taillight converter installed

CORRECTION: I installed the universal receiver on the rear of the van. I removed the taillight and ran wiring for the taillight converter. Wired the taillight converter to the new 7-way installed on the receiver.

Labor

Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	GAH	N/C

Parts

Part #	Description	Qty	Price	Total
13362	96-07 CARAVANTOWN & COUNTRY(NOT STO	1.00	N/C	N/C

Other Services

Code	Description	Qty	Price	Total
FRT	FREIGHT	1.00	N/C	N/C

Subtotal for Job #3001: 0.00

Job #1 - Warranty

COMPLAINT: WATER LEAKING AT THE SHOWER ON THE DRAIN WHILE THE WATER IS RUNNING



Customer #: 55833
 MCCORMICK, PAUL



CAUSE: Shower leaking water

CORRECTION: The pvc nuts on the shower drain was loose. I hand tightened it and the tightened it with a wrench. No water leak now.

Labor Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	JTW	55.50
Subtotal for Job #1:			55.50

Parts Total:	0.00
Labour Total:	55.50
Sublet Total:	0.00
Extras Total:	0.00
WORK ORDER TOTAL:	55.50

Thank you for being a valued customer. We appreciate your business.

All labor is guaranteed for 90 days from invoice date. Guarantee is limited to work performed. Consequential damages are not covered. All guaranteed work must be completed in our service department.

Customer Signature : _____

Date: 02 Jun 2025

W/O: 76839
Promised Date: 30 MAY 25



Customer #: 55833
MCCORMICK, PAUL

