



600 E. Baseline Rd.
Evansville, IN 47725

www.AmericanRVCenter.com

812.867.5200
FAX 812.868.1012

W/O: 76871
Promised Date:
24 MAY 25



Customer #: 1000
BASDEN'S AMERICAN RV,



CUSTOMER WORK ORDER

WO #: 76871

Customer: 1000 - BASDEN'S AMERICAN
RV -

Tag:

Author: PH

Location: 0606 BH TO CLOSE

Stock #: 11609

Stock Desc: 2025 TT COACHMEN
CATALINA 293QBCKLE

Chassis #: 5ZT2CAUB0SN301650

Serial #: 5ZT2CAUB0SN301650

Mileage: 0

Licence:

Invoice #:

Date In: 29 MAY 25

Promised: 31 MAY 25

Date Sched:

Completed: 30 MAY 25

Warr. Date:

Job #PDINTT - Internal

COMPLAINT: PDI - NEW TRAVEL TRAILER

CAUSE: Pdi

CORRECTION: VIN check, checked all of the following condition of the battery and battery cables and connections, condition of the trailer coupler, the safety chain, operation of the tongue jack, running lights, brake lights, and turn signals, breakaway cable and brakes, Plug in the shore power cord, fresh water drain caps, wastewater cap and close waste system valves, inspect brake wires, shackles, axle, LP lines and clamp spacing, the underbelly for holes, gaps, and loose materials, Pressurize the city water system and check for leaks/missing caps on drain lines.. Inspect and clean out exterior appliance compartments (refrigerator, water heater, furnace), preformed a lp drop test and checked for leaks in lines, Check exterior lights, windows and vents for fit and finish.. Inspect storage compartment, emptied black and grey tanks

Labor

Code	Description	Mechanic	Total
Z991	MISC LABOUR CODE (INTERNAL)	JLC	N/C
Z991	MISC LABOUR CODE (INTERNAL)	JLC	N/C
Z991	MISC LABOUR CODE (INTERNAL)	JLC	N/C
Z991	MISC LABOUR CODE (INTERNAL)	JLC	N/C
Z991	MISC LABOUR CODE (INTERNAL)	JLC	N/C
Z991	MISC LABOUR CODE (INTERNAL)	JLC	N/C

Parts

Part #	Description	Qty	Price	Total
13034	55362 STD BATTERY BOX	1.00	N/C	N/C

Other Services

Code	Description	Qty	Price	Total
SS	SHOP SUPPLIES	1.00	N/C	N/C
LPGI	LP - UNIT SALES	8.00	N/C	N/C

Subtotal for Job #PDINTT: 0.00

Job #1 - Warranty

COMPLAINT: CABINET DOOR HINDGE LOOSE


CAUSE: Cabinet door

CORRECTION: Cabinet door was loose, so took out old screws got new ones that are longer and now shuts correctly

Labor

Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	JLC	18.50





Subtotal for Job #1: 18.50

Job #2 - Warranty

COMPLAINT: WALL PAPER IN THE SLIDE ROOM COMING LOOSE

CAUSE: Vinyl trim was loose

CORRECTION: The trim was loose in the ceiling in the slide room, so took a roller to it too smooth it out and now is smoother than before

Labor			
Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	JLC	18.50

Subtotal for Job #2: 18.50

Job #3 - Warranty

COMPLAINT: THE CURTAIN FELL IN THE SLIDE ROOM AND NEEDS TO BE REINSATLLED

CAUSE: Curtain

CORRECTION: Curtain was not hung up correctly so had to get a different piece of velcro to put on it so it hangs up correctly

Labor			
Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	JLC	18.50

Subtotal for Job #3: 18.50

Job #4 - Warranty

COMPLAINT: BATHROOM DOOR NOT SHUTTING

CAUSE: Bathroom door

CORRECTION: Adjusted the bathroom door so the door will shut properly and adjust the screws

Labor			
Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	JLC	37.00

Subtotal for Job #4: 37.00

Job #5 - Warranty

COMPLAINT: FIRE EXT HOLDER NOT INSTALLED RIGHT

CAUSE: Fire extinguisher

CORRECTION: Took off wall mount and reposition in new place now fire extinguisher is put in correctly

Labor			
Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	JLC	9.25

Subtotal for Job #5: 9.25

Job #6 - Warranty

COMPLAINT: ENTRY DOOR NOT SHUTTING

CAUSE: Entry door

CORRECTION: Adjusted the entry door now door will shut properly

Labor			
Code	Description	Mechanic	Total



Subtotal for Job #6:55.50

Job #7 - Warranty

COMPLAINT: DOOR FRAME PLASTIC NEAR THE SLIDING DOOR IS COMING LOOSE AND NEEDS TO BE REINSTALLED

CAUSE: Plastic near door

CORRECTION: Pushed and reglued the door frame and now is not coming apart

Labor Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	JLC	37.00
Subtotal for Job #7:			37.00

Job #8 - Warranty

COMPLAINT: WALL PAPER IN THE BUNK NEAR THE BED LATCH IS COMING LOOSE

CAUSE: Wallpaper

CORRECTION: Took staple out of bedroom wall for wallpaper to set in better now isn't that noticeable

Labor Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	JLC	18.50
Subtotal for Job #8:			18.50

Parts Total:0.00Labour Total:212.75Sublet Total:0.00Extras Total:0.00WORK ORDER TOTAL:212.75

Thank you for being a valued customer. We appreciate your business.

All labor is guaranteed for 90 days from invoice date. Guarantee is limited to work performed. Consequential damages are not covered. All guaranteed work must be completed in our service department.

Customer Signature : _____

Date: 06 Jun 2025

W/O: 76871
Promised Date: 31 MAY 25

Customer #: 1000
BASDEN'S AMERICAN RV,