

BASDEN RV CENTER, INC dba AMERICAN RV
 600 E. Baseline Rd.
 Evansville, IN
 US
 47725
 812-867-5200

WARRANTY CLAIM # 76894
 MANUFACTURER'S CLAIM #:

Manufacturer: 10024 - FOREST RIVER TRAVEL TRAILER
 Customer: 55123 - RICHARD POHL
 Address: 120 W 975 S HAUBSTADT, IN

47639

Phone: 812-779-6831

Stock Number: 11413 - 2024 CATALINA 293QBCKLE 5ZT2CAUB0RN300461

VIN: 5ZT2CAUB0RN300461 HIN: SER#: 5ZT2CAUB0RN300461

Mileage: 0 Work Order Comp: 05 JUN 25

Auth. No: Dealer #:

Warr. Date: 16 AUG 24 Work Order Date: 02 JUN 25 Inv #: 418335

WO #	Job #	Description	JOB INFORMATION
76894	2	25V264 THE FRONT EXTERIOR ACCENT LAMP WIRE (16AWG) MAY BE ON A 30 AMP BREAKER, WHEREAS IT SHOULD BE ON A 10 AMP OVER CURRENT DEVICE. THE AWNING MAY BE MISSING THE REQUIRED 15AMP OVER CURRENT PROTECTION. THE AUTO-LEVELING SYSTEM MAY BE WIRED TO CONSTANT HO ON A 30 AMP MINI-BREAKER.	1, no Accent Lamps. 2, Self Leveling system needed a breaker added. 3, awning power wire needed a 15a inline fuse added. There was no Accent Lamps oin this unit. There is a Self Leveling System on this unit. This unit did not have removable Lag Screw so i cut a access hole in area where Wires from battery entered the underbelly. there was no conjoining breakers on this unit. recieved 30A breaker and copper Buss from Parts. removed Terminals from Battery. Removed wires from installed Breaker. Mounted 2nd breaker next to 1st Breaker and conjoined breakers with Buss Bar.Mounted Wires in explained areas from Recalls directions. Hooked Terminals back to Battery and turned on Battery Disconnect and tested operations... All are function correctly. Ziptied Wires in underbelly to secure them and closed cut out panel with underbelly Tape. There is a Awning on this unit. Removed inside panel in cabinet located behind the Control Center. Located the Yellow Awning Power Wire. Installed a 15A Inline Fuse on Awning Power Wire and hooked it back up to the Control Box. Tested Awning operations which worked properly. Secured the inner wires and reinstalled Panel inside Cabinet.

Part No	Job#	Description	PARTS	Qty	Price	Total
BDR31820	2	Fuse Holder; ATO/ ATC Blade Fuses		1.00	8.96	8.96

Claim : 76894

```
*****
Part No      Job#  Description          PARTS          Qty    Price    Total
*****
CUR58361     2    16-3030 30A CIRCUIT BREAKER          1.00    3.85    3.85
*****
```

```
*****
Lab Code     Job#  Description          LABOUR          Hrs    Rate    Total
*****
Z990         2    MISC LABOUR CODE (EXTERNAL)          0.75   185.00   138.75
Z990         2    MISC LABOUR CODE (EXTERNAL)          0.50   185.00    92.50
*****
```

Parts Total: 12.81
Labour Total: 231.25
Sublet Total: 0.00
Extras Total: 0.00

>>>> Claim Total: 244.06

Customer Signature: _____

Date: _____