

FOREST RIVER WARRANTY CLAIM FORM

DEALER ACCOUNT #	0005106	CLAIM STATUS	Authorized
BASDEN RV CENTER INC		CLAIM	2331648
DBA AMERICAN RV CENTER		CLAIM ORIGIN	WEB
600 E BASELINE ROAD		ORIGINAL CLAIM ID	
EVANSVILLE, IN 47725		VIN	5ZT2CAXB6SX033056
USA		CHASSIS VIN	
		MILEAGE	0
Labor rate:	\$185.00	SITE/WAREHOUSE	205 / 205
OWNER INFORMATION		ITEM #	ACAT323BHDSCKLE
RYAN N ALLEN		DEALER RO #	76901
804 WEST ELM ST		CLAIM START DATE	06/12/2025
Haubstadt, IN 47639		CLAIM END DATE	01/01/1900
USA			
Retail Date of Purchase	06/09/2025	WARRANTY EXPIRATION DATE	06/09/2026

Claim Line Details

Labor

Line# 1	Operation Code	Operational Description		
	60-143-01-00-001634	Exterior Shower Vent Cover - Plumbing/Exterior Shower/Replace/No Tread Code		
	Complaint, Cause, Correction			
	Original Note : bhoffman@americanrvcenter.com, 2025-06-12 10:49:33 :: SHOWER VENT IS BUSTED ON THE ROOF Bathroom vent busted On my roof inspection found that the bathroom roof vent was busted. So I removed the broken one and the sealer. Put on a new roof vent i used Dicor self-leveling to seal it up.			
Model#	Dlr Sub Hrs	0.40	Sub Labor Amt	\$74.00
Serial#	Appr Hrs	0.20	Appr Labor Amt	\$37.00
	Notes			
	AUTHORIZED AS SUBMITTED			

Labor

Line# 2	Operation Code	Operational Description		
	60-136-01-00-001480	City Water Connection - Plumbing/Fresh Water Supply/Replace/No Tread Code		
	Complaint, Cause, Correction			
	Original Note : bhoffman@americanrvcenter.com, 2025-06-12 10:50:27 :: CITY WATER LINE LEAKING City water inlet check valve leaking Replaced the city water inlet because the check valve was leaking.			
Model#	Dlr Sub Hrs	0.30	Sub Labor Amt	\$55.50
Serial#	Appr Hrs	0.30	Appr Labor Amt	\$55.50
	Notes			

Labor

Line# 3	Operation Code	Operational Description		
	30-307-01-00-000920	Fireplace Remote Control - Interior/Fireplace/Replace/No Tread Code		
	Complaint, Cause, Correction			
	Original Note : bhoffman@americanrvcenter.com, 2025-06-12 10:51:31 :: MISSING FIRE PLACE REMOTE FIRE PLACE MISSING NEED TO PULL THE FIRE PLACE AND GET THE MODEL NUMBER ANDORDER A NEW ONE			
Model#	Dlr Sub Hrs	0.10	Sub Labor Amt	\$18.50
Serial#	Appr Hrs	0.10	Appr Labor Amt	\$18.50
	Notes			
	AUTHORIZED AS SUBMITTED			

Labor

Line# 4	Operation Code	Operational Description		
	30-103-24-00-001125	Linoleum - Interior/Flooring/Repair/No Tread Code		
	Complaint, Cause, Correction			
	Original Note : bhoffman@americanrvcenter.com, 2025-06-12 10:52:24 :: BUBBLE IN LINO IN HALLWAY BY FURNACE VENT Linolium Removed floor heat vent. Put glue under area needed. Cleaned up. Put ventback.			
Model#	Dlr Sub Hrs	0.30	Sub Labor Amt	\$55.50

Serial#

Appr Hrs

0.30

Appr Labor Amt \$55.50

Notes

AUTHORIZED AS SUBMITTED

Submitted

Labor Amt	\$203.50
Parts & Freight	\$0.00
Total	\$203.50

Approved

Labor Amt	\$166.50
Parts & Freight	\$0.00
Total	\$166.50

DEALER

DATE

SIGNATURE

I certify that I have performed these repairs consistent with Forest River Policies.

CUSTOMER

DATE

SIGNATURE

All repairs described have been inspected and are satisfactory.