



600 E. Baseline Rd.
Evansville, IN 47725

www.AmericanRVCenter.com

812.867.5200
FAX 812.868.1012

W/O: 76901
Promised Date:
06 JUN 25

CUSTOMER WORK ORDER

WO #: 76901

Customer: 55203 - ALLEN, RYAN -
812-270-3184

Tag:

Author: BH

Location: 0616 CHECK PREAUTH

Stock #: 11472

Stock Desc: 2025 TT COACHMEN

CATALINA 323BHDSCLE

Chassis #: 5ZT2CAXB6SX033056

Serial #: 5ZT2CAXB6SX033056

Mileage: 0

Licence:

Invoice #:

Date In: 02 JUN 25

Promised: 06 JUN 25

Date Sched:

Completed: 16 JUN 25

Warr. Date: 06 JUN 25

Job #FPDINTT - Internal

COMPLAINT: FINAL PDI ON NEW TRAVEL TRAILERS

CAUSE: Final pdi

CORRECTION: All lug nuts torqued to spec. 65 psi in all 5 tires. Brakes and Emergency Brakes work properly. All running lights and tail lights work properly. Installed a new battery. Roof inspection found broken bathroom vent. Replaced it and sealed it with Dicor self-leveling. And there was a spot on right front that I used black Dicor to seal that up. Roof looks good now. Checked all the window seals and the outside compartments all work properly and seals are good. Ac and furnace works properly. Flushed all the water lines sinks and shower and toilet work properly. Lp and smoke alarm works properly. Stove and oven works properly. All interior lights work. Awning fabric is good and it works properly. Range hood fan and light work properly. City water inlet check valve is bad. Put a new one on and it works properly. Fireplace is missing its remote. Gas water heater works properly but the fault light is on when it is running. Checked antenna works properly outside grill works properly. Had to turn lp tanks around and regulator because they were forward facing. Did my lp drop test on outside port with stove and furnace running. Regulator was good now adjustment needed. Drivers side fender was hitting the slide out room. So I cut some off for clearance. Drained black and grey tanks left 1/3 in fresh tank.

Labor

Code	Description	Mechanic	Total
PDINTT	PDI - NEW TRAVEL TRAILER	JTW	N/C
PDINTT	PDI - NEW TRAVEL TRAILER	JTW	N/C
PDINTT	PDI - NEW TRAVEL TRAILER	JTW	N/C
PDINTT	PDI - NEW TRAVEL TRAILER	JTW	N/C
PDINTT	PDI - NEW TRAVEL TRAILER	JTW	N/C
PDINTT	PDI - NEW TRAVEL TRAILER	JTW	N/C

Parts

Part #	Description	Qty	Price	Total
DC-24	ADVANCE GROUP 24 DEEP CYCLE BATTERY	1.00	N/C	N/C
5516	A10-3050FHVP 30M-50F PIGTAIL	1.00	N/C	N/C
F100307355	FIRELACE REMOTE	1.00	N/C	N/C
11-0429	39463 SEWER CAP W/HOSE CONNECTION	1.00	N/C	N/C

Subtotal for Job #FPDINTT: 0.00

Job #SWAP - Internal

COMPLAINT: SWAP CUSTOMER'S HITCHWORK

CAUSE: Swapped customer hitch setup from trade in



Customer #: 55203
ALLEN, RYAN



CORRECTION: Unhinged the snap up brackets from the camper and unbolted the snapup brackets and sway ball. Noticed the customer was missing the washer shims from the hitch. Drove the vehicle to the walkthru. Leveled the camper, then matched the ball height. Measured and drilled holes for the sway ball and mounted the snap up brackets. Put in washer shims in the hitch and tightened. Connected the vehicle and camper. Connected the 7-way, coupler, breakaway cable and safety chains. Checked the ride height. Checked the running lights.

Labor			
Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	SAR	N/C

Other Services				
Code	Description	Qty	Price	Total
SS	SHOP SUPPLIES	0.00	N/C	N/C

Subtotal for Job #SWAP: 0.00

Job #1 - Warranty

COMPLAINT: SHOWER VENT IS BUSTED ON THE ROOF

CAUSE: Bathroom vent busted

CORRECTION: On my roof inspection found that the bathroom roof vent was busted. So I removed the broken one and the sealer. Put on a new roof vent i used Dicor self-leveling to seal it up.

Labor			
Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	JTW	37.00

Parts				
Part #	Description	Qty	Price	Total
31-8490	40033 REPLACE ALL PLUMBING VENT	1.00	5.09	5.09
13-1320	PW HAPS FREE SELF-LEVELING DICOR	1.00	8.26	8.26

Subtotal for Job #1: 50.35

Job #2 - Warranty

COMPLAINT: CITY WATER LINE LEAKING

CAUSE: City water inlet check valve leaking

CORRECTION: Replaced the city water inlet because the check valve was leaking.

Labor			
Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	JTW	55.50

Parts				
Part #	Description	Qty	Price	Total
10-1105	62165 PW METAL MPT CITY WATER FLANGE	1.00	14.27	14.27

Subtotal for Job #2: 69.77

Job #3 - Warranty

MISSING FIRE PLACE REMOTE

Labor			
Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	JTW	18.50

Other Services				
Code	Description	Qty	Price	Total
FRT	UPS-REMOTE	1.00	15.58	15.58

Subtotal for Job #3: 34.08



Job #4 - WarrantyCOMPLAINT: BUBBLE IN LINO IN HALLWAY BY FURNACE
VENT

CAUSE: Linolium

CORRECTION: Removed floor heat vent. Put glue under area needed. Cleaned up. Put ventback.

Labor

Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	BB	55.50

Subtotal for Job #4: 55.50

Parts Total:	27.62
Labour Total:	166.50
Sublet Total:	0.00
Extras Total:	15.58
WORK ORDER TOTAL:	209.70

Thank you for being a valued customer. We appreciate your business.

All labor is guaranteed for 90 days from invoice date. Guarantee is limited to work performed. Consequential damages are not covered. All guaranteed work must be completed in our service department.

Customer Signature : _____

Date: 16 Jun 2025

W/O: 76901
Promised Date: 06 JUN 25Customer #: 55203
ALLEN, RYAN