



Warranty Authorization Form

Date: 6/23/2025

Basden RV Center, Inc. DBA/ American RV
600 E Baseline Rd
Evansville, IN 47725
Ph. (812) 867-5200
cbruce@americanrvcenter.com

General Information

Pre-Auth #: 96540 Unit: 7M5FA2821SA009937
Series: Avenue Model: 2025AVE23ML
Notes:
Status: Approved

Dealer Information

American RV
(812) 867-5200
cbruce@americanrvcenter.com

Basden RV Center, Inc. DBA/ American RV
600 E Baseline Rd
Evansville, IN 47725

Requestor: Ben Hoffman
Return Fax #:
Email: bhoffman@americanrvcenter.com

Operation Line 1

Flat Rate Code: 22434 SLIDEOUT FASCIA - EXTERIOR - REPAIR

Fault Code: IMPROPERLY INSTALLED

Serial #:

Model #:

Notes:

Problem: Screw in slide out rail is sheared off. Currently covered with silicone.

Time Requested: .1

Cause: Screw broke off

Time Allowed: .1

Remedy: Used a self tapper and put a screw next to the broken one and sealed it with white silicone. Look good

Sublet Repairs: 0.00

Part Return Req: No

Status: Approved

Operation Line 2

Flat Rate Code: 14085 TRIM - INTERIOR - REPAIR

Fault Code: LOOSE

Serial #:

Model #:

Notes:

Problem: Bedroom driver side trim is bowed ?and needs a staple/nail or two.

Time Requested: .1

Cause: Bedroom trim bowed

Time Allowed: .1

Remedy: Trim was loose and I shot a couple nails in the trim. Looks good now

Sublet Repairs: 0.00

Part Return Req: No

Status: Approved

Operation Line 3

Flat Rate Code: 10012 AXLE - REPAIR WIRING

Fault Code: IMPROPERLY INSTALLED

Serial #: NA

Model #: NA

Notes:

Problem: Rear left brake wires need reattached to hub. Looks like a broken clip.

Time Requested: .2

Cause: Left side rear brake wires hanging down

Time Allowed: .2

Remedy: Plastic clip that holds the brake wires is broken. So I secured the wires with a zip tie nice and neat

Sublet Repairs: 0.00

Part Return Req: No

Status: Approved