



600 E. Baseline Rd.
Evansville, IN 47725

www.AmericanRVCenter.com

812.867.5200
FAX 812.868.1012

W/O: 76937
Promised Date:
20 JUN 25

CUSTOMER WORK ORDER

WO #: 76937 (Appointment Date: 04 JUN 2025 - Time: 01:00pm)

Customer: 55093 - MCCOMBS, DARREN Stock #: 11496

- Stock Desc: (11496) 2025 ALLIANCE RV
Tag: AVENUE 23ML

Author: BJW Chassis #: 7M5FA2821SA009937

Location: 0623 BH TO CLOSE Serial #: 7M5FA2821SA009937

Mileage:

Licence:

Invoice #:

Date In: 04 JUN 25

Promised: 30 JUN 25

Date Sched:

Completed: 23 JUN 25

Warr. Date: 08 NOV 24

Job #1 - External

install table has open ro

Other Services

Code	Description	Qty	Price	Total
SS	SHOP SUPPLIES	1.00	N/C	N/C
Subtotal for Job #1:				0.00

Job #2 - Internal

COMPLAINT: ? Leaky front black/grey tank valve - water is making it past the knife valves. Not sure if grey or black. I have an aftermarket valve on this as a quick fix. Please check grey and black tank valves on front of rig. Cable Pulls are in the pass through.

CAUSE: Black k or gray valves not shutting completely

CORRECTION: After inspection of the black and gray shut offs. They seemed to be working properly. I put 1/3 of water in each tank. And didn't have any water getting by. It set over night with 1/3 in each tank and did not see any signs of pass by the valve there was nothing in the bucket I had sitting there. Now there may be some water still in the pipes after dumping that customer may notice. But I worked both valves and they worked properly.

Labor

Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	JTW	N/C
Z990	MISC LABOUR CODE (EXTERNAL)	JTW	N/C

Parts

Part #	Description	Qty	Price	Total
4351	QUICK ROOF EXTREME - BLACK FOR RV'S	1.00	N/C	N/C

Subtotal for Job #2: 0.00

Job #3 - Warranty

COMPLAINT: Screw in slide out rail is sheared off. Currently covered with silicone.

CAUSE: Screw broke off

CORRECTION: Used a self tapper and put a screw next to the broken one and sealed it with white silicone. Look good

Labor

Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	JTW	18.50



Customer #: 55093
MCCOMBS, DARREN

W/O: 76937
Promised Date: 30 JUN 25



Customer #: 55093
MCCOMBS, DARREN



Subtotal for Job #3: 18.50

Job #4 - Warranty

COMPLAINT: Bedroom driver side trim is bowed ?and needs a staple/nail or two.

CAUSE: Bedroom trim bowed

CORRECTION: Trim was loose and I shot a couple nails in the trim. Looks good now

Labor Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	JTW	18.50

Subtotal for Job #4: 18.50

Job #5 - Warranty

COMPLAINT: Rear left brake wires need reattached to hub. Looks like a broken clip.

CAUSE: Left side rear brake wires hanging down

CORRECTION: Plastic clip that holds the brake wires is broken. So I secured the wires with a zip tie nice and neat

Labor Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	JTW	37.00

Subtotal for Job #5: 37.00

Parts Total:	0.00
Labour Total:	74.00
Sublet Total:	0.00
Extras Total:	0.00
WORK ORDER TOTAL:	74.00

Thank you for being a valued customer. We appreciate your business.

All labor is guaranteed for 90 days from invoice date. Guarantee is limited to work performed. Consequential damages are not covered. All guaranteed work must be completed in our service department.

Customer Signature : _____

Date: 23 Jun 2025

