

Claim: C3841258

Last Modified byambri

Deny code	Item number	Name	Quantity	Qty Returned	Dealer price	Markup	Part total	Appr Freight	Sub Freight	Sublet	Status
	492981	Water Heater - Tankless "On	1.00	1.00	530.10	30.00	689.13	50.00	0.00	0.00	Approved

Component Model: 1 **Component Serial Number:** 31 12/9/2024

Deny code	Operation	Description	Srvc advisory	Sub hours	Apvd Hours	Labor amt	Sublet	Qty	Base Hours	Status
	4154006B	Water Heater - Tankless - Replac		1.20	1.20	216.00	0.00	1	1.00	Approved

Correction: Turned on water pump and LP. Ran hot water at sink and it came in fairly quick and was Warm. Checked all areas where lines are exposed for kinks or pinches but all flow to all lines and pressure is efficient. Ran Hot Water at Bathroom sink with the Temp setting at 120* and with a manual thermometer read 101* and a digital (about 30 seconds later) read 98.2! Temp is not reaching what the wall unit says so I believe it's in the Water Heater.

KRV- replace water heater VCB.

Claim Response

Submitted parts & subLet	823.80
Submitted labor & subLet	216.00
Submitted freight:	0.00
Tax:	0.00
Total Submitted:	<u>1,039.80</u>

Approved parts & subLet	689.13
Approved labor & subLet	216.00
Approved freight	50.00
Tax:	0.00
Total approved:	<u>955.13</u>