

BASDEN RV CENTER, INC dba AMERICAN RV
600 E. Baseline Rd.
Evansville, IN
US
47725
812-867-5200

WARRANTY CLAIM # 77018
MANUFACTURER'S CLAIM #:

Manufacturer: 10024 - FOREST RIVER TRAVEL TRAILER
Customer: 1000 - BASDEN'S AMERICAN RV
Address: 600 E. BASELINE RD. EVANSVILLE, IN
USA
47725
Phone:
Stock Number: 11625 - 2026 CHEROKEE GREY WOLF 26DBH 4X4TCKB29TK096289
VIN: 4X4TCKB29TK096289 HIN: SER#: 4X4TCKB29TK096289
Mileage: 0 Work Order Comp: 28 JUN 25
Auth. No: Dealer #:
Warr. Date: Work Order Date: 13 JUN 25 Inv #: 419256

WO # Job # Description JOB INFORMATION

77018 10 LP TANK VALVE GASKET HAS COME OUT
Lp tank
Took lp to go fill up when I started to fill tank the hose wasn't
fitting correctly so looked on tank and noticed the o ring was
messed up so went and got a new tank from pants to preform lp
drop test

77018 1 ENTRY DOOR SCREEN DOOR
Entry door
The entrydoor frame was bent so i pushed it back and now the
screen door will shut

77018 2 LIGHT IN FLICKERING
Light
Light was flickering due to a loose wire so I took off light
cover removed loose wire and then put back into the correct spot
now light isn't flickering

77018 3 2 CABINET DOOR LOOSE
Cabinet door
Doors were loose from screws so drilled them tighter now shuts
better

77018 4 BEDROOM DOOR HAD TO OPEN
Bedroom door
Bedroom door was hard to open due to a screw in the way so took

Claim : 77018

 WO # Job # Description JOB INFORMATION

screw out now door shuts

77018	5	DRAWER IN KITCHEN STICKS Cabnet drawer The drawer was hard to open so adjusted how the drawer sits in the frame and will shut smoother now without papers being in the way causing it not to shut completly
77018	6	REAR ENTRY DOOR Back door Re adjusted back door lock and latch and now door will shut properly
77018	7	MARK ON CEILING IN BATHROOM Mark on ceiling Mark on ceiling and caused small stain so I took a paint maker and also some mineral spirits and took Mark off the ceiling
77018	8	BATHROOM DOOR NEEDS ADJUSTED Door Bathroom door hard to open so adjusted the frame where latch goes in and now shuts perfectly fine
77018	9	STAPLE HOLES IN WOOD NEAR BATHROOM DOOR Staple holes Took some wood putty and tried to match with wood color and fill in the staple holes with the putty

 Part No Job# Description PARTS Qty Price Total

 FLKYSN201 10 L.P.CYLINDER 20 LB. PW 1.00 63.91 63.91

 Lab Code Job# Description LABOUR Hrs Rate Total

 Z990 10 MISC LABOUR CODE (EXTERNAL) 0.20 185.00 37.00
 Z990 1 MISC LABOUR CODE (EXTERNAL) 0.10 185.00 18.50
 Z990 1 MISC LABOUR CODE (EXTERNAL) 0.10 185.00 18.50
 Z990 2 MISC LABOUR CODE (EXTERNAL) 0.20 185.00 37.00
 Z990 3 MISC LABOUR CODE (EXTERNAL) 0.20 185.00 37.00
 Z990 4 MISC LABOUR CODE (EXTERNAL) 0.10 185.00 18.50
 Z990 5 MISC LABOUR CODE (EXTERNAL) 0.20 185.00 37.00
 Z990 6 MISC LABOUR CODE (EXTERNAL) 0.20 185.00 37.00
 Z990 7 MISC LABOUR CODE (EXTERNAL) 0.10 185.00 18.50
 Z990 8 MISC LABOUR CODE (EXTERNAL) 0.20 185.00 37.00
 Z990 9 MISC LABOUR CODE (EXTERNAL) 0.10 185.00 18.50

Claim : 77018

Lab Code Job# Description LABOUR Hrs Rate Total

Parts Total: 63.91
Labour Total: 314.50
Sublet Total: 0.00
Extras Total: 0.00

>>>> Claim Total: 378.41

Customer Signature: _____

Date: _____