

FOREST RIVER WARRANTY CLAIM FORM

DEALER ACCOUNT # 0005106		CLAIM STATUS Authorized
BASDEN RV CENTER INC		CLAIM 2349354
DBA AMERICAN RV CENTER		CLAIM ORIGIN WEB
600 E BASELINE ROAD		ORIGINAL CLAIM ID
EVANSVILLE, IN 47725		VIN 4X4TCKB29TK096289
USA		CHASSIS VIN
		MILEAGE 0
Labor rate: \$185.00		SITE/WAREHOUSE 094 / 094A
OWNER INFORMATION		ITEM # CKT26DBH-94
		DEALER RO # 77018
		CLAIM START DATE 06/27/2025
		CLAIM END DATE 01/01/1900

Retail Date of Purchase

WARRANTY EXPIRATION DATE

Claim Line Details

Labor

Line# 1	Operation Code 20-66-02-00-000678	Operational Description Screen Door - Exterior/Entry Doors/Adjust/No Tread Code
	Complaint, Cause, Correction Original Note : bhoffman@americanrvcenter.com, 2025-06-27 13:28:13 :: ENTRY DOOR SCREEN DOOR Entry door The entrydoor frame was bent so i pushed it back and now the screen door will shut	
Model#	Dlr Sub Hrs 0.20	Sub Labor Amt \$37.00
Serial#	Appr Hrs 0.20	Appr Labor Amt \$37.00
	Notes	

Labor

Line# 2	Operation Code 40-196-24-11-001297	Operational Description Interior 12 Volt Wiring - Electrical/12 Volt Interior/Repair/Electrical
	Complaint, Cause, Correction Original Note : bhoffman@americanrvcenter.com, 2025-06-27 13:33:50 :: LIGHT IN FLICKERING Light Light was flickering due to a loose wire so I took off light cover removed loose wire and then put back into the correct spot now light isn't flickering	
Model#	Dlr Sub Hrs 0.20	Sub Labor Amt \$37.00
Serial#	Appr Hrs 0.20	Appr Labor Amt \$37.00
	Notes thank you	

Labor

Line# 3	Operation Code 30-100-02-00-003062	Operational Description Cabinet Door Hinge or Latch, each - Interior/Cabinetry/Adjust/No Tread Code
	Complaint, Cause, Correction Original Note : bhoffman@americanrvcenter.com, 2025-06-27 13:37:39 :: 2 CABIBNET DOOR LOOSE Cabinet door Doors were loose from screws so drilled them tighter now shuts better	
Model#	Dlr Sub Hrs 0.20	Sub Labor Amt \$37.00
Serial#	Appr Hrs 0.20	Appr Labor Amt \$37.00
	Notes thank you	

Labor

Line# 4	Operation Code 30-101-02-00-001077	Operational Description Hinged Passage Door Striker - Interior/Interior Doors/Adjust/No Tread Code
	Complaint, Cause, Correction Original Note : bhoffman@americanrvcenter.com, 2025-06-27 13:38:24 :: BEDROOM DOOR HAD TO OPEN Bedroom door Bedroom door was hard to open due to a screw in the way so took screw out now door shuts	
Model#	Dlr Sub Hrs 0.10	Sub Labor Amt \$18.50
Serial#	Appr Hrs 0.10	Appr Labor Amt \$18.50

Notes**Labor****Line# 5****Operation Code**

30-100-02-00-001044

Operational Description

Drawer Guides or Tracks, pair - Interior/Cabinetry/Adjust/No Tread Code

Complaint, Cause, Correction

Original Note : bhoffman@americanrvcenter.com, 2025-06-27 13:39:40 :: DRAWER IN KITCHEN STICKS Cabnet drawer The drawer was hard to open so adjusted how the drawer sits in the frame and will shut smoother now without papers being in the way causing it not to shut completely

Model#**Dlr Sub Hrs**

0.20

Sub Labor Amt \$37.00**Serial#****Appr Hrs**

0.20

Appr Labor Amt \$37.00**Notes****Labor****Line# 6****Operation Code**

20-66-24-00-000658

Operational Description

Entry Door - Exterior/Entry Doors/Repair/No Tread Code

Complaint, Cause, Correction

Original Note : bhoffman@americanrvcenter.com, 2025-06-27 13:41:28 :: REAR ENTRY DOOR Back door Re adjusted back door lock and latch and now door will shut properly

Model#**Dlr Sub Hrs**

0.20

Sub Labor Amt \$37.00**Serial#****Appr Hrs**

0.20

Appr Labor Amt \$37.00**Notes**

thank you

Labor**Line# 7****Operation Code**

30-102-24-00-003061

Operational Description

Ceiling Panel - Touchup - Interior/Panels, Ceilings, & Interior Moldings/Repair/No Tread Code

Complaint, Cause, Correction

Original Note : bhoffman@americanrvcenter.com, 2025-06-27 13:42:20 :: MARK ON CEILING IN BATHROOM Mark on ceiling Mark on ceiling and caused small stain so I took a paint maker and also some mineral spirits and took Mark off the ceiling

Model#**Dlr Sub Hrs**

0.10

Sub Labor Amt \$18.50**Serial#****Appr Hrs**

0.10

Appr Labor Amt \$18.50**Notes****Labor****Line# 8****Operation Code**

30-101-02-00-001076

Operational Description

Hinged Passage Door - Interior/Interior Doors/Adjust/No Tread Code

Complaint, Cause, Correction

Original Note : bhoffman@americanrvcenter.com, 2025-06-27 13:44:12 :: BATHROOM DOOR NEEDS ADJUSTED Door Bathroom door hard to open so adjusted the frame where latch goes in and now shuts perfectly fine

Model#**Dlr Sub Hrs**

0.20

Sub Labor Amt \$37.00**Serial#****Appr Hrs**

0.20

Appr Labor Amt \$37.00**Notes****Labor****Line# 9****Operation Code**

30-102-12-00-001096

Operational Description

Interior Trim or Moldings, each - Interior/Panels, Ceilings, & Interior Moldings/ Resecure or Tighten/No Tread Code

Complaint, Cause, Correction

Original Note : bhoffman@americanrvcenter.com, 2025-06-27 13:45:18 :: STAPLE HOLES IN WOOD NEAR BATHROOM DOOR Staple holes Took some wood putty and tried to match with wood color and fill in the staple holes with the putty

Model#**Dlr Sub Hrs**

0.10

Sub Labor Amt \$18.50**Serial#****Appr Hrs**

0.10

Appr Labor Amt \$18.50**Notes****Labor**

Line# 10

Operation Code
50-134-01-00-001442

Operational Description
LP Tank or Bottle - LP Gas/LP Gas System/Replace/No Tread Code

Complaint, Cause, Correction
Original Note : bhoffman@americanrvcenter.com, 2025-06-27 13:47:17 :: LP TANK VALVE GASKET HAS COME OUT Lp tank Took lp to go fill up when I started to fill tank the hose wasn't fitting correctly so looked on tank and noticed the o ring was messed up so went and got a new tank from pants to preform lp drop test

Model# NA

Dlr Sub Hrs 0.20

Sub Labor Amt \$37.00

Serial# NA

Appr Hrs 0.20

Appr Labor Amt \$37.00

Notes
thank you

Submitted	Labor Amt	\$314.50	Approved	Labor Amt	\$314.50
	Parts & Freight	\$0.00		Parts & Freight	\$0.00
	Total	\$314.50		Total	\$314.50

DEALER

DATE

SIGNATURE

I certify that I have performed these repairs consistent with Forest River Policies.

CUSTOMER

DATE

SIGNATURE

All repairs described have been inspected and are satisfactory.