



600 E. Baseline Rd.
Evansville, IN 47725

www.AmericanRVCenter.com

812.867.5200
FAX 812.868.1012

W/O: 77018
Promised Date:
20 JUN 25



CUSTOMER WORK ORDER

WO #: 77018

Customer: 1000 - BASDEN'S AMERICAN
RV -

Tag:

Author: BH

Location: 0630 CHECK PREAUTH

Stock #: 11625

Stock Desc: 2026 TT FOREST RIVER

CHEROKEE GREY WOLF 26DBH

Chassis #: 4X4TCKB29TK096289

Serial #: 4X4TCKB29TK096289

Mileage: 0

Licence:

Invoice #:

Date In: 13 JUN 25

Promised: 30 JUN 25

Date Sched:

Completed: 28 JUN 25

Warr. Date:

Job #PDINTT - Internal

COMPLAINT: PDI - NEW TRAVEL TRAILER
CHEROKEE TK096289

CAUSE: Pdi

CORRECTION:

Started on new pdi

Checked all exterior lights,tires, checked roof and seals on windows, checked all interior lights and outlets, checked all cabinets and also doors all shut, ran all antifreeze out of lines also checked for leaks, checked all flooring for cracks and no evidence of any showing, checked all beds,filled lp also did the drop test while checking the furnace and water heater and working correctly, checked tv connection and is working correctly, Furciger is working properly as well as ac, smoke detector is working/ carbon monoxide detector is working, refrigerator and microwave are working properly, drained all black and grey tanks

Labor

Code	Description	Mechanic	Total
Z991	MISC LABOUR CODE (INTERNAL)	JLC	N/C
Z991	MISC LABOUR CODE (INTERNAL)	JLC	N/C
Z991	MISC LABOUR CODE (INTERNAL)	JLC	N/C
Z991	MISC LABOUR CODE (INTERNAL)	JLC	N/C
Z991	MISC LABOUR CODE (INTERNAL)	JLC	N/C
Z991	MISC LABOUR CODE (INTERNAL)	JLC	N/C

Parts

Part #	Description	Qty	Price	Total
13034	55362 STD BATTERY BOX	1.00	N/C	N/C

Other Services

Code	Description	Qty	Price	Total
SS	SHOP SUPPLIES	1.00	N/C	N/C
LPGI	LP - UNIT SALES	8.00	N/C	N/C

Subtotal for Job #PDINTT: 0.00

Job #1 - Warranty

COMPLAINT: ENTRY DOOR SCREEN DOOR

CAUSE: Entry door

CORRECTION: The entrydoor frame was bent so i pushed it back and now the screen door will shut

Labor

Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	JLC	18.50



Customer #: 1000
BASDEN'S AMERICAN RV,



Subtotal for Job #1: 37.00

Job #2 - Warranty

COMPLAINT: LIGHT IN FLICKERING

CAUSE: Light

CORRECTION: Light was flickering due to a loose wire so I took off light cover removed loose wire and then put back into the correct spot now light isn't flickering

Labor Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	JLC	37.00
Subtotal for Job #2:			37.00

Job #3 - Warranty

COMPLAINT: 2 CABINET DOOR LOOSE

CAUSE: Cabinet door

CORRECTION: Doors were loose from screws so drilled them tighter now shuts better

Labor Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	JLC	37.00
Subtotal for Job #3:			37.00

Job #4 - Warranty

COMPLAINT: BEDROOM DOOR HAD TO OPEN

CAUSE: Bedroom door

CORRECTION: Bedroom door was hard to open due to a screw in the way so took screw out now door shuts

Labor Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	JLC	18.50
Subtotal for Job #4:			18.50

Job #5 - Warranty

COMPLAINT: DRAWER IN KITCHEN STICKS

CAUSE: Cabnet drawer

CORRECTION: The drawer was hard to open so adjusted how the drawer sits in the frame and will shut smoother now without papers being in the way causing it not to shut completely

Labor Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	JLC	37.00
Subtotal for Job #5:			37.00


Job #6 - Warranty

COMPLAINT: REAR ENTRY DOOR

CAUSE: Back door

CORRECTION: Re adjusted back door lock and latch and now door will shut properly

W/O: 77018
Promised Date: 30 JUN 25



Customer #: 1000
BASDEN'S AMERICAN RV,





Labor Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	JLC	37.00
Subtotal for Job #6:			37.00

Job #7 - Warranty

COMPLAINT: MARK ON CEILING IN BATHROOM

CAUSE: Mark on ceiling

CORRECTION: Mark on ceiling and caused small stain so I took a paint maker and also some mineral spirits and took Mark off the ceiling

Labor Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	JLC	18.50
Subtotal for Job #7:			18.50

Job #8 - Warranty

COMPLAINT: BATHROOM DOOR NEEDS ADJUSTED

CAUSE: Door

CORRECTION: Bathroom door hard to open so adjusted the frame where latch goes in and now shuts perfectly fine

Labor Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	JLC	37.00
Subtotal for Job #8:			37.00

Job #9 - Warranty

COMPLAINT: STAPLE HOLES IN WOOD NEAR BATHROOM DOOR

CAUSE: Staple holes

CORRECTION: Took some wood putty and tried to match with wood color and fill in the staple holes with the putty

Labor Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	JLC	18.50
Subtotal for Job #9:			18.50

Job #10 - Warranty

COMPLAINT: LP TANK VALVE GASKET HAS COME OUT

CAUSE: Lp tank

CORRECTION: Took lp to go fill up when I started to fill tank the hose wasn't fitting correctly so looked on tank and noticed the o ring was messed up so went and got a new tank from pants to preform lp drop test

Labor Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	JLC	37.00

Parts Part #	Description	Qty	Price	Total
66-4905	L.P.CYLINDER 20 LB. PW	1.00	63.91	63.91



Subtotal for Job #10: 100.91

Parts Total: 63.91
Labour Total: 314.50
Sublet Total: 0.00
Extras Total: 0.00

WORK ORDER TOTAL: 378.41


Thank you for being a valued customer. We appreciate your business.

All labor is guaranteed for 90 days from invoice date. Guarantee is limited to work performed. Consequential damages are not covered. All guaranteed work must be completed in our service department.

Customer Signature : _____

Date: 28 Jun 2025

W/O: 77018
Promised Date: 30 JUN 25



Customer #: 1000
BASDENS AMERICAN RV,

