



600 E. Baseline Rd.
Evansville, IN 47725

www.AmericanRVCenter.com

812.867.5200
FAX 812.868.1012

W/O: 77025
Promised Date:
20 JUN 25



Customer #: 55679
WILLARD, RONALD



CUSTOMER WORK ORDER

WO #: 77025

Customer: 55679 - WILLARD, RONALD -
859-626-2541

Tag:

Author: BH

Location: 0711 CHECK STATUS WITH
ZMS

Stock #: 11620

Stock Desc: 2026 TT COACHMEN APEX

NANO 203RBK

Chassis #: 5ZT2CXJB6TL019274

Serial #: 5ZT2CXJB6TL019274

Mileage: 0

Licence:

Invoice #:

Date In: 16 JUN 25

Promised: 30 JUN 25

Date Sched:

Completed: 10 JUL 25

Warr. Date: 21 JUN 25

Job #PDINTT - Internal

Transferred to BAS*77210 on 02 JUL 25

Estimate amount was 0.00

PDI - NEW TRAVEL TRAILER

Labor

Code	Description	Mechanic	Total
Z991	MISC LABOUR CODE (INTERNAL)	ZMS	N/C
Z991	MISC LABOUR CODE (INTERNAL)	ZMS	N/C
Z991	MISC LABOUR CODE (INTERNAL)	ZMS	N/C
Z991	MISC LABOUR CODE (INTERNAL)	ZMS	N/C

Other Services

Code	Description	Qty	Price	Total
SS	SHOP SUPPLIES	0.00	N/C	N/C
LPGI	LP - UNIT SALES	0.00	N/C	N/C

Subtotal for Job #PDINTT: 0.00

Job #FPDINTT - Internal

Transferred to BAS*77210 on 02 JUL 25

Estimate amount was 0.00

FINAL PDI ON NEW TRAVEL TRAILERS

Labor

Code	Description	Mechanic	Total
PDINTT	PDI - NEW TRAVEL TRAILER	ZMS	N/C
PDINTT	PDI - NEW TRAVEL TRAILER	ZMS	N/C
PDINTT	PDI - NEW TRAVEL TRAILER	ZMS	N/C

Subtotal for Job #FPDINTT: 0.00

Job #DELUXE - Internal

Transferred to BAS*77210 on 02 JUL 25

Estimate amount was 0.00

DELUXE STARTER KIT



Subtotal for Job #DELUXE: 0.00

Job #1 - Warranty

COMPLAINT: THE DOOR SIDE FRONT STAY JACK IS MAKING NOISE AND THE ROD IS NOT STRAIGHT

CAUSE: jack needs replaced.

CORRECTION: recived new jack from parts. removed mounting bolts. secured new jack to unit. placed old jack in box. parked unit.

Labor

Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	ZMS	0.00
Z990	MISC LABOUR CODE (EXTERNAL)	ZMS	37.00

Parts

Part #	Description	Qty	Price	Total
F100178595	JACK, STAB SCISSOR 24" 2500#	1.00	34.59	34.59

Other Services

Code	Description	Qty	Price	Total
FRT	UPS-JACK	1.00	15.58	15.58

Subtotal for Job #1: 87.17

Job #2 - Internal

COMPLAINT: COVER FOR THE SHOWER PAN KEEPS FALLING

CAUSE: Pulled unit into shop. Opened slide room. The cutout for the access panel is too big. Waited on warranty advisor to approve applying silicone around the access panel.

CORRECTION: Applied silicone around access panel and let dry with pressure on panel.

Labor

Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	ZMS	N/C

Subtotal for Job #2: 0.00

Job #3 - Internal

Transferred to BAS*77210 on 02 JUL 25

Estimate amount was 0.00

FREE STORAGE FOR 2 MONTH PER CHAD

Subtotal for Job #3: 0.00

Parts Total:	34.59
Labour Total:	37.00
Sublet Total:	0.00
Extras Total:	15.58
WORK ORDER TOTAL:	87.17

Thank you for being a valued customer. We appreciate your business.

All labor is guaranteed for 90 days from invoice date. Guarantee is limited to work performed. Consequential damages are not covered. All guaranteed work must be completed in our service department.

W/O: 77025
Promised Date: 30 JUN 25



Customer #: 55679
WILLARD, RONALD



Customer Signature : _____

Date: 10 Jul 2025

W/O: 77025
Promised Date: 30 JUN 25



Customer #: 55679
WILLARD, RONALD

