

Model#	Dlr Sub Hrs	0.10	Sub Labor Amt	\$18.50
Serial#	Appr Hrs	0.10	Appr Labor Amt	\$18.50

Notes

Labor

Line# 5 Operation Code 30-102-12-00-002691 Operational Description
 Wall Panel - Luan - Interior/Panels, Ceilings, & Interior Moldings/Resecure or Tighten/No Tread Code

Complaint, Cause, Correction

Original Note : bhoffman@americanrvcenter.com, 2025-07-10 11:35:06 :: LOOSE WALLPAPER IN MAIN BEDROOM Wallpaper loose Took a roller and smoothed out the wallpaper in spots where it was loose then made sure it wasn't coming loose again by adding some adhesive

Model#	Dlr Sub Hrs	0.20	Sub Labor Amt	\$37.00
Serial#	Appr Hrs	0.20	Appr Labor Amt	\$37.00

Notes

Submitted	Labor Amt	\$166.50	Approved	Labor Amt	\$166.50
	Parts & Freight	\$0.00		Parts & Freight	\$0.00
	Total	\$166.50		Total	\$166.50

DEALER _____ DATE _____

SIGNATURE

I certify that I have performed these repairs consistent with Forest River Policies.

CUSTOMER _____ DATE _____

SIGNATURE

All repairs described have been inspected and are satisfactory.