

FOREST RIVER WARRANTY CLAIM FORM

DEALER ACCOUNT #	0005106	CLAIM STATUS	Authorized
BASDEN RV CENTER INC		CLAIM	2360239
DBA AMERICAN RV CENTER		CLAIM ORIGIN	WEB
600 E BASELINE ROAD		ORIGINAL CLAIM ID	
EVANSVILLE, IN 47725		VIN	4X4TCKC21TX166918
USA		CHASSIS VIN	
		MILEAGE	0
Labor rate:	\$185.00	SITE/WAREHOUSE	017 / 017A
OWNER INFORMATION		ITEM #	ACKT27LH
		DEALER RO #	77070
		CLAIM START DATE	07/09/2025
		CLAIM END DATE	01/01/1900

Retail Date of Purchase

WARRANTY EXPIRATION DATE

Claim Line Details

Labor

Line# 1	Operation Code	Operational Description		
	30-102-12-00-001096	Interior Trim or Moldings, each - Interior/Panels, Ceilings, & Interior Moldings/ Resecure or Tighten/No Tread Code		
	Complaint, Cause, Correction			
	Original Note : bhoffman@americanrvcenter.com, 2025-07-09 10:14:32 :: FIREPLACE WOOD IS COMING OFF Fireplace wood is loose When looking at fireplace the wood on the side was loose so I had to get a staple gun and staple 6 staples in the trim and make sure it was level and aligned with thr other trim then I took some wood putty to fill in gaps where staples went then I also used some paint pens to match the best I could with the wood color and cover up the wood putty marks			
Model#		Dlr Sub Hrs	0.10	Sub Labor Amt \$18.50
Serial#		Appr Hrs	0.10	Appr Labor Amt \$18.50
	Notes			

Labor

Line# 2	Operation Code	Operational Description		
	30-91-15-00-004713	Furniture/Fabric Tack - Interior/Living Quarters, Sofa, Chair/Repair or Replace/No Tread Code		
	Complaint, Cause, Correction			
	Original Note : bhoffman@americanrvcenter.com, 2025-07-09 10:15:35 :: STAIN ON COUCH IN AREAS Stain on couch Got a mixture of water and dawn dish soap and gently applied it to the areas that had stained and then whipped off with a towel to clean area on couch and now the stains are gone off the couch			
	Model#	Dlr Sub Hrs	0.10	Sub Labor Amt \$18.50
	Serial#	Appr Hrs	0.10	Appr Labor Amt \$18.50
	Notes			

Labor

Line# 3	Operation Code	Operational Description		
	40-196-24-11-001297	Interior 12 Volt Wiring - Electrical/12 Volt Interior/Repair/Electrical		
	Complaint, Cause, Correction			
	Original Note : bhoffman@americanrvcenter.com, 2025-07-09 10:16:26 :: BATHROOM LIGHT FLICKERS			
	Bathroom light The bathroom light would flicker when you turn on the switch so I took the light out of the ceiling and found out there was a loose wire so I twisted it up and made sure i put it in the correct spot and then I tested for electricity and the light is now working properly			
Model#		Dlr Sub Hrs	0.15	Sub Labor Amt \$27.75
Serial#		Appr Hrs	0.15	Appr Labor Amt \$27.75
	Notes			
	Authorized as requested.			

Labor

Line# 4	Operation Code	Operational Description
---------	----------------	-------------------------

70-147-24-00-001658

TV Swing Bracket - Appliances/Television/Repair/No Tread Code

Complaint, Cause, Correction

Original Note : bhoffman@americanrvcenter.com, 2025-07-09 10:17:12 :: TV MOUNT IS LOOSE Tv mount When looking at TV mount couldn't tell it was loose until you try to set something on it then it would pull away from the wall so I added some adhesive and also new screws and set it in the correct position now the TV mount is fixed on the wall and should work properly

Model#	Dlr Sub Hrs	0.10	Sub Labor Amt	\$18.50
--------	-------------	------	---------------	---------

Serial#	Appr Hrs	0.10	Appr Labor Amt	\$18.50
---------	----------	------	----------------	---------

Notes

**Labor
Line# 5****Operation Code**

30-100-24-00-001046

Operational Description

Cabinet Door - Interior/Cabinetry/Repair/No Tread Code

Complaint, Cause, Correction

Original Note : bhoffman@americanrvcenter.com, 2025-07-09 10:18:08 :: CABINET DOOR IN BEDROOM IS LOOSE Loose door Got different screws to put in cabinet door so it would shut properly and is now opening and closing correctly

Model#	Dlr Sub Hrs	0.30	Sub Labor Amt	\$55.50
--------	-------------	------	---------------	---------

Serial#	Appr Hrs	0.30	Appr Labor Amt	\$55.50
---------	----------	------	----------------	---------

Notes

**Labor
Line# 6****Operation Code**

30-96-24-00-000969

Operational Description

Folding Table Leg, each - Interior/Folding Leg/Repair/No Tread Code

Complaint, Cause, Correction

Original Note : bhoffman@americanrvcenter.com, 2025-07-09 10:18:59 :: KITCHEN TABLE IS LOOSE Kitchen table loose When looking at the kitchen table / island it appears to fine fine until you push on it with hand so looking underneath the table had a screw loose so I tightened all of them down

Model#	Dlr Sub Hrs	0.10	Sub Labor Amt	\$18.50
--------	-------------	------	---------------	---------

Serial#	Appr Hrs	0.10	Appr Labor Amt	\$18.50
---------	----------	------	----------------	---------

Notes

**Labor
Line# 7****Operation Code**

60-141-12-00-001592

Operational Description

Tub Surround to Wall, each section - Plumbing/Shower, Tub Surround/Resecure or Tighten/No Tread Code

Complaint, Cause, Correction

Original Note : bhoffman@americanrvcenter.com, 2025-07-09 10:20:12 :: BATHROOM BATH NEEDS SILICONEE Bathroom shower When looking in the bathroom shower the shower was needing some silicone sealer added to it so no water would go behind it and ruin the wood behind it so i added silicone all around the surround and then whipped off the extra with a towel

Model#	Dlr Sub Hrs	0.20	Sub Labor Amt	\$37.00
--------	-------------	------	---------------	---------

Serial#	Appr Hrs	0.20	Appr Labor Amt	\$37.00
---------	----------	------	----------------	---------

Notes

Authorized as requested.

**Labor
Line# 8****Operation Code**

20-66-02-00-000664

Operational Description

Entry Door - RV - Exterior/Entry Doors/Adjust/No Tread Code

Complaint, Cause, Correction

Original Note : bhoffman@americanrvcenter.com, 2025-07-09 10:20:53 :: FRONT DOOR NEEDS ADJUSTED Frontdoor Adjusted front door by taking a small rubber hammer and making the latch flat and also adjusted the screws where they sit and now the door will shut properly

Model#	Dlr Sub Hrs	0.20	Sub Labor Amt	\$37.00
--------	-------------	------	---------------	---------

Serial#	Appr Hrs	0.20	Appr Labor Amt	\$37.00
---------	----------	------	----------------	---------

Notes

Changed repair code to more closely match the repair.

Please add labor time in the corresponding box on the claim. Thank you
added thank you

Authorized as requested.

Labor

Line# 9 **Operation Code** **Operational Description**
60-136-15-00-001499 Water Line - Plumbing/Fresh Water Supply/Repair or Replace/No Tread Code
Complaint, Cause, Correction
Original Note : bhoffman@americanrvcenter.com, 2025-07-09 10:23:05 :: KITCHEN CUP WASHER NOT WORKING
Cup washer When looking and trying the cup washer it wasn't working so I opened the cabinet door to find the
line running to it had been shut off and also had a small kink in the line so I turned the knob and also undid the
kink now is working properly

Model#	Dlr Sub Hrs	0.10	Sub Labor Amt	\$18.50
Serial#	Appr Hrs	0.10	Appr Labor Amt	\$18.50

Notes
Authorized as requested.

Labor

Line# 10 **Operation Code** **Operational Description**
40-196-24-11-001297 Interior 12 Volt Wiring - Electrical/12 Volt Interior/Repair/Electrical
Complaint, Cause, Correction
Original Note : bhoffman@americanrvcenter.com, 2025-07-09 10:24:06 :: LIGHT IN FRONT CARGO AREA NOT
WORKING Cargo light not coming on Argo light wasn't coming on due to both wires were hooked up wrong and
also the 2 negative wires had to be touching for light to work after taking a volt meter to it and also having Greg
come over and looking i found out the wires were in wrong location so I rewired it and got the light working
properly

Model#	Dlr Sub Hrs	0.40	Sub Labor Amt	\$74.00
Serial#	Appr Hrs	0.40	Appr Labor Amt	\$74.00

Notes
Authorized as requested.

Submitted	Labor Amt	\$323.75	Approved	Labor Amt	\$323.75
	Parts & Freight	\$0.00		Parts & Freight	\$0.00
	Total	\$323.75		Total	\$323.75

DEALER DATE

SIGNATURE

I certify that I have performed these repairs consistent with Forest River Policies.

CUSTOMER DATE

SIGNATURE

All repairs described have been inspected and are satisfactory.