

FOREST RIVER WARRANTY CLAIM FORM

DEALER ACCOUNT #	0005106	CLAIM STATUS	Authorized
BASDEN RV CENTER INC		CLAIM	2346033
DBA AMERICAN RV CENTER		CLAIM ORIGIN	WEB
600 E BASELINE ROAD		ORIGINAL CLAIM ID	
EVANSVILLE, IN 47725		VIN	5ZT2FEPB7SW031112
USA		CHASSIS VIN	
		MILEAGE	0
Labor rate:	\$185.00	SITE/WAREHOUSE	320 / 320
OWNER INFORMATION		ITEM #	FET245RKS-320
MISTY L MILLER		DEALER RO #	77091
1725 BROADWAY ST		CLAIM START DATE	06/25/2025
Vincennes, IN 47591		CLAIM END DATE	01/01/1900
USA			
Retail Date of Purchase	05/31/2025	WARRANTY EXPIRATION DATE	05/31/2026

Claim Line Details

Labor

Line# 1	Operation Code	Operational Description		
	60-141-12-00-001592	Tub Surround to Wall, each section - Plumbing/Shower, Tub Surround/Resecure or Tighten/No Tread Code		
	Complaint, Cause, Correction			
	Original Note : bhoffman@americanrvcenter.com, 2025-06-25 12:00:22 :: SHOWER LEAKS AT THE DOOR SLIDE AND AT THE BACK OF THE SHOWER WHEN USING THE SHOWER Assess and seal leak at backside of shower door... Sealed corner with White Sealant at corner and lowered door seal.			
Model#	Dlr Sub Hrs	0.10	Sub Labor Amt \$18.50	
Serial#	Appr Hrs	0.10	Appr Labor Amt \$18.50	
	Notes			

Labor

Line# 2	Operation Code	Operational Description		
	30-102-12-00-001096	Interior Trim or Moldings, each - Interior/Panels, Ceilings, & Interior Moldings/ Resecure or Tighten/No Tread Code		
	Complaint, Cause, Correction			
	Original Note : bhoffman@americanrvcenter.com, 2025-06-25 12:01:01 :: A TRIM PEICE IN THE BATHROOM IS LOOSE AND LOOKS BAD Loos3 trim in bathroom... Stapled trim back into place and filled the staple marks with white puddy.			
Model#	Dlr Sub Hrs	0.10	Sub Labor Amt \$18.50	
Serial#	Appr Hrs	0.10	Appr Labor Amt \$18.50	
	Notes			

Labor

Line# 3	Operation Code	Operational Description		
	30-95-24-00-000971	Dinette Seat or Back Cover, each - Interior/Dinette/Repair/No Tread Code		
	Complaint, Cause, Correction			
	Original Note : bhoffman@americanrvcenter.com, 2025-06-25 12:02:14 :: THE SEATING IN THE SLIDE IS NOT SCREWED DOWN Secure Recliners to slideout floor... 1 small L Bracket was the only thing securing it to slideout floor. And these specific set are technically to long for this slideout and the front brackets slightly over hangouts the floor. Was instructed by Ben to go ahead and secure the rear. Had to completely disassemble 3 piece dual Recliners to secure the rear brackets on Recliners. Retrieved heavier diameter and correct length mount screws. Had to mount the far left seat 1st, middle union 2nd and then right seat last, in that order due to the interconnecting bracketsbetweenpieces. Cleaned up my tools.			
Model#	Dlr Sub Hrs	0.80	Sub Labor Amt \$148.00	
Serial#	Appr Hrs	0.50	Appr Labor Amt \$92.50	
	Notes			

resecure theater chairs

Submitted	Labor Amt	\$185.00
	Parts & Freight	\$0.00
	Total	\$185.00

Approved	Labor Amt	\$129.50
	Parts & Freight	\$0.00
	Total	\$129.50

DEALER	DATE
SIGNATURE	

I certify that I have performed these repairs consistent with Forest River Policies.

CUSTOMER	DATE
SIGNATURE	

All repairs described have been inspected and are satisfactory.