



600 E. Baseline Rd.
Evansville, IN 47725

www.AmericanRVCenter.com

812.867.5200
FAX 812.868.1012

W/O: 77091



Customer #: 43532
MILLER, MISTY L.



CUSTOMER WORK ORDER

WO #: 77091 (Appointment Date: 21 JUN 2025 - Time: 01:00pm)

Customer: 43532 - MILLER, MISTY L. -
812-899-0578

Tag:

Author: BH

Location: 0630 CHECK PREAUTH

Stock #: 11601

Stock Desc: 2025 TT COACHMEN

FREEDOM EXPRESS 245RKS

Chassis #: 5ZT2FEPB7SW031112

Serial #: 5ZT2FEPB7SW031112

Mileage:

Licence:

Invoice #:

Date In: 21 JUN 25

Promised:

Date Sched:

Completed: 27 JUN 25

Warr. Date: 31 MAY 25

Job #1 - Warranty

COMPLAINT: SHOWER LEAKS AT THE DOOR SLIDE AND AT THE BACK OF THE SHOWER WHEN USING THE SHOWER

CAUSE: Assess and seal leak at backside of shower door...

CORRECTION: Sealed corner with White Sealant at corner and lowered door seal.

Labor

Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	JRK	92.50

Parts

Part #	Description	Qty	Price	Total
500629	SIKASIL N PLUS WHITE	1.00	8.89	8.89

Other Services

Code	Description	Qty	Price	Total
SS	SHOP SUPPLIES	1.00	0.00	0.00

Subtotal for Job #1: 101.39

Job #2 - Warranty

COMPLAINT: A TRIM PEICE IN THE BATHROOM IS LOOSE AND LOOKS BAD

CAUSE: Loos3 trim in bathroom...

CORRECTION: Stapled trim back into place and filled the staple marks with white puddy.

Labor

Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	JRK	92.50

Subtotal for Job #2: 92.50

Job #3 - Warranty

COMPLAINT: THE SEATING IN THE SLIDE IS NOT SCREWED DOWN

CAUSE: Secure Recliners to slideout floor...

CORRECTION: 1 small L Bracket was the only thing securing it to slideout floor. And these specific set are technically to long for this slideout and the front brackets slightly over hangouts the floor. Was instructed by Ben to go ahead and secure the rear. Had to completely disassemble 3 piece dual Recliners to secure the rear brackets on Recliners. Retrieved heavier diameter and correct length mount screws. Had to mount the far left seat 1st, middle union 2nd and then right seat last, in that order due to the interconnecting bracketsbetweenpieces. Cleaned up my tools.



Labor

Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	JRK	92.50

Subtotal for Job #3: 92.50

Job #4 - Internal

INSTALL LEVELS FOR CUSTOMER...SITTING
INSIDE CAMPER ALREADY

Labor

Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	JRK	N/C

Subtotal for Job #4: 0.00

Parts Total: 8.89
Labour Total: 277.50
Sublet Total: 0.00
Extras Total: 0.00

WORK ORDER TOTAL: 286.39

Thank you for being a valued customer. We appreciate your business.

All labor is guaranteed for 90 days from invoice date. Guarantee is limited to work performed. Consequential damages are not covered. All guaranteed work must be completed in our service department.

Customer Signature : _____

Date: 27 Jun 2025

Customer #: 43532
MILLER, MISTY L.

