



600 E. Baseline Rd.
Evansville, IN 47725

www.AmericanRVCenter.com

812.867.5200
FAX 812.868.1012

W/O: 75596
Promised Date:
24 DEC 24

CUSTOMER WORK ORDER

WO #: 75596 (Appointment Date: 02 DEC 2024 - Time: 04:30pm)

Customer: 54983 - MORRISON, ELISA -

Tag: BJ - FOIL TAPE ORDERED. 12-12

Author: BJW

Location: 0127 BH TO CLOSE

Stock #:

Stock Desc: 2023 A FOREST RIVER

GEORGETOWN GT5 34M5

Chassis #: 4X4MGTK27PH036111

Serial #: 1F66F5DN7N0A16198

Mileage: 3698

Licence:

Invoice #: 413460

Date In: 02 DEC 24

Promised: 31 DEC 24

Date Sched:

Completed: 27 JAN 25

Warr. Date:

Job #WINTER - External

COMPLAINT: Transferred to BAS*75655 on 06 DEC 24

Estimate amount was 0.00

WINTERIZE UNIT AND DRAIN HOLDING TANKS.

INCLUDES 2 GALLONS OF ANTI-FREEZE

UNITS WITH WASHING MACHINE OR ICEMAKER

WILL BE EXTRA

DE-WINTERIZATION IS NOT INCLUDED

NUMBER OF GALLONS USED _____

CAUSE: Winterizing 6 gallons

CORRECTION: Drained black, grey, fresh tanks, turned valves at the water pump. Added 6 gallons thru the kitchen faucet, bathroom faucet, toilet, shower, outside shower, washer. Depressed the city connection and water heater.

Labor

Code	Description	Mechanic	Total
Z990	WINTERIZE UNIT	SAR	N/C
Z990	WINTERIZE UNIT	SAR	N/C

Other Services

Code	Description	Qty	Price	Total
SS	SHOP SUPPLIES	0.00	N/C	N/C

Subtotal for Job #WINTER: 0.00

Job #ROOFT - External

COMPLAINT: Transferred to BAS*75655 on 06 DEC 24

Estimate amount was 0.00

INSPECT ROOF AND ROOF SEAMS - CLEAN AND FILL VOIDS. 1 TUBE OF ROOF SEALANT INCLUDED.

CAUSE: Cracks and voids

CORRECTION: Got on the roof then inspected around vents, skylight, antenna, roof edges, roof caps, and solar panel. Notified Ben about the roof and approval.

Labor

Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	SAR	N/C
Z990	MISC LABOUR CODE (EXTERNAL)	SAR	N/C

Customer #: 54983
MORRISON, ELISA





Other Services

Code	Description	Qty	Price	Total
SS	SHOP SUPPLIES	0.00	N/C	N/C

Subtotal for Job #ROOFT: 0.00

Job #OILF - External

COMPLAINT: Transferred to BAS*75655 on 06 DEC 24

Estimate amount was 0.00

OIL, LUBE, AND FILTER ON FORD GAS CHASSIS

CAUSE: Oil change

CORRECTION: Drained the oil pan and removed the oil filter. Gathered up the new oil and oil filter. Put new oil in the filter and put the drain plug back in. Added 8.5 qts and checked the oil level. 3699 miles

Labor

Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	SAR	N/C

Other Services

Code	Description	Qty	Price	Total
SS	SHOP SUPPLIES	0.00	N/C	N/C
PARTS	UNINVENTORIED PARTS	0.00	N/C	N/C
PARTS	UNINVENTORIED PARTS	0.00	N/C	N/C

Subtotal for Job #OILF: 0.00

Job #4 - Warranty

COMPLAINT: MARKER LIGHT NOT WORKING ON THE FRONT.

THIS IS A WHITE LED TUBE THAT OUTLINES THE COACH. IT IS WORKING ON THE PASSENGER SIDE, BUT NOT THE DRIVER SIDE

CAUSE: Wires was disconnected

CORRECTION: Searched for the button that cause the lights to come on. Turned on the the lights then checked the wires. Found the black and yellow wires was unplugged. Plugged in those wires and the lights work.

Labor

Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	SAR	34.00

Subtotal for Job #4: 34.00

Job #5 - Warranty

COMPLAINT: FRIDGE NOT WORKING AT ALL

CAUSE: Possible blockage

CORRECTION: Plugged in the shore cord, then turned the fridge to lp and checked the back side for a flame. Took pictures of the flame. Set the fridge to ac and put antifreeze bottles with thermometers in side the fridge to cool overnight. Checked the amp draw on the heating elements of 3.5 amps. Checked the fridge again after 24 hrs. The cooling unit was hot, but the freezer and fridge were hot at 70 degrees. It's possible a blockage in the cooling unit. Filled out the paperwork while testing the fridge. Received the copper tape. Unscrewed the fridge control board cover then covered the cover with copper tape as noted. Took pictures. Screwed the cover back on to the fridge. Plugged in the shore power and power on the fridge. Put bottles of antifreeze with thermometers inside. Will let the fridge set for 24hrs. After 48 hrs thr fridge was not cold. Put in po sheet for a new fridge.

Labor

Code	Description	Mechanic	Total
Z990	MISC LABOR CODE (EXTERNAL)	SAR	1.70
Z990	MISC LABOUR CODE (EXTERNAL)	SAR	51.00
Z990	MISC LABOUR CODE (EXTERNAL)	SAR	18.70



Z990	MISC LABOUR CODE (EXTERNAL)	SAR	0.00
Z990	MISC LABOR CODE (EXTERNAL)	SAR	124.10
Z990	MISC LABOR CODE (EXTERNAL)	SAR	40.80
Z990	MISC LABOR CODE (EXTERNAL)	SAR	190.40
Z990	MISC LABOR CODE (EXTERNAL)	SAR	0.00
Z990	MISC LABOR CODE (EXTERNAL)	SAR	56.10
Z990	MISC LABOUR CODE (EXTERNAL)	JG	17.00
Z990	MISC LABOUR CODE (EXTERNAL)	JG	302.60
Z990	MISC LABOUR CODE (EXTERNAL)	JG	47.60

Parts

Part #	Description	Qty	Price	Total
AMZCOPPERTA PE	Copper Foil Tape (2inch X 66 FT)	1.00	17.81	17.81

Subtotal for Job #5: 867.81

Job #6 - Warranty

COMPLAINT: CUSTOMER ADVISES THAT ONE OF THE BLINDS IN THE BATHROOM HAS FALLEN DOWN.

CAUSE: Screw had pulled out of the valance

CORRECTION: Took a picture of the blind then inspected why it was sitting wrong. Pulled down the rest of the blind to find that a screw wasn't in place. Put the screw and clip back in the valance and clipped in the blind. Pulled on the blind to make sure it still was functioning. Blind works as should.

Labor

Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	SAR	34.00

Subtotal for Job #6: 34.00

Job #SVCGEN - External

COMPLAINT: Transferred to BAS*75655 on 06 DEC 24

Estimate amount was 0.00

SERVICE GENERATOR OIL/FILTER

CAUSE: Oil change GEN RUN HRS 1

CORRECTION: Removed the generator cover to find the drain plug and fill port. Unbolted the cover to the drain plug then unbolted the drain plug. Let the oil drain, bolted the drain plug back in and tightened. Filled the generator with 1.1 qts of 10w 40 yamalube oil. Checked the oil level after.

Labor

Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	SAR	N/C

Other Services

Code	Description	Qty	Price	Total
SS	SHOP SUPPLIES	0.00	N/C	N/C
PARTS	UNINVENTORIED PARTS	0.00	N/C	N/C
PARTS	UNINVENTORIED PARTS	0.00	N/C	N/C

Subtotal for Job #SVCGEN: 0.00

Job #1 - External

COMPLAINT: Transferred to BAS*75655 on 06 DEC 24

Estimate amount was 0.00

FIX THE ROOF FROM THE ROOF INSPECTION

CAUSE: Cracks and voids

CORRECTION: Cleaned the roof around roof caps, vents, skylight, solar panel, roof edges, antenna, then applied dicor sealer as necessary to fill the cracks and voids.





Labor			
Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	SAR	N/C
Subtotal for Job #1:			0.00

Job #2 - Warranty

COMPLAINT: FIX THE ROOF FROM THE ROOF INSPECTION

CAUSE: Cracks and voids

CORRECTION: Cleaned the roof around roof caps, vents, skylight, solar panel, roof edges, antenna, then applied dicor sealer as necessary to fill the cracks and voids.

Labor				
Code	Description	Mechanic		Total
Z990	MISC LABOUR CODE (EXTERNAL)	SAR		510.00
Parts				
Part #	Description	Qty	Price	Total
13-1287	NON SELF LEVELING DICOR	1.00	6.98	6.98
13-1320	PW HAPS FREE SELF-LEVELING DICOR	7.00	7.71	53.97
Subtotal for Job #2:				570.95

Job #3 - External

NEGATIVE FROM FIX ROOF BECAUSE WARRANTY PAID FOR IT

Labor				
Code	Description	Mechanic		Total
Z990	MISC LABOUR CODE (EXTERNAL)	SAR		N/C
Parts				
Part #	Description	Qty	Price	Total
13-1287	NON SELF LEVELING DICOR	-1.00	N/C	N/C
13-1320	PW HAPS FREE SELF-LEVELING DICOR	-7.00	N/C	N/C
Subtotal for Job #3:				0.00

Parts Total: 78.76
 Labour Total: 1,428.00
 Sublet Total: 0.00
 Extras Total: 0.00
WORK ORDER TOTAL: 1,506.76

Thank you for being a valued customer. We appreciate your business.

All labor is guaranteed for 90 days from invoice date. Guarantee is limited to work performed. Consequential damages are not covered. All guaranteed work must be completed in our service department.

Customer Signature : _____

Date: 27 Jan 2025

