

FOREST RIVER WARRANTY CLAIM FORM

DEALER ACCOUNT #	0005106	CLAIM STATUS	Authorized
BASDEN RV CENTER INC		CLAIM	2156111
DBA AMERICAN RV CENTER		CLAIM ORIGIN	WEB
600 E BASELINE ROAD		ORIGINAL CLAIM ID	
EVANSVILLE, IN 47725		VIN	5ZT2FESB3SW030238
USA		CHASSIS VIN	
		MILEAGE	0
Labor rate:	\$170.00	SITE/WAREHOUSE	320 / 320
OWNER INFORMATION		ITEM #	FET274RKS-320
		DEALER RO #	75623
		CLAIM START DATE	12/20/2024
		CLAIM END DATE	01/01/1900

Retail Date of Purchase _____ WARRANTY EXPIRATION DATE _____

Claim Line Details

Labor

Line# 1

Operation Code	30-101-01-00-001072	Operational Description	Hinged Passage Door Knob - Interior/Interior Doors/Replace/No Tread Code
Complaint, Cause, Correction	Original Note : bhoffman@americanrvcenter.com, 2024-12-20 13:22:37 :: BATHROOM DOOR HANDLE FELL APART AND NEEDS REASSEMBLED I TIGHTENED UP THE SCREW IN THE DOOR HANDLE AND PUT THE SCREW BACK IN THE DOOR HANDLE THAT WAS IN THE FLOOR.		
Model#	Dlr Sub Hrs	0.25	Sub Labor Amt \$42.50
Serial#	Appr Hrs	0.10	Appr Labor Amt \$17.00
Notes	adjusted excess time = resecure handle by tightning 2 screws		

Labor

Line# 2

Operation Code	70-147-24-00-001761	Operational Description	Winegard TV Antenna On Off Power Supply Booster - Appliances/Television/Repair/No Tread Code
Complaint, Cause, Correction	Original Note : bhoffman@americanrvcenter.com, 2024-12-20 13:23:43 :: NO TV RECEPTION ANTENNA I REMOVED THE THE BOOSTER AND FOUND THAT ALL OF THE CABLES GOING TO THE BACK OF THE BOOSTER NEEDED TO HAVE THE CENTER OF THE CABLE PUSHED INTO THE CONNECTOR. AFTER FIXING THE CABLES ON THE BACK OF THE BOOSTER, I WAS ABLE TO GET THE CABLE INPUT TO FEED ALL THE TV PORTS. I STILL HAD NO TV ANTENNA SIGNAL. I REMOVED THE TV ANTENNA TO CHECK THE CABLE AT THE ANTENNA. I FOUND NO PROBLEM WITH THE CABLE. I HOOKED UP A NEW ANTENNA AND THEN I WAS ABLE TO GET SIGNAL TO THE TV PORTS. I REQUESTED A NEW ANTENNA AND THEN INSTALLED THE NEW ANTENNA. AFTER INSTALLING THE NEW TV ANTENNA, I PUT EVERYTHING BACK TOGETHER AND TESTED THE TVS AGAIN. I AM NOW GETTING TV SIGNAL TO ALL TV PORTS WITH BOOSTER ON.		
Model#	Dlr Sub Hrs	2.50	Sub Labor Amt \$425.00
Serial#	Appr Hrs	1.50	Appr Labor Amt \$255.00
Notes	R&RI booster to check connections and adjust the cables for center wires = 0.50; test all cables = 0.50; R&R antenna = 0.50		

Submitted	Labor Amt	\$467.50	Approved	Labor Amt	\$272.00
	Parts & Freight	\$0.00		Parts & Freight	\$0.00
	Total	\$467.50		Total	\$272.00

DEALER _____ DATE _____
SIGNATURE _____
I certify that I have performed these repairs consistent with Forest

CUSTOMER _____ DATE _____
SIGNATURE _____
All repairs described have been inspected and are satisfactory.

