



600 E. Baseline Rd.
Evansville, IN 47725

www.AmericanRVCenter.com

812.867.5200
FAX 812.868.1012

W/O: 75623
Promised Date:
24 DEC 24

CUSTOMER WORK ORDER

WO #: 75623

Customer: 1000 - BASDEN'S AMERICAN
RV -
Tag:
Author: BH
Location: 0102 BH TO CLOSE

Stock #: 11490
Stock Desc: 2025 TT FOREST RIVER
FREEDOM EXPRESS 274RKS
Chassis #: 5ZT2FESB3SW030238
Serial #: 5ZT2FESB3SW030238
Mileage: 0
Licence:

Invoice #:
Date In: 04 DEC 24
Promised: 31 DEC 24
Date Sched:
Completed: 30 DEC 24
Warr. Date:

Job #PDINTT - Internal

COMPLAINT: PDI - NEW TRAVEL TRAILER

CORRECTION: I DID PDI PROCESS AND INSPECTION ON UNIT.

Labor

Code	Description	Mechanic	Total
Z991	MISC LABOUR CODE (INTERNAL)	GAH	N/C
Z991	MISC LABOUR CODE (INTERNAL)	GAH	N/C
Z991	MISC LABOUR CODE (INTERNAL)	GAH	N/C

Parts

Part #	Description	Qty	Price	Total
13034	55362 STD BATTERY BOX	1.00	N/C	N/C

Other Services

Code	Description	Qty	Price	Total
SS	SHOP SUPPLIES	1.00	N/C	N/C
LPGI	LP - UNIT SALES	8.00	N/C	N/C

Subtotal for Job #PDINTT: 0.00

Job #WINTER - Internal

COMPLAINT: WINTERIZE UNIT AND DRAIN HOLDING TANKS.

INCLUDES 2 GALLONS OF ANTI-FREEZE

UNITS WITH WASHING MACHINE OR ICEMAKER
WILL BE EXTRA

DE-WINTERIZATION IS NOT INCLUDED

NUMBER OF GALLONS USED _____

CORRECTION: WINTERIZED UNIT AND DRAINED TANKS. USED 2 GAL OF ANTIFREEZE.

Labor

Code	Description	Mechanic	Total
Z990	WINTERIZE UNIT	GAH	N/C

Parts

Part #	Description	Qty	Price	Total
24181	-50 RV ANTI-FREEZE GALLON	2.00	N/C	N/C

Other Services

Code	Description	Qty	Price	Total
SS	SHOP SUPPLIES	1.00	N/C	N/C

Subtotal for Job #WINTER: 0.00

Customer #: 1000
BASDEN'S AMERICAN RV,



W/O: 75623
 Promised Date: 31 DEC 24



Customer #: 1000
 BASDENS AMERICAN RV,



Job #1 - Warranty

COMPLAINT: BATHROOM DOOR HANDLE FELL APART AND NEEDS REASSEMBLED

CORRECTION: I TIGHTENED UP THE SCREW IN THE DOOR HANDLE AND PUT THE SCREW BACK IN THE DOOR HANDLE THAT WAS IN THE FLOOR.

Labor

Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	GAH	17.00
Subtotal for Job #1:			17.00

Job #2 - Warranty

COMPLAINT: NO TV RECEPTION

CORRECTION: I REMOVED THE THE BOOSTER AND FOUND THAT ALL OF THE CABLES GOING TO THE BACK OF THE BOOSTER NEEDED TO HAVE THE CENTER OF THE CABLE PUSHED INTO THE CONNECTOR. AFTER FIXING THE CABLES ON THE BACK OF THE BOOSTER, I WAS ABLE TO GET THE CABLE INPUT TO FEED ALL THE TV PORTS. I STILL HAD NO TV ANTENNA SIGNAL. I REMOVED THE TV ANTENNA TO CHECK THE CABLE AT THE ANTENNA. I FOUND NO PROBLEM WITH THE CABLE. I HOOKED UP A NEW ANTENNA AND THEN I WAS ABLE TO GET SIGNAL TO THE TV PORTS. I REQUESTED A NEW ANTENNA AND THEN INSTALLED THE NEW ANTENNA. AFTER INSTALLING THE NEW TV ANTENNA, I PUT EVERYTHING BACK TOGETHER AND TESTED THE TVS AGAIN. I AM NOW GETTING TV SIGNAL TO ALL TV PORTS WITH BOOSTER ON.

Labor

Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	GAH	255.00
Z990	MISC LABOUR CODE (EXTERNAL)	GAH	0.00

Parts

Part #	Description	Qty	Price	Total
020041	AR2-5G1 AIR 360+ 5G ANTENNA	1.00	174.80	174.80
PUTTY	PUTTY TAPE - ROLL	1.00	6.16	6.16
13-1320	PW HAPS FREE SELF-LEVELING DICOR	2.00	7.71	15.42
Subtotal for Job #2:				451.38

Parts Total:	196.38
Labour Total:	272.00
Sublet Total:	0.00
Extras Total:	0.00
WORK ORDER TOTAL:	468.38

Thank you for being a valued customer. We appreciate your business.

All labor is guaranteed for 90 days from invoice date. Guarantee is limited to work performed. Consequential damages are not covered. All guaranteed work must be completed in our service department.

Customer Signature : _____

Date: 02 Jan 2025

