



Warranty Authorization Form

Date: 1/2/2025

Basden RV Center, Inc. DBA/ American RV
600 E Baseline Rd
Evansville, IN 47725
Ph. (812) 867-5200
cbruce@americanrvcenter.com

General Information

Pre-Auth #: 81605 Unit: 7M5FA3524SA009926
Series: Avenue Model: 2025AVE32RLS
Notes:
Status: Approved with Modifications

Dealer Information

American RV
(812) 867-5200
cbruce@americanrvcenter.com

Basden RV Center, Inc. DBA/ American RV
600 E Baseline Rd
Evansville, IN 47725

Requestor: Ben Hoffman
Return Fax #:
Email: bhoffman@americanrvcenter.com

Operation Line 1

Flat Rate Code: 14085 TRIM - INTERIOR - REPAIR

Fault Code: LOOSE

Serial #:

Model #:

Notes:

Problem: TRIM IN CLOSET PULLING AWAY

Time Requested: .1

Cause: trim in closet

Time Allowed: .1

Remedy: restapled trim back in place.

Sublet Repairs: 0.00

Part Return Req: No

Status: Approved

Operation Line 2

Flat Rate Code: 14085 TRIM - INTERIOR - REPAIR

Fault Code: LOOSE

Serial #:

Model #:

Notes:

Problem: 2 PIECES OF TRIM ABOVE COUCH ARE COMING OFF

Time Requested: .2

Cause: 2 pieces of trim coming off

Time Allowed: .2

Remedy: had to take valance off and restaple trim in place, then stapled other piece in place then reinstalled valance.

Sublet Repairs: 0.00

Part Return Req: No

Status: Approved

Operation Line 3

Flat Rate Code: 18010B 50 AMP POWER / SHORE POWER CORD -
REPLACE (Photo of defect and entire cord required)

Fault Code: DOCUMENTED

Serial #:

Model #:

Notes: 12/26: Dayra - dealer transports its own units - drivers sign there is a cord present. this would be on the transport the dealer uses - please file through them

Problem: 50 AMP CORD MISSING, WAS NOTED ON DELIVERY FORM

Time Requested: .1

Cause: MISSING CORD

Time Allowed: 0

Remedy: INSTALL NEW CORD

Sublet Repairs: 0.00

Part Return Req: No

Status: Denied

Denial Code: