



600 E. Baseline Rd.
Evansville, IN 47725

www.AmericanRVCenter.com

812.867.5200
FAX 812.868.1012

W/O: 77095
Promised Date:
09 JUN 25

CUSTOMER WORK ORDER

WO #: 77095

Customer: 8283 - NEUKAM, TERRY L. -
812-639-8052

Tag:

Author: BH

Location: 0710 CHECK PREAUTH

Stock #: 11630

Stock Desc: 2026 TT FOREST RIVER
CHEROKEE 301BH

Chassis #: 4X4TCKF25TX167047

Serial #: 4X4TCKF25TX167047

Mileage:

Licence:

Invoice #:

Date In: 21 JUN 25

Promised: 28 JUN 25

Date Sched:

Completed: 08 JUL 25

Warr. Date: 28 JUN 25

Job #PDINTT - Internal

Transferred to BAS*77201 on 01 JUL 25

Estimate amount was 0.00

PDI - NEW TRAVEL TRAILER

Labor

Code	Description	Mechanic	Total
Z991	MISC LABOUR CODE (INTERNAL)	ZMS	N/C
Z991	MISC LABOUR CODE (INTERNAL)	ZMS	N/C
Z991	MISC LABOUR CODE (INTERNAL)	ZMS	N/C
Z991	MISC LABOUR CODE (INTERNAL)	ZMS	N/C
Z991	MISC LABOUR CODE (INTERNAL)	ZMS	N/C

Other Services

Code	Description	Qty	Price	Total
SS	SHOP SUPPLIES	0.00	N/C	N/C
LPGI	LP - UNIT SALES	0.00	N/C	N/C

Subtotal for Job #PDINTT: 0.00

Job #FPDINTT - Internal

Transferred to BAS*77201 on 01 JUL 25

Estimate amount was 0.00

FINAL PDI ON NEW TRAVEL TRAILERS

Labor

Code	Description	Mechanic	Total
PDINTT	PDI - NEW TRAVEL TRAILER	ZMS	N/C
PDINTT	PDI - NEW TRAVEL TRAILER	ZMS	N/C
PDINTT	PDI - NEW TRAVEL TRAILER	ZMS	N/C

Subtotal for Job #FPDINTT: 0.00

Job #SWAP - Internal

Transferred to BAS*77201 on 01 JUL 25

Estimate amount was 0.00

SWAP CUSTOMER'S HITCHWORK

Labor

Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	ZMS	N/C

Customer #: 8283
NEUKAM, TERRY L.





Other Services

Code	Description	Qty	Price	Total
SS	SHOP SUPPLIES	0.00	N/C	N/C

Subtotal for Job #SWAP: 0.00

Job #1 - Warranty

COMPLAINT: FRONT ENTRY DOOR IS HARD TO OPEN

CAUSE: Door is hard to open

CORRECTION: Sprayed latch with lubricant. The door opens easily now.

Labor

Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	ZMS	18.50

Subtotal for Job #1: 18.50

Job #2 - Warranty

COMPLAINT: REAR SCREEN DOOR IS HITTING FRAME

CAUSE: The door is hitting the latch.

CORRECTION: Moved the latch over with a hammer. The screen door is clearing the latch.

Labor

Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	ZMS	37.00

Subtotal for Job #2: 37.00

Job #3 - Warranty

COMPLAINT: OUTDOOR KITCHEN DOOR IS HITTING THE DOOR FRAME

CAUSE: The door is hitting a screw head on the frame

CORRECTION: Tightened screws to pull it away from the door.

Labor

Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	ZMS	37.00

Subtotal for Job #3: 37.00

Job #4 - Warranty

COMPLAINT: REAR ROOF TRIM NEEDS DICOR

CAUSE: The dicor is thin near the edge of the transition strip.

CORRECTION: A

Labor

Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	ZMS	0.00
Z990	MISC LABOUR CODE (EXTERNAL)	ZMS	37.00

Parts

Part #	Description	Qty	Price	Total
13-1320	PW HAPS FREE SELF-LEVELING DICOR	1.00	8.26	8.26



Subtotal for Job #4: 45.26

Parts Total: 8.26
Labour Total: 129.50
Sublet Total: 0.00
Extras Total: 0.00

WORK ORDER TOTAL: 137.76

Thank you for being a valued customer. We appreciate your business.

All labor is guaranteed for 90 days from invoice date. Guarantee is limited to work performed. Consequential damages are not covered. All guaranteed work must be completed in our service department.

Customer Signature : _____

Date: 08 Jul 2025

W/O: 77095
Promised Date: 28 JUN 25



Customer #: 8283
NEUKAM, TERRY L.

