

BASDEN RV CENTER, INC dba AMERICAN RV  
600 E. Baseline Rd.  
Evansville, IN  
US  
47725  
812-867-5200

WARRANTY CLAIM # 77103  
MANUFACTURER'S CLAIM #:

Manufacturer: 10024 - FOREST RIVER TRAVEL TRAILER  
Customer: 1000 - BASDEN'S AMERICAN RV  
Address: 600 E. BASELINE RD. EVANSVILLE, IN  
USA  
47725

Phone:

Stock Number: 11632 - 2025 CATALINA SUMMIT SERIES 134BHX 5ZT2CABC4SK011599  
VIN: 5ZT2CABC4SK011599 HIN: SER#: 5ZT2CABC4SK011599  
Mileage: 0 Work Order Comp: 12 JUL 25  
Auth. No: Dealer #:  
Warr. Date: Work Order Date: 23 JUN 25 Inv #: 419853

\*\*\*\*\*  
WO # Job # Description JOB INFORMATION  
\*\*\*\*\*  
77103 2 ALL WINDOWS NEED SILICONE  
Windows needing silicone  
Added silicone sealer and taped the windows so the silicone  
sealer will make sure the windows wouldn't be leaking and having  
wind sounds coming in  
  
77103 1 ENTRY DOOR IS VERY HARD TO OPEN  
Front door  
the front door was hard to open so i adjusted it by taking the  
screws are reposition them and also took a hammer and flitting  
the striker and latch to insure the door would shut properly  
  
77103 3 BATHROOM DOOR TRIM IS LOOSE  
Bathroom door  
The bathroom door wasn't shutting properly so looked at it and  
noticed the board was bowed so I took it off and then I  
reposition it and also took 5 screws and made the board flat so  
the door would shut properly  
  
77103 4 TOWEL RACK IS LOOSE  
Towel holder  
The towel holder was loose due to the holder not being put in  
properly and also not screwed into the correct position  
  
77103 5 SHOWER NEEDS SILICONE  
Bathroom floor

Claim : 77103

```

*****
WO #      Job #   Description      JOB INFORMATION
*****
          Added silicone sealer to the bottom of the shower flooring to
          insure nothing water would leak and cause damage to the wood
          inside the camper and also protection of the shower surround

77103     6      SHOWER FAUCET IS LOOSE AT THE WALL
          Shower head turns
          When looking in the shower the turn knobs were loose so I took
          off the surround and tightened the knobs up then I added silicone
          around the area to make sure it was sealed up correctly

77103     7      SHOWER CURTAIN ISN'T INSTALLED
          Shower curtain
          Shower curtain was installed incorrectly so I redid the work and
          laced in the tabs in the correct way so the shower curtain can be
          used properly

77103     8      INSIDE STORAGE COMPARTMENT ABOVE FRIDGE IS LOOSE
          Cabinet above refrigerator
          Tightened screws down and now cabinet is set properly

77103     9      TRIM AROUND BEDROOM AREA IS LOOSE
          Trim
          The bedroom trim was loose so I added adhesive and also a small
          amount of super glue to the trim so it wouldn't come loose

77103     10     WATER HEATER NOT HOOKED UP
          Water heater
          When I turned on the switch for the water heater I noticed
          nothing was happening so I took off the cover under the bed and
          found out it wasn't plugged in after plugging in i waited 5
          minutes before turning on hot water to see if it got hot and in
          which case it did so I know the water heater is working correctly
    
```

```

*****
Part No   Job#   Description      PARTS      Qty      Price      Total
*****
SIK432053  2      CLEAR SIKASIL PLUS          1.00      9.17      9.17
    
```

```

*****
Lab Code  Job#   Description      LABOUR      Hrs      Rate      Total
*****
Z990     2      MISC LABOUR CODE (EXTERNAL)  0.40      185.00    74.00
Z990     1      MISC LABOUR CODE (EXTERNAL)  0.20      185.00    37.00
Z990     3      MISC LABOUR CODE (EXTERNAL)  0.00      185.00     0.00
Z990     3      MISC LABOUR CODE (EXTERNAL)  0.10      185.00    18.50
Z990     4      MISC LABOUR CODE (EXTERNAL)  0.10      185.00    18.50
    
```

Claim : 77103

```
*****
Lab Code  Job#  Description          LABOUR          Hrs    Rate    Total
*****
Z990      5  MISC LABOUR CODE (EXTERNAL)      0.20   185.00   37.00
Z990      6  MISC LABOUR CODE (EXTERNAL)      0.40   185.00   74.00
Z990      7  MISC LABOUR CODE (EXTERNAL)      0.20   185.00   37.00
Z990      8  MISC LABOUR CODE (EXTERNAL)      0.20   185.00   37.00
Z990      9  MISC LABOUR CODE (EXTERNAL)      0.10   185.00   18.50
Z990     10  MISC LABOUR CODE (EXTERNAL)      0.20   185.00   37.00
```

Parts Total: 9.17  
Labour Total: 388.50  
Sublet Total: 0.00  
Extras Total: 0.00

>>>> Claim Total: 397.67

Customer Signature: \_\_\_\_\_

Date: \_\_\_\_\_