



600 E. Baseline Rd.
Evansville, IN 47725

www.AmericanRVCenter.com

812.867.5200
FAX 812.868.1012

W/O: 77103



CUSTOMER WORK ORDER

WO #: 77103

Customer: 1000 - BASDEN'S AMERICAN
RV -
Tag:
Author: PH
Location: 0715 CHECK PREAUTH

Stock #: 11632
Stock Desc: 2025 TT COACHMEN
CATALINA SUMMIT SERIES 134BHX
Chassis #: 5ZT2CABC4SK011599
Serial #: 5ZT2CABC4SK011599
Mileage: 0
Licence:

Invoice #:
Date In: 23 JUN 25
Promised:
Date Sched:
Completed: 12 JUL 25
Warr. Date:

Job #PDINTT - Internal

PDI - NEW TRAVEL TRAILER - 3 HR PDI

Labor

Code	Description	Mechanic	Total
Z991	MISC LABOUR CODE (INTERNAL)	JLC	N/C
Z991	MISC LABOUR CODE (INTERNAL)	JLC	N/C
Z991	MISC LABOUR CODE (INTERNAL)	JLC	N/C
Z991	MISC LABOUR CODE (INTERNAL)	JLC	N/C

Parts

Part #	Description	Qty	Price	Total
13034	55362 STD BATTERY BOX	1.00	N/C	N/C

Other Services

Code	Description	Qty	Price	Total
SS	SHOP SUPPLIES	1.00	N/C	N/C
LPGI	LP - UNIT SALES	4.00	N/C	N/C

Subtotal for Job #PDINTT: 0.00

Job #1 - Warranty

COMPLAINT: ENTRY DOOR IS VERY HARD TO OPEN

CAUSE: Front door

CORRECTION: the front door was hard to open so i adjusted it by taking the screws are reposition them and also took a hammer and flitting the striker and latch to insure the door would shut properly

Labor

Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	JLC	37.00

Subtotal for Job #1: 37.00

Job #2 - Warranty

COMPLAINT: ALL WINDOWS NEED SILICONE

CAUSE: Windows needing silicone

CORRECTION: Added silicone sealer and taped the windows so the silicone sealer will make sure the windows wouldn't be leaking and having wind sounds coming in

Labor

Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	JLC	74.00



Customer #: 1000
BASDEN'S AMERICAN RV,



Parts

Part #	Description	Qty	Price	Total
500627	CLEAR SIKASIL PLUS	1.00	9.17	9.17

Subtotal for Job #2: 83.17

Job #3 - Warranty

COMPLAINT: BATHROOM DOOR TRIM IS LOOSE

CAUSE: Bathroom door

CORRECTION: The bathroom door wasn't shutting properly so looked at it and noticed the board was bowed so I took it off and then I reposition it and also took 5 screws and made the board flat so the door would shut properly

Labor

Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	JLC	0.00
Z990	MISC LABOUR CODE (EXTERNAL)	JLC	18.50

Subtotal for Job #3: 18.50

Job #4 - Warranty

COMPLAINT: TOWEL RACK IS LOOSE

CAUSE: Towel holder

CORRECTION: The towel holder was loose due to the holder not being put in properly and also not screwed into the correct position

Labor

Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	JLC	18.50

Subtotal for Job #4: 18.50

Job #5 - Warranty

COMPLAINT: SHOWER NEEDS SILICONE

CAUSE: Bathroom floor

CORRECTION: Added silicone sealer to the bottom of the shower flooring to insure nothing water would leak and cause damage to the wood inside the camper and also protection of the shower surround

Labor

Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	JLC	37.00

Subtotal for Job #5: 37.00

Job #6 - Warranty

COMPLAINT: SHOWER FAUCET IS LOOSE AT THE WALL

CAUSE: Shower head turns

CORRECTION: When looking in the shower the turn knobs were loose so I took off the surround and tightened the knobs up then I added silicone around the area to make sure it was sealed up correctly

Labor

Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	JLC	74.00



Customer #: 1000
BASDEN'S AMERICAN RV,



Subtotal for Job #6: 74.00

Job #7 - Warranty

COMPLAINT: SHOWER CURTAIN ISN'T INSTALLED

CAUSE: Shower curtain

CORRECTION: Shower curtain was installed incorrectly so I redid the work and laced in the tabs in the correct way so the shower curtain can be used properly

Labor Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	JLC	37.00

Subtotal for Job #7: 37.00

Job #8 - Warranty

COMPLAINT: INSIDE STORAGE COMPARTMENT ABOVE FRIDGE IS LOOSE

CAUSE: Cabinet above refrigerator

CORRECTION: Tightened screws down and now cabinet is set properly

Labor Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	JLC	37.00

Subtotal for Job #8: 37.00

Job #9 - Warranty

COMPLAINT: TRIM AROUND BEDROOM AREA IS LOOSE

CAUSE: Trim

CORRECTION: The bedroom trim was loose so I added adhesive and also a small amount of super glue to the trim so it wouldn't come loose

Labor Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	JLC	18.50

Subtotal for Job #9: 18.50

Job #10 - Warranty

COMPLAINT: WATER HEATER NOT HOOKED UP

CAUSE: Water heater

CORRECTION: When I turned on the switch for the water heater I noticed nothing was happening so I took off the cover under the bed and found out it wasn't plugged in after plugging in i waited 5 minutes before turning on hot water to see if it got hot and in which case it did so I know the water heater is working correctly

Labor Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	JLC	37.00

Subtotal for Job #10: 37.00

W/O: 77103



Customer #: 1000
BASDEN'S AMERICAN RV,



Parts Total: 9.17
Labour Total: 388.50
Sublet Total: 0.00
Extras Total: 0.00
WORK ORDER TOTAL: 397.67

W/O: 77103

Thank you for being a valued customer. We appreciate your business.

All labor is guaranteed for 90 days from invoice date. Guarantee is limited to work performed. Consequential damages are not covered. All guaranteed work must be completed in our service department.

Customer Signature : _____

Date: 12 Jul 2025



Customer #: 1000
BASDEN'S AMERICAN RV,



Customer Work Order

