

FOREST RIVER WARRANTY CLAIM FORM

DEALER ACCOUNT # 0005106
BASDEN RV CENTER INC
DBA AMERICAN RV CENTER
600 E BASELINE ROAD
EVANSVILLE, IN 47725
USA

CLAIM STATUS Authorized
CLAIM 2363958
CLAIM ORIGIN WEB
ORIGINAL CLAIM ID
VIN 5ZT2CABC8SK011654
CHASSIS VIN
MILEAGE 0
SITE/WAREHOUSE 203 / 203
ITEM # BCAT134RKX
DEALER RO # 77106
CLAIM START DATE 07/11/2025
CLAIM END DATE 01/01/1900

Labor rate: \$185.00

OWNER INFORMATION

Retail Date of Purchase

WARRANTY EXPIRATION DATE

Claim Line Details

Labor

Line# 1 **Operation Code** **Operational Description**
20-66-02-17-000672 Striker Plate or Door Lock - Exterior/Entry Doors/Adjust/Latch
Complaint, Cause, Correction
Original Note : bhoffman@americanrvcenter.com, 2025-07-11 13:33:18 :: ENTRY DOOR NEEDS ADJUSTED Front door Adjusted front door by moving the striker plate as well flattened the hinge out some now door will shut properly
Model# **Dlr Sub Hrs** 0.20 **Sub Labor Amt** \$37.00
Serial# **Appr Hrs** 0.20 **Appr Labor Amt** \$37.00
Notes

Labor

Line# 2 **Operation Code** **Operational Description**
20-46-01-00-000733 Screw Cover - Exterior/Windows/Replace/No Tread Code
Complaint, Cause, Correction
Original Note : bhoffman@americanrvcenter.com, 2025-07-11 13:44:25 :: REFRIGERATOR IS MAKING A LOUD NOISE WHEN RUNNING Refrigerator Refrigerator was making a sound and found out it was a loose screw in the back of it rubbing
Model# **Dlr Sub Hrs** 0.10 **Sub Labor Amt** \$18.50
Serial# **Appr Hrs** 0.10 **Appr Labor Amt** \$18.50
Notes

Labor

Line# 3 **Operation Code** **Operational Description**
30-100-19-00-001054 Kitchen/Galley Countertop - Interior/Cabinetry/Reseal/No Tread Code
Complaint, Cause, Correction
Original Note : bhoffman@americanrvcenter.com, 2025-07-11 13:46:43 :: KITCHEN AREA NEEDS SILICONED aKitchen needed silicone Added silicone to the bottom of the base boards to insure that the water wouldn't get in and cause water damage
Model# **Dlr Sub Hrs** 0.20 **Sub Labor Amt** \$37.00
Serial# **Appr Hrs** 0.20 **Appr Labor Amt** \$37.00
Notes

Labor

Line# 4 **Operation Code** **Operational Description**
60-141-01-00-001618 Shower Head, Hose Assembly - Plumbing/Shower, Tub Surround/Replace/No Tread Code
Complaint, Cause, Correction
Original Note : bhoffman@americanrvcenter.com, 2025-07-11 13:47:37 :: SHOWER HEAD IS LEAKING Shower head The shower head was put on sideways making it leak and when put on correctly it's not leaking

Model#	Dlr Sub Hrs	0.10	Sub Labor Amt	\$18.50
Serial#	Appr Hrs	0.10	Appr Labor Amt	\$18.50
Notes				

Labor

Line# 5	Operation Code	Operational Description		
	30-92-19-00-004336	Spot Seal Interior (Dealer) - Interior/Interior Miscellaneous/Reseal/No Tread Code		
Complaint, Cause, Correction				
Original Note : bhoffman@americanrvcenter.com, 2025-07-11 13:49:15 :: SHOWER WALLS NEED SILICONED Bathroom needed silicone Added silicone sealer to the side that water would go through and now is all sealed up				
Model#	Dlr Sub Hrs	0.10	Sub Labor Amt	\$18.50
Serial#	Appr Hrs	0.10	Appr Labor Amt	\$18.50
Notes				
UPDATED REPAIR CODE				

Labor

Line# 6	Operation Code	Operational Description		
	30-102-24-00-001094	Wall Panel Touch up - Luan - Interior/Panels, Ceilings, & Interior Moldings/Repair/No Tread Code		
Complaint, Cause, Correction				
Original Note : bhoffman@americanrvcenter.com, 2025-07-11 14:01:37 :: WALLPAPER IS COMING LOOSE Seam tape is loose Seam tape is loose and will need to have 2 or 3 staples in it as well as new seam tape if need replaced				
Model#	Dlr Sub Hrs	0.20	Sub Labor Amt	\$37.00
Serial#	Appr Hrs	0.20	Appr Labor Amt	\$37.00
Notes				

Labor

Line# 7	Operation Code	Operational Description		
	30-101-02-00-001077	Hinged Passage Door Striker - Interior/Interior Doors/Adjust/No Tread Code		
Complaint, Cause, Correction				
Original Note : bhoffman@americanrvcenter.com, 2025-07-11 14:03:03 :: BATHROOM DOOR IS NOT SHUTTING Bathroom door Had to adjust the door latch so the door will shut properly and smoother				
Model#	Dlr Sub Hrs	0.10	Sub Labor Amt	\$18.50
Serial#	Appr Hrs	0.10	Appr Labor Amt	\$18.50
Notes				

Labor

Line# 8	Operation Code	Operational Description		
	30-91-24-11-001301	LED Light Strip or Rope Lights - Interior/Living Quarters, Sofa, Chair/Repair/Electrical		
Complaint, Cause, Correction				
Original Note : bhoffman@americanrvcenter.com, 2025-07-11 14:04:22 :: LED STRIPE LIGHT ON FRONT NOSE CAP NEEDS REGLUED Led lights Led lights were out of track so I pushed them back into track then added a small amount of silicone sealer to insure they are waterproof and not going to be ruined by rain				
Model#	Dlr Sub Hrs	0.20	Sub Labor Amt	\$37.00
Serial#	Appr Hrs	0.20	Appr Labor Amt	\$37.00
Notes				
AUTHORIZED AS REQUESTED.				

Submitted	Labor Amt	\$222.00	Approved	Labor Amt	\$222.00
	Parts & Freight	\$0.00		Parts & Freight	\$0.00
	Total	\$222.00		Total	\$222.00

DEALER	DATE
--------	------

CUSTOMER	DATE
----------	------

SIGNATURE

I certify that I have performed these repairs consistent with Forest River Policies.

SIGNATURE

All repairs described have been inspected and are satisfactory.