



600 E. Baseline Rd.
Evansville, IN 47725

www.AmericanRVCenter.com

812.867.5200
FAX 812.868.1012

W/O: 77106
Promised Date: 24 JUL 25

CUSTOMER WORK ORDER

WO #: 77106

Customer: 1000 - BASDEN'S AMERICAN
RV -
Tag:
Author: PH
Location: 0730 CHECK WORK

Stock #: 11631
Stock Desc: 2025 TT COACHMEN
CATALINA SUMMIT SERIES 134RKX
Chassis #: 5ZT2CABC8SK011654
Serial #: 5ZT2CABC8SK011654
Mileage: 0
Licence:

Invoice #:
Date In: 23 JUN 25
Promised: 31 JUL 25
Date Sched:
Completed: 26 JUL 25
Warr. Date:

Job #PDINTT - Internal

COMPLAINT: PDI - NEW TRAVEL TRAILER - 3 HR PDI

CAUSE: Pdi

CORRECTION: Started on new pdi

Checked all exterior lights,tires, checked roof and seals on windows, checked all interior lights and outlets, checked all cabinets and also doors all shut, ran all antifreeze out of lines also checked for leaks, checked all flooring for cracks and no evidence of any showing, checked all beds,filled lp also did the drop test while checking the furnance and water heater and working correctly, checked tv connection and is working correctly, radio is working inside and outside , Furance is working properly as well as ac, smoke detector is working/ carbon monoxide detector is working, refrigerator and microwave are working properly, drained all black and grey tanks

Labor

Code	Description	Mechanic	Total
Z991	MISC LABOUR CODE (INTERNAL)	JLC	N/C
Z991	MISC LABOUR CODE (INTERNAL)	JLC	N/C
Z991	MISC LABOUR CODE (INTERNAL)	JLC	N/C
Z991	MISC LABOUR CODE (INTERNAL)	JLC	N/C

Parts

Part #	Description	Qty	Price	Total
13034	55362 STD BATTERY BOX	1.00	N/C	N/C

Other Services

Code	Description	Qty	Price	Total
SS	SHOP SUPPLIES	0.00	N/C	N/C
LPGI	LP - UNIT SALES	4.00	N/C	N/C

Subtotal for Job #PDINTT: 0.00

Job #1 - Warranty

COMPLAINT: ENTRY DOOR NEEDS ADJUSTED

CAUSE: Front door

CORRECTION: Adjusted frontdoor by moving the striker plate as well flattened the hinge out some now door will shut properly

Labor

Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	JLC	0.00
Z990	MISC LABOUR CODE (EXTERNAL)	CCV	37.00



Customer #: 1000
BASDEN'S AMERICAN RV,





Subtotal for Job #1: 37.00

Job #2 - Warranty

COMPLAINT: REFRIGERATOR IS MAKING A LOUD NOISE WHEN RUNNING

CAUSE: Refrigerator

CORRECTION: Refrigerator was making a sound and found out it was a loose screw in the back of it rubbing

Labor			
Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	JLC	0.00
Z990	MISC LABOUR CODE (EXTERNAL)	JLC	18.50

Subtotal for Job #2: 18.50

Job #3 - Warranty

COMPLAINT: KITCHEN AREA NEEDS SILICONED

CAUSE: Kitchen needed silicone

CORRECTION: Added silicone to the bottom of the base boards to insure that the water wouldn't get in and cause water damage

Labor			
Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	JLC	37.00

Subtotal for Job #3: 37.00

Job #4 - Warranty

COMPLAINT: SHOWER HEAD IS LEAKING

CAUSE: Shower head

CORRECTION: The shower head was put on sideways making it leak and when put on correctly it's not leaking

Labor			
Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	JLC	9.25
Z990	MISC LABOUR CODE (EXTERNAL)	JLC	9.25

Subtotal for Job #4: 18.50

Job #5 - Warranty

COMPLAINT: SHOWER WALLS NEED SILICONED

CAUSE: Bathroom needed silicone

CORRECTION: Added silicone sealer to the side that water would go through and now is all sealed up

Labor			
Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	JLC	12.95
Z990	MISC LABOUR CODE (EXTERNAL)	JLC	5.55

Subtotal for Job #5: 18.50

Job #6 - Warranty

COMPLAINT: WALLPAPER IS COMING LOOSE

CAUSE: Seam tape is loose





CORRECTION: Seam tape is loose and will need to have 2 or 3 staples in it as well as new seam tape if need replaced

Labor

Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	JLC	9.25
Z990	MISC LABOUR CODE (EXTERNAL)	JLC	27.75
Z990	MISC LABOUR CODE (EXTERNAL)		0.00

Parts

Part #	Description	Qty	Price	Total
F100418113	TAPE, SEAM 1" GAUZE ASH	6.00	0.21	1.26

Other Services

Code	Description	Qty	Price	Total
FRT	FREIGHT	1.00	15.68	15.68

Subtotal for Job #6: 53.94

Job #7 - Warranty

COMPLAINT: BATHROOM DOOR IS NOT SHUTTING

CAUSE: Bathroom door

CORRECTION: Had to adjust the door latch so the door will shut properly and smoother

Labor

Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	JLC	0.00
Z990	MISC LABOUR CODE (EXTERNAL)	JLC	18.50

Subtotal for Job #7: 18.50

Job #8 - Warranty

COMPLAINT: LED STRIPE LIGHT ON FRONT NOSE CAP NEEDS REGLUED

CAUSE: Led lights

CORRECTION: Led lights were out of track so I pushed them back into track then added a small amount of silicone sealer to insure they are waterproof and not going to be ruined by rain

Labor

Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	JLC	37.00

Parts

Part #	Description	Qty	Price	Total
500627	CLEAR SIKASIL PLUS	1.00	9.17	9.17

Subtotal for Job #8: 46.17

Job #9 - Internal

COMPLAINT: GRIP TAPE ON STEPS NEEDS REPLACED

CAUSE: grip tape on step torn

CORRECTION: pulled off old grip tape and replaced with new

Labor

Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	CCV	N/C

Subtotal for Job #9: 0.00



W/O: 77106
Promised Date: 31 JUL 25

Parts Total:	10.43
Labour Total:	222.00
Sublet Total:	0.00
Extras Total:	15.68
WORK ORDER TOTAL:	248.11

Thank you for being a valued customer. We appreciate your business.

All labor is guaranteed for 90 days from invoice date. Guarantee is limited to work performed. Consequential damages are not covered. All guaranteed work must be completed in our service department.

Customer Signature : _____

Date: 26 Jul 2025



Customer #: 1000
BASDEN'S AMERICAN RV,

