

BASDEN RV CENTER, INC dba AMERICAN RV
600 E. Baseline Rd.
Evansville, IN
US
47725
812-867-5200

WARRANTY CLAIM # 77108
MANUFACTURER'S CLAIM #:

Manufacturer: 10024 - FOREST RIVER TRAVEL TRAILER
Customer: 1000 - BASDEN'S AMERICAN RV
Address: 600 E. BASELINE RD. EVANSVILLE, IN
USA
47725
Phone:
Stock Number: 11634 - 2026 CHEROKEE WOLF PUP 16BHSW 5ZT2CKEC8TY038921
VIN: 5ZT2CKEC8TY038921 HIN: SER#: 5ZT2CKEC8TY038921
Mileage: 0 Work Order Comp: 30 JUN 25
Auth. No: Dealer #:
Warr. Date: Work Order Date: 23 JUN 25 Inv #: 419469

WO # Job # Description JOB INFORMATION

77108 1 THE DINING TABLE NEEDS TO BE SECURED
Dinner table
Table had 3 screws loose on each side so took my drill and
tightened screws and the table is more sturdy and isn't moving
near as much

77108 2 THE KITCHEN CABINET DOOR NEEDS TO BE TIGHTENED
Cabinet door
Took cabinetdoor off and rescrewed in 2 screws so the cabinets
will shut properly

77108 4 THE OUTDOOR REFRIGERATOR IS NOT FUNCTIONING PROPERLY
Outside refrigerator
Refrigerator wasn't working so i looked to see where the plug was
so I took off the wooden panel come to find out it was unplugged
in so I plugged it in now is working properly

77108 5 THE TOILET IS NOT SECURED TO THE FLOOR PROPERLY
Loose toilet
Took some clear silicone sealer and added on bottom of toilet so
the bottom of it is more secured and sealed to the toilet insure
that it wouldn't come loose

77108 6 THE MICROWAVE IS NOT SECURED IN PLACE PROPERLY
Microwave
When looking at microwave I noticed it had some screws that were

Claim : 77108

 WO # Job # Description JOB INFORMATION

loose so I took my drill gun and found the correct bit and
 replace the screws and drilled them in so the microwave wouldn't
 shift during travel

77108 7 THERE IS A SMALL HOLE IN THE CEILING
 Hole in ceiling
 Took some white putty and covered up hole in ceiling then
 smoothed it out with a towel for texture look of ceiling

77108 8 THIS UNIT IS NOT SEALED PROPERLY AROUND THE BATHTUB
 Bathroom shower loose
 Took some clear silicone and applied to the areas that were
 needing it and filled in the gaps with it then I took off tape

 Lab Code Job# Description LABOUR Hrs Rate Total

 Z990 1 MISC LABOUR CODE (EXTERNAL) 0.20 185.00 37.00
 Z990 2 MISC LABOUR CODE (EXTERNAL) 0.15 185.00 27.75
 Z990 2 MISC LABOUR CODE (EXTERNAL) 0.15 185.00 27.75
 Z990 4 MISC LABOUR CODE (EXTERNAL) 0.10 185.00 18.50
 Z990 5 MISC LABOUR CODE (EXTERNAL) 0.10 185.00 18.50
 Z990 6 MISC LABOUR CODE (EXTERNAL) 0.10 185.00 18.50
 Z990 7 MISC LABOUR CODE (EXTERNAL) 0.10 185.00 18.50
 Z990 8 MISC LABOUR CODE (EXTERNAL) 0.10 185.00 18.50

Parts Total: 0.00
 Labour Total: 185.00
 Sublet Total: 0.00
 Extras Total: 0.00

>>>> Claim Total: 185.00

Customer Signature: _____

Date: _____