

FOREST RIVER WARRANTY CLAIM FORM

DEALER ACCOUNT #	0005106	CLAIM STATUS	Authorized
BASDEN RV CENTER INC		CLAIM	2349968
DBA AMERICAN RV CENTER		CLAIM ORIGIN	WEB
600 E BASELINE ROAD		ORIGINAL CLAIM ID	
EVANSVILLE, IN 47725		VIN	5ZT2CKEC8TY038921
USA		CHASSIS VIN	
		MILEAGE	0
Labor rate:	\$185.00	SITE/WAREHOUSE	095 / 095A
OWNER INFORMATION		ITEM #	CKT16BHSW-95
		DEALER RO #	77108
		CLAIM START DATE	06/28/2025
		CLAIM END DATE	01/01/1900

Retail Date of Purchase

WARRANTY EXPIRATION DATE

Claim Line Details

Labor

Line# 1	Operation Code	Operational Description		
	30-95-24-00-000948	Dinette Table Top - Booth - Interior/Dinette/Repair/No Tread Code		
	Complaint, Cause, Correction			
	Original Note : bhoffman@americanrvcenter.com, 2025-06-28 14:14:49 :: THE DINING TABLE NEEDS TO BE SECURED Dinner table Table had 3 screws loose on each side so took my drill and tightened screws and the table is more sturdy and isn't moving near as much			
Model#	Dlr Sub Hrs	0.20	Sub Labor Amt	\$37.00
Serial#	Appr Hrs	0.20	Appr Labor Amt	\$37.00
	Notes			

Labor

Line# 2	Operation Code	Operational Description		
	30-100-24-00-001046	Cabinet Door - Interior/Cabinetry/Repair/No Tread Code		
	Complaint, Cause, Correction			
	Original Note : bhoffman@americanrvcenter.com, 2025-06-28 14:16:06 :: THE KITCHEN CABINET DOOR NEEDS TO BE TIGHTENED Cabinet door Took cabinetdoor off and rescrewed in 2 screws so the cabinets will shut properly			
Model#	Dlr Sub Hrs	0.30	Sub Labor Amt	\$55.50
Serial#	Appr Hrs	0.30	Appr Labor Amt	\$55.50
	Notes			

Labor

Line# 3	Operation Code	Operational Description		
	70-675-01-11-003364	Hotpoint Mini Refrigerator - Appliances/Mini Refrigerator (Hotpoint)/Replace/ Electrical		
	Complaint, Cause, Correction			
	Original Note : bhoffman@americanrvcenter.com, 2025-06-28 14:18:34 :: THE OUTDOOR REFRIGERATOR IS NOT FUNCTIONING PROPERLY Outside refrigerator Refrigerator wasn't working so i looked to see where the plug was so I took off the wooden panel come to find out it was unplugged in so I plugged it in now is working properly Additional Note : bhoffman@americanrvcenter.com, 2025-06-28 14:19:22 :: ONLY PLUG UNIT IN			
Model# NA	Dlr Sub Hrs	0.10	Sub Labor Amt	\$18.50
Serial# NA	Appr Hrs	0.10	Appr Labor Amt	\$18.50
	Notes			
	dealer plugged in outside moni refrigerator thank you			

Labor

Line# 4	Operation Code	Operational Description		
	60-137-12-00-001374	Toilet Seat - Plumbing/Toilet (Thetford)/Resecure or Tighten/No Tread Code		
	Complaint, Cause, Correction			

Original Note : bhoffman@americanrvcenter.com, 2025-06-28 14:20:07 :: THE TOILET IS NOT SECURED TO THE FLOOR PROPERLY Loose toilet Took some clear silicone sealer and added on bottom of toilet so the bottom of it is more secured and sealed to the toilet insure that it wouldn't come loose

Model#	Dlr Sub Hrs	0.10	Sub Labor Amt	\$18.50
Serial#	Appr Hrs	0.10	Appr Labor Amt	\$18.50
Notes				

Labor

Line# 5	Operation Code 70-150-24-00-002780 Complaint, Cause, Correction Original Note : bhoffman@americanrvcenter.com, 2025-06-28 14:22:29 :: THE MICROWAVE IS NOT SECURED IN PLACE PROPERLY Microwave When looking at microwave I noticed it had some screws that were loose so I took my drill gun and found the correct bit and replace the screws and drilled them in sothe microwave wouldn't shift during travel	Operational Description Greystone Microwave - Appliances/Microwave/Repair/No Tread Code		
Model# NA	Dlr Sub Hrs	0.10	Sub Labor Amt	\$18.50
Serial# NA	Appr Hrs	0.10	Appr Labor Amt	\$18.50
Notes				

Labor

Line# 6	Operation Code 30-102-24-00-003061 Complaint, Cause, Correction Original Note : bhoffman@americanrvcenter.com, 2025-06-28 14:24:18 :: THERE IS A SMALL HOLE IN THE CEILING Hole in ceiling Took some white putty and covered up hole in ceiling then smoothed it out with a towel for texture look of ceiling	Operational Description Ceiling Panel - Touchup - Interior/Panels, Ceilings, & Interior Moldings/Repair/No Tread Code		
Model#	Dlr Sub Hrs	0.10	Sub Labor Amt	\$18.50
Serial#	Appr Hrs	0.10	Appr Labor Amt	\$18.50
Notes				

Labor

Line# 7	Operation Code 60-141-12-00-001592 Complaint, Cause, Correction Original Note : bhoffman@americanrvcenter.com, 2025-06-28 14:33:20 :: THIS UNIT IS NOT SEALED PROPERLY AROUND THE BATHTUB Bathroom shower loose Took some clear silicone and applied to the areas that were needing it and filled in the gaps with it then I took off tape	Operational Description Tub Surround to Wall, each section - Plumbing/Shower, Tub Surround/Resecure or Tighten/No Tread Code		
Model#	Dlr Sub Hrs	0.10	Sub Labor Amt	\$18.50
Serial#	Appr Hrs	0.10	Appr Labor Amt	\$18.50
Notes				

Submitted	Labor Amt	\$185.00	Approved	Labor Amt	\$185.00
	Parts & Freight	\$0.00		Parts & Freight	\$0.00
	Total	\$185.00		Total	\$185.00

DEALER	DATE
SIGNATURE	

I certify that I have performed these repairs consistent with Forest River Policies.

CUSTOMER	DATE
SIGNATURE	

All repairs described have been inspected and are satisfactory.