



600 E. Baseline Rd.
Evansville, IN 47725

www.AmericanRVCenter.com

812.867.5200
FAX 812.868.1012

W/O: 77108
Promised Date:
20 JUN 25

CUSTOMER WORK ORDER

WO #: 77108

Customer: 1000 - BASDEN'S AMERICAN
RV -
Tag:
Author: PH
Location: 0707 BH TO DO PREAUTH

Stock #: 11634
Stock Desc: 2026 TT FOREST RIVER
CHEROKEE WOLF PUP 16BHSW
Chassis #: 5ZT2CKEC8TY038921
Serial #: 5ZT2CKEC8TY038921
Mileage: 0
Licence:

Invoice #:
Date In: 23 JUN 25
Promised: 30 JUN 25
Date Sched:
Completed: 30 JUN 25
Warr. Date:

Job #PDINTT - Internal

Transferred to BAS*77216 on 02 JUL 25
Estimate amount was 0.00
PDI - NEW TRAVEL TRAILER - 4 HR PDI

Labor

Code	Description	Mechanic	Total
Z991	MISC LABOUR CODE (INTERNAL)	JLC	N/C
Z991	MISC LABOUR CODE (INTERNAL)	JLC	N/C
Z991	MISC LABOUR CODE (INTERNAL)	JLC	N/C
Z991	MISC LABOUR CODE (INTERNAL)	JLC	N/C

Other Services

Code	Description	Qty	Price	Total
SS	SHOP SUPPLIES	0.00	N/C	N/C
LPGI	LP - UNIT SALES	0.00	N/C	N/C

Subtotal for Job #PDINTT: 0.00

Job #1 - Warranty

COMPLAINT: THE DINING TABLE NEEDS TO BE SECURED

CAUSE: Dinner table

CORRECTION: Table had 3 screws loose on each side so took my drill and tightened screws and the table is more sturdy and isn't moving near as much

Labor

Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	JLC	37.00

Subtotal for Job #1: 37.00

Job #2 - Warranty

COMPLAINT: THE KITCHEN CABINET DOOR NEEDS TO BE TIGHTENED

CAUSE: Cabinet door

CORRECTION: Took cabinetdoor off and rescrewed in 2 screws so the cabinets will shut properly

Labor

Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	JLC	27.75
Z990	MISC LABOUR CODE (EXTERNAL)	JLC	27.75



Customer #: 1000
BASDEN'S AMERICAN RV,



Subtotal for Job #2: 55.50

Job #3 - Internal

COMPLAINT: Transferred to BAS*77216 on 02 JUL 25
 Estimate amount was 0.00
 THE AIR CONDITIONER IS NOT BLOWING COOL AIR

CAUSE: Air-conditioner

CORRECTION: The air conditioner wasn't cooling so I took the air vent down and found out the vents were shut and so I opened them up and changed the settings now is working properly

Labor			
Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	JLC	N/C
Subtotal for Job #3:			0.00

Job #4 - Warranty

COMPLAINT: THE OUTDOOR REFRIGERATOR IS NOT FUNCTIONING PROPERLY

CAUSE: Outside refrigerator

CORRECTION: Refrigerator wasn't working so i looked to see where the plug was so I took off the wooden panel come to find out it was unplugged in so I plugged it in now is working properly

Labor			
Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	JLC	18.50
Subtotal for Job #4:			18.50

Job #5 - Warranty

COMPLAINT: THE TOILET IS NOT SECURED TO THE FLOOR PROPERLY

CAUSE: Loose toilet

CORRECTION: Took some clear silicone sealer and added on bottom of toilet so the bottom of it is more secured and sealed to the toilet insure that it wouldn't come loose

Labor			
Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	JLC	18.50
Subtotal for Job #5:			18.50

Job #6 - Warranty

COMPLAINT: THE MICROWAVE IS NOT SECURED IN PLACE PROPERLY

CAUSE: Microwave

CORRECTION: When looking at microwave I noticed it had some screws that were loose so I took my drill gun and found the correct bit and replace the screws and drilled them in so the microwave wouldn't shift during travel

Labor			
Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	JLC	18.50
Subtotal for Job #6:			18.50

Job #7 - Warranty

COMPLAINT: THERE IS A SMALL HOLE IN THE CEILING





CAUSE: Hole in ceiling

CORRECTION: Took some white putty and covered up hole in ceiling then smoothed it out with a towel for texture look of ceiling

Labor Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	JLC	18.50
Subtotal for Job #7:			18.50

Job #8 - Warranty

COMPLAINT: THIS UNIT IS NOT SEALED PROPERLY AROUND THE BATHTUB

CAUSE: Bathroom shower loose

CORRECTION: Took some clear silicone and applied to the areas that were needing it and filled in the gaps with it then I took off tape

Labor Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	JLC	18.50
Subtotal for Job #8:			18.50

Job #9 - Internal

COMPLAINT: Transferred to BAS*77216 on 02 JUL 25

Estimate amount was 0.00

THE FRONT DOOR IS NOT ADJUSTED PROPERLY

CAUSE: Frontdoor wouldn't shut

CORRECTION: Front door wasn't shutting properly so I adjusted the stairs as well as slightly adjusted screen door and now door will shut properly when adjusted the stairs

Labor Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	JLC	N/C
Z990	MISC LABOUR CODE (EXTERNAL)	JLC	N/C
Subtotal for Job #9:			0.00

Parts Total:	0.00
Labour Total:	185.00
Sublet Total:	0.00
Extras Total:	0.00
WORK ORDER TOTAL:	185.00

Thank you for being a valued customer. We appreciate your business.

All labor is guaranteed for 90 days from invoice date. Guarantee is limited to work performed. Consequential damages are not covered. All guaranteed work must be completed in our service department.

Customer Signature : _____

Date: 02 Jul 2025

