



600 E. Baseline Rd.  
Evansville, IN 47725

www.AmericanRVCenter.com

812.867.5200  
FAX 812.868.1012

W/O: 77141  
Promised Date:  
07 JUN 25


### CUSTOMER WORK ORDER

WO #: 77141

Customer: 20806 - GRAHAM, GREGORY  
- 812-499-4295  
Tag:  
Author: BH  
Location: DELIVERY 0627

Stock #: 11502  
Stock Desc: 2025 TT COACHMEN  
FREEDOM EXPRESS 18SE  
Chassis #: 5ZT2FEGB0SW030416  
Serial #: 5ZT2FEGB0SW030416  
Mileage:  
Licence:

Invoice #:  
Date In: 25 JUN 25  
Promised: 27 JUN 25  
Date Sched:  
Completed: 30 JUN 25  
Warr. Date: 27 JUN 25



#### Job #FPDINTT - Internal

COMPLAINT: FINAL PDI ON NEW TRAVEL TRAILERS

CAUSE: Final inspection before delivery

CORRECTION: Received a new battery from the parts department and mounted it in the battery box. Plugged in the test box and tested the running lights, brakes and breakaway switch. Inspected the roof membrane and sealer, and touch-up any spots as necessary. Plugged in the shore power, tested the lp detector, smoke alarm, tv, microwave, slide, ac, 120v outlets. Started the lp drop test at the stove. Adjusted the lp regulator as necessary with the furnace and water heater running. Let the fridge cool. Checked the emergency exits. Checked and set lug nut torque to 110ftlbs. Checked and set tires to 65psi. Found the water heater door was chipping paint and rusted, got with Ben. Put in po for a new water heater door. Ran awning in and out

#### Labor

Code	Description	Mechanic	Total
PDINTT	PDI - NEW TRAVEL TRAILER	SAR	N/C
PDINTT	PDI - NEW TRAVEL TRAILER	SAR	N/C

#### Parts

Part #	Description	Qty	Price	Total
DC-24	ADVANCE GROUP 24 DEEP CYCLE BATTERY	1.00	N/C	N/C

**Subtotal for Job #FPDINTT: 0.00**

#### Job #1 - Internal

COMPLAINT: INSTALL BIG FAN IN THE BATHROOM

CAUSE: Customer wants a bigger fan in the bathroom.

CORRECTION: Inside the bathroom unscrewed the the trim cover from the ceiling. Disconnected the 12v power from the fan. Went on the roof and unscrewed the fan from the roof. Peeled up the fan. On the new fan put butyl tape on the bottom side then screwed the fan down to the roof. Trimmed the fan with dicor as necessary. In the bathroom cut the trim cover to fit and screwed it to the ceiling. Tested the fan operation.

#### Labor

Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	SAR	N/C
Z990	MISC LABOUR CODE (EXTERNAL)	SAR	N/C

#### Parts

Part #	Description	Qty	Price	Total
10926	MAXXFAN PLUS ROOF VENT W/ 12V FAN AN	1.00	N/C	N/C

Customer #: 20806  
GRAHAM, GREGORY



**Subtotal for Job #1: 0.00**

**Job #2 - Internal**

COMPLAINT: INSTALL LP QUICK CONNECT SOME WHERE ON THE DOOR SIDE

CAUSE: Lp hose and lp quick connection add on

CORRECTION: Unbolted the plug in the manifold block then went to the parts department to find a lp hose. Ben gave me a lp quick connection, got with parts for a fitting to connect the lp hose to the quick connection. Screwed in the lp hose to the manifold block and connected the lp hose to the quick connection. Mounted the quick connection on the doorside rear of the axle. Turned on the lp to check for leaks. No leaks occurred.

**Labor**

Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	SAR	N/C
Z990	MISC LABOUR CODE (EXTERNAL)	SAR	N/C

**Other Services**

Code	Description	Qty	Price	Total
PARTS	LP HOSE AND FITTINGS	1.00	N/C	N/C

**Subtotal for Job #2: 0.00**

**Job #3 - Internal**

COMPLAINT: INSTALL CUSTOMER SUPPLIED STRUTS ON BED

CAUSE: Bed risers installation

CORRECTION: Pulled off the mattress then measured for the risers. Mounted the risers bit the lid didn't close. Got with Ben for a solution.

**Labor**

Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)		N/C
Z990	MISC LABOUR CODE (EXTERNAL)	SAR	N/C

**Parts**

Part #	Description	Qty	Price	Total
20-1086	GSNI-5200-30 GAS SPRING	1.00	N/C	N/C
4B-3813LR	LIFT SUPPORT	1.00	N/C	N/C

**Subtotal for Job #3: 0.00**

**Job #4 - Internal**

SWAP BUMPER RECEIVER FROM RADE

**Labor**

Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	SAR	N/C
Z990	MISC LABOUR CODE (EXTERNAL)	SAR	N/C

**Subtotal for Job #4: 0.00**

**Job #SWAP - Internal**

SWAP CUSTOMER'S HITCHWORK

**Labor**

Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)		N/C
Z990	MISC LABOUR CODE (EXTERNAL)	SAR	N/C
Z990	MISC LABOUR CODE (EXTERNAL)		N/C
Z990	MISC LABOUR CODE (EXTERNAL)	BRM	N/C

W/O: 77141  
Promised Date: 27 JUN 25



Customer #: 20806  
GRAHAM, GREGORY



W/O: 77141  
Promised Date: 27 JUN 25

**Other Services**

Code	Description	Qty	Price	Total
SS	SHOP SUPPLIES	0.00	N/C	N/C
<b>Subtotal for Job #SWAP:</b>				<b>0.00</b>

**Job #5 - Warranty**

WATER HEATER DOOR RUSTED

**Labor**

Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	BRM	55.50

**Parts**

Part #	Description	Qty	Price	Total
07-7917	SUBURBAN WATER HEATER ACCESS DOOR ST	1.00	57.81	57.81
500627	CLEAR SIKASIL PLUS	1.00	9.17	9.17
<b>Subtotal for Job #5:</b>				<b>122.48</b>

Parts Total: 66.98  
Labour Total: 55.50  
Sublet Total: 0.00  
Extras Total: 0.00  
**WORK ORDER TOTAL: 122.48**

Thank you for being a valued customer. We appreciate your business.

All labor is guaranteed for 90 days from invoice date. Guarantee is limited to work performed. Consequential damages are not covered. All guaranteed work must be completed in our service department.

Date: 01 Jul 2025

Customer Signature : \_\_\_\_\_

Customer #: 20806  
GRAHAM, GREGORY

