

BASDEN RV CENTER, INC dba AMERICAN RV
600 E. Baseline Rd.
Evansville, IN
US
47725
812-867-5200

WARRANTY CLAIM # 77157
MANUFACTURER'S CLAIM #:

Manufacturer: 10024 - FOREST RIVER TRAVEL TRAILER
Customer: 1000 - BASDEN'S AMERICAN RV
Address: 600 E. BASELINE RD. EVANSVILLE, IN
USA
47725
Phone:
Stock Number: 11636 - 2026 CHEROKEE WOLF PUP 17SC 5ZT2CKFC5TY039054
VIN: 5ZT2CKFC5TY039054 HIN: SER#: 5ZT2CKFC5TY039054
Mileage: 0 Work Order Comp: 11 AUG 25
Auth. No: Dealer #:
Warr. Date: Work Order Date: 27 JUN 25 Inv #: 420972

WO # Job # Description JOB INFORMATION

77157 1 THE OUTSIDE FRIDGE HITS THE DOOR
outside fridge hits door
outside fridge door hits exterior door but it looks to be
designed that way. fridge door has scratch on it. parts order
request submited.

77157 3 LEAKE INSIDE BLACK TANK FLUSH
leak in black tank flush vaccum
during PDI found a leak in black tank flush vaccum. got new job
line created. attachede hose to oustide black tank flush and
found vaccum still leaking. turned off water recived new B&B
vaccum flush and attached it to flush lines. truned water back on
and found no leaks when new vaccum was attached.

77157 5 ENTRY DOOR HARD TO SHUT. HAS TO BE SLAMMED
entry door has to be forced shut
tried adjusting door within frame to fix did not work. tried
using wood blocks to adjust door slightly. also did not work.
door bows hard around middle of door and cannot hit the plate to
lock without begin slammed

77157 6 ROOF NEEDS SELF LEVELER SEALANT
roof needed sealing
grabed a step ladder climbed on roof took pictures of the voids
on roof the grab sealent and filled voids with sealent. took
pictures of voids now sealed.

Claim : 77157

```

*****
WO #      Job #   Description      JOB INFORMATION
*****
77157      7      ON THE ENTRY DOOR THERE IS A FEW SCRACHES ON THE TRIM ON THE SIDE

                scratches on exterior door trim
                cut seal holding in scratched trim piece the removed the screw in
                the top of door fram holding in trim. pulled scratched trim out
                the inserted new piece into trim frame. put the screw back inside
                to secure trim and clipped in new piece. added seal wear it had
                been removed.

77157      8      BATTERY DISCONNECT PLATE HAS CRACK IN IT
                crack in battery disconnect plate.
                crack on plate of battery disconnect. parts request put in.

77157      2      INSIDE FRIDGE ISAN'T WORKING
                inside fridge not working
                inside fridge would not turn on. checked fuse on break and it was
                not blown then checked fuse on fridge itself and it was also not
                blown.took all screws out of fridge to move it out of place and
                see behind fridge. after removing the quick clip connect for
                wires checked and saw that the wires giving power had voltage.
                switched the connect clips to a crimp for all wires and fridge
                light turned on as well as fridge itself and freezer.

```

```

*****
Part No      Job#   Description      PARTS      Qty      Price      Total
*****
F100264020    1   REFRIGERATOR, 1.7 CU. FT EVERCHIL  1.00    146.87    146.87
282770        3   94239 VACUUM BREAKER/CHECK VALVE  1.00     19.03     19.03
F100199304    5   DOOR, ENTRY 26" X 72" RH BLACK GL  1.00    584.60    584.60
F100616132    5   DECAL, 2025/2026 CHEROKEE DOOR LE  1.00      9.20      9.20
500627        5   CLEAR SIKASIL PLUS  1.00    10.36    10.36
20X40636A     5   SCREW COVER FOR 72" DOOR- BLACK 7  2.00      1.87      3.74
13-1320       6   PW HAPS FREE SELF-LEVELING DICOR  1.00      8.26      8.26
20X40636A     7   SCREW COVER FOR 72" DOOR- BLACK 7  1.00      1.66      1.66
219088        7   SILICONE II BLACK  1.00    11.99    11.99
F100125854    8   SWITCH, BATTERY DISCONNECT 300 AM  1.00    15.92    15.92

```

```

*****
Lab Code Job#   Description      LABOUR      Hrs      Rate      Total
*****
Z990      1   MISC LABOUR CODE (EXTERNAL)  0.47    185.00    86.95
Z990      1   MISC LABOUR CODE (EXTERNAL)  0.03    185.00      5.55
Z990      3   MISC LABOUR CODE (EXTERNAL)  0.30    185.00    55.50
Z990      5   MISC LABOUR CODE (EXTERNAL)  0.00    185.00      0.00
Z990      5   MISC LABOUR CODE (EXTERNAL)  0.50    185.00    92.50
Z990      5   MISC LABOUR CODE (EXTERNAL)  0.00    185.00      0.00

```

Claim : 77157

```

*****
Lab Code  Job#  Description          LABOUR          Hrs      Rate      Total
*****
Z990      5    MISC LABOUR CODE (EXTERNAL)      0.00    185.00      0.00
Z990      5    MISC LABOUR CODE (EXTERNAL)      0.00    185.00      0.00
Z990      5    MISC LABOUR CODE (EXTERNAL)      0.00    185.00      0.00
Z990      5    MISC LABOUR CODE (EXTERNAL)      0.60    185.00    111.00
Z990      5    MISC LABOUR CODE (EXTERNAL)      0.00    185.00      0.00
Z990      5    MISC LABOUR CODE (EXTERNAL)      0.00    185.00      0.00
Z990      6    MISC LABOUR CODE (EXTERNAL)      0.20    185.00     37.00
Z990      7    MISC LABOUR CODE (EXTERNAL)      0.20    185.00     37.00
Z990      8    MISC LABOUR CODE (EXTERNAL)      0.20    185.00     37.00
Z990      8    MISC LABOUR CODE (EXTERNAL)      0.00    185.00      0.00
Z990      2    MISC LABOUR CODE (EXTERNAL)      0.80    185.00    148.00

```

```

*****
Excode    Job#  Description          EXTRAS          Qty      Price      Total
*****
FRT       1    UPS REFER              1.00    150.00    150.00
FRT       5    UPS-DECAL              1.00     15.68     15.68
FRT       5    CEVA FREIGHT - DOOR    1.00    150.00    150.00
FRT       8    FREIGHT                1.00     15.68     15.68

```

```

Parts Total:      811.63
Labour Total:     610.50
Sublet Total:       0.00
Extras Total:     331.36

```

>>>> Claim Total: 1,753.49

Customer Signature: _____

Date: _____