



600 E. Baseline Rd.  
Evansville, IN 47725

www.AmericanRVCenter.com

812.867.5200  
FAX 812.868.1012

W/O: 77157  
Promised Date: 24 JUL 25

### CUSTOMER WORK ORDER

WO #: 77157

Customer: 1000 - BASDEN'S AMERICAN  
RV -  
Tag:  
Author: BH  
Location: 0811 BH TO CLOSE

Stock #: 11636  
Stock Desc: 2026 TT FOREST RIVER  
CHEROKEE WOLF PUP 17SC  
Chassis #: 5ZT2CKFC5TY039054  
Serial #: 5ZT2CKFC5TY039054  
Mileage: 0  
Licence:

Invoice #:  
Date In: 27 JUN 25  
Promised: 31 JUL 25  
Date Sched:  
Completed: 11 AUG 25  
Warr. Date:

#### Job #PDINTT - Internal

COMPLAINT: Transferred to BAS\*77446 on 01 AUG 25  
Estimate amount was 0.00  
PDI - NEW TRAVEL TRAILER

CAUSE: new pdi

CORRECTION: brought in camper for pdi. torqued all lug nuts to 110ftlbs. checked all exterior lights to be in working order. checked all three tires for correct psi of 65. checked all breaks and emergency breaks in working order. exterior seals all in good condition. roof had voids in seal and had job line created for it. exterior fridge door had scratch on it and had job line created for it. entry door did not shut properly had job line created for it. checked all appliances to be in working order besides interior fridge and had work order created for it. model and serial numbers documented for all appliances. checked plumbing all both sinks, shower, and toilet to be in working order. all pipes drain with no leaks. all connectings working. found leak in black tank flush vacuum and had work order created for it. found crack in battery disconnect and had work order put in for it. black and grey tanks drain well with no leaks. interior and exterior in good condition. all cabinets and drawers open and close properly.

#### Labor

Code	Description	Mechanic	Total
Z991	MISC LABOUR CODE (INTERNAL)	CCV	N/C
Z991	MISC LABOUR CODE (INTERNAL)	CCV	N/C
Z991	MISC LABOUR CODE (INTERNAL)	CCV	N/C
Z991	MISC LABOUR CODE (INTERNAL)	CCV	N/C

#### Other Services

Code	Description	Qty	Price	Total
SS	SHOP SUPPLIES	0.00	N/C	N/C
LPGI	LP - UNIT SALES	0.00	N/C	N/C

**Subtotal for Job #PDINTT: 0.00**

#### Job #1 - Warranty

COMPLAINT: THE OUTSIDE FRIDGE HITS THE DOOR

CAUSE: outside fridge hits door

CORRECTION: outside fridge door hits exterior door but it looks to be designed that way. fridge door has scratch on it. parts order request submitted.

#### Labor

Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	CCV	86.95
Z990	MISC LABOUR CODE (EXTERNAL)	CCV	5.55

#### Parts



Customer #: 1000  
BASDEN'S AMERICAN RV,



Part #	Description	Qty	Price	Total
F100264020	REFRIGERATOR, 1.7 CU. FT EVERCHILL,	1.00	146.87	146.87

**Other Services**

Code	Description	Qty	Price	Total
FRT	UPS REFER	1.00	150.00	150.00
<b>Subtotal for Job #1:</b>				<b>389.37</b>

**Job #2 - Warranty**

COMPLAINT: INSIDE FRIDGE ISAN'T WORKING

CAUSE: inside fridge not working

CORRECTION: inside fridge would not turn on. checked fuse on break and it was not blown then checked fuse on fridge itself and it was also not blown. took all screws out of fridge to move it out of place and see behind fridge. after removing the quick clip connect for wires checked and saw that the wires giving power had voltage. switched the connect clips to a crimp for all wires and fridge light turned on as well as fridge itself and freezer.

**Labor**

Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	CCV	148.00
<b>Subtotal for Job #2:</b>			<b>148.00</b>

**Job #3 - Warranty**

COMPLAINT: LEAKE INSIDE BLACK TANK FLUSH

CAUSE: leak in black tank flush vaccum

CORRECTION: during PDI found a leak in black tank flush vaccum. got new job line created. attachede hose to oustide black tank flush and found vaccum still leaking. turned off water recived new B&B vaccum flush and attached it to flush lines. truned water back on and found no leaks when new vaccum was attached.

**Labor**

Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	CCV	55.50

**Parts**

Part #	Description	Qty	Price	Total
282770	94239 VACUUM BREAKER/CHECK VALVE	1.00	19.03	19.03
<b>Subtotal for Job #3:</b>				<b>74.53</b>

**Job #4 - Internal**

COMPLAINT: Transferred to BAS\*77446 on 01 AUG 25  
 Estimate amount was 0.00  
 SCRATCHES AROUND ENTRY DOOR

CAUSE: FOUND THE PLASTIC AROUND THE ENTRY DOOR IS SCRATCHED

CORRECTION: need to replace it

**Labor**

Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	CCV	N/C
Z990	MISC LABOUR CODE (EXTERNAL)	CCV	N/C
<b>Subtotal for Job #4:</b>			<b>0.00</b>


**Job #5 - Warranty**

COMPLAINT: ENTRY DOOR HARD TO SHUT. HAS TO BE SLAMMED

W/O: 77157  
 Promised Date: 31 JUL 25



Customer #: 1000  
 BASDENS AMERICAN RV,





CAUSE: entry door has to be forced shut

CORRECTION: tried adjusting door within frame to fix did not work. tried using wood blocks to adjust door slightly. also did not work. door bows hard around middle of door and cannot hit the plate to lock without begin slammed

<b>Labor</b>			
Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	CCV	0.00
Z990	MISC LABOUR CODE (EXTERNAL)	CCV	92.50
Z990	MISC LABOUR CODE (EXTERNAL)	CCV	0.00
Z990	MISC LABOUR CODE (EXTERNAL)	CCV	0.00
Z990	MISC LABOUR CODE (EXTERNAL)	CCV	0.00
Z990	MISC LABOUR CODE (EXTERNAL)	CCV	0.00
Z990	MISC LABOUR CODE (EXTERNAL)	CCV	111.00
Z990	MISC LABOUR CODE (EXTERNAL)	CCV	0.00
Z990	MISC LABOUR CODE (EXTERNAL)	CCV	0.00

<b>Parts</b>				
Part #	Description	Qty	Price	Total
F100199304	DOOR, ENTRY 26" X 72" RH BLACK GLASS	1.00	584.60	584.60
F100616132	DECAL, 2025/2026 CHEROKEE DOOR LEGEN	1.00	9.20	9.20
500627	CLEAR SIKASIL PLUS	1.00	10.36	10.36
20X40636A	SCREW COVER FOR 72" DOOR-BLACK 76"	2.00	1.87	3.74

<b>Other Services</b>				
Code	Description	Qty	Price	Total
FRT	UPS-DECAL	1.00	15.68	15.68
FRT	CEVA FREIGHT - DOOR	1.00	150.00	150.00
<b>Subtotal for Job #5:</b>				<b>977.08</b>

**Job #6 - Warranty**

COMPLAINT: ROOF NEEDS SELF LEVELER SEALANT

CAUSE: roof needed sealing

CORRECTION: grabed a step ladder climbed on roof took pictures of the voids on roof the grab sealent and filled voids with sealent. took pictures of voids now sealed.

<b>Labor</b>			
Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	CCV	37.00

<b>Parts</b>				
Part #	Description	Qty	Price	Total
13-1320	PW HAPS FREE SELF-LEVELING DICOR	1.00	8.26	8.26
<b>Subtotal for Job #6:</b>				<b>45.26</b>

**Job #7 - Warranty**

COMPLAINT: ON THE ENTRY DOOR THERE IS A FEW SCRACHES ON THE TRIM ON THE SIDE

CAUSE: scratches on exterior door trim

CORRECTION: cut seal holding in scratched trim piece the removed the screw in the top of door fram holding in trim. pulled scratched trim out the inserted new piece into trim frame. put the screw back inside to secure trim and clipped in new piece. added seal wear it had been removed.

<b>Labor</b>			
Code	Description	Mechanic	Total



Z990 MISC LABOUR CODE (EXTERNAL) CCV 37.00

**Parts**

Part #	Description	Qty	Price	Total
20X40636A	SCREW COVER FOR 72" DOOR- BLACK 76"	1.00	1.66	1.66
219088	SILICONE II BLACK	1.00	11.99	11.99
<b>Subtotal for Job #7:</b>				<b>50.65</b>

**Job #8 - Warranty**

COMPLAINT: BATTERY DISCONNECT PLATE HAS CRACK IN IT

CAUSE: crack in battery disconnect plate.

CORRECTION: crack on plate of battery disconnect. parts request put in.

**Labor**

Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	CCV	37.00
Z990	MISC LABOUR CODE (EXTERNAL)	CCV	0.00

**Parts**

Part #	Description	Qty	Price	Total
F100125854	SWITCH, BATTERY DISCONNECT 300 AMP S	1.00	15.92	15.92

**Other Services**

Code	Description	Qty	Price	Total
FRT	FREIGHT	1.00	15.68	15.68

**Subtotal for Job #8: 68.60**

Parts Total: 811.63  
Labour Total: 610.50  
Sublet Total: 0.00  
Extras Total: 331.36  
**WORK ORDER TOTAL: 1,753.49**

Thank you for being a valued customer. We appreciate your business.

All labor is guaranteed for 90 days from invoice date. Guarantee is limited to work performed. Consequential damages are not covered. All guaranteed work must be completed in our service department.

Customer Signature : \_\_\_\_\_

Date: 11 Aug 2025

W/O: 77157  
Promised Date: 31 JUL 25



Customer #: 1000  
BASDENS AMERICAN RV,

