

BASDEN RV CENTER, INC dba AMERICAN RV
600 E. Baseline Rd.
Evansville, IN
US
47725
812-867-5200

WARRANTY CLAIM # 77158
MANUFACTURER'S CLAIM #:

Manufacturer: 1013 - KEYSTONE RV CO
Customer: 1000 - BASDEN'S AMERICAN RV
Address: 600 E. BASELINE RD. EVANSVILLE, IN
USA
47725
Phone:
Stock Number: 11635 - 2026 COUGAR HALF-TON 22MLS 4YDTCGK21TV500085
VIN: 4YDTCGK21TV500085 HIN: SER#: 4YDTCGK21TV500085
Mileage: 0 Work Order Comp: 22 JUL 25
Auth. No: Dealer #: 1194
Warr. Date: Work Order Date: 27 JUN 25 Inv #: 420172

WO # Job # Description JOB INFORMATION

77158 2 EXIT WINDOW SCREEN IS OUT
Exit screen
The exit screen for the window was laying on the ground when I
walked into the camper and noticed the screen wasn't installed
correctly so I had to fix that then put it back into the window
frame

77158 11 SCRATCHES AND GOUGES ON SLIDE ROOM FACIAI

77158 1 ADJUST STEEPS
Steps
Adjusted steps so the steps would be level and also adjusted the
end so it would be level

77158 3 SILICONE NEEDED IN KITCHEN AROUND COUNTER
Added silicone
Added silicone around kitchen edges for a seal fix

77158 4 CABINITS AROUND TV NOT EVEN
Cabinets near tv
Cabinet near tv were not even so I adjusted them and then screwed
in screws correctly

77158 5 TOWEL BAR IN BATHROOM IS NOT MOUNTED
Towel bar
Towel bar in bathroom was loose so I took it off the wall and

Claim : 77158

```

*****
WO #      Job #   Description      JOB INFORMATION
*****
also had to find some solution to put on it so it wouldn't come
off the wall so I found some spray adhesive and also used some 3m
tape that had adhesive also on it and used that to put on the
wall then re mounted it on the wall with some stronger screws and
also made sure it wouldn't come off the wall that's why the
longer time to insure it wasn't coming off the wall

77158      6      BEDROOM TRIM NEEDS WOOD PUTTY
Trim
Bedroom got putty and marks are fixed that were needing putty on
them

77158      7      DOOR SIDE TRIM NEAR TIRE IS LOOSE
Trim loose
Trim was loose near tire got with manager and determined that was
supposed to be like so no job was needed

77158      8      OFF DOOR SIDE NEAR BEDROOM WINDOW NEEDS SILICONE
Silicone
Added silicone around the bottom side of the window to insure
that it wouldn't leak from the rain or any water to get in and
cause damage

77158      9      REAR WINDOW NEEDS SILICONE
Added silicone
Added silicone to back glass where silicone wasn't installed from
the factory

77158      10     ENTRY DOOR CORNER IS BENT AT THE BOTTOM
Door bent
Took a pair of vise grips and slowly gripping the bend and bent
it back straight then took a white marker to clean up scratch
marks

77158      12     LED LIGHT IS HANGING DOWN ABOVE SINK
Led lights
Lights were coming down and off track so I fixed it by using some
3m adhesive and made sure the lights were in track before adding
the 3mtape adhesive to the back of lights and then made sure they
were in the correct spot

77158      13     CABINET DOOR BY MICROWAVE NOT EVEN
Cabnitdoor
Adjusted cabinets by moving the screws and reposition them and
the door will be even now and not be sitting sideways

```

Claim : 77158

 WO # Job # Description JOB INFORMATION

 Part No Job# Description PARTS Qty Price Total

 SIK432053 2 CLEAR SIKASIL PLUS 1.00 9.17 9.17
 765966 11 Trim - Fascia - Insert - 3mm x 4 1.00 5.80 5.80

 Lab Code Job# Description LABOUR Hrs Rate Total

 Z990 2 MISCELLANEOUS REPAIR 0.00 180.00 0.00
 Z990 2 MISCELLANEOUS REPAIR 0.10 180.00 18.00
 Z990 11 MISCELLANEOUS REPAIR 0.60 180.00 108.00
 Z990 11 MISCELLANEOUS REPAIR 0.40 180.00 72.00
 Z990 11 MISCELLANEOUS REPAIR 0.00 180.00 0.00
 Z990 1 MISCELLANEOUS REPAIR 0.00 180.00 0.00
 Z990 1 MISCELLANEOUS REPAIR 0.10 180.00 18.00
 Z990 1 MISCELLANEOUS REPAIR 0.00 180.00 0.00
 Z990 3 MISCELLANEOUS REPAIR 0.30 180.00 54.00
 Z990 3 MISCELLANEOUS REPAIR 0.00 180.00 0.00
 Z990 4 MISCELLANEOUS REPAIR 0.20 180.00 36.00
 Z990 5 MISCELLANEOUS REPAIR 0.20 180.00 36.00
 Z990 6 MISCELLANEOUS REPAIR 0.10 180.00 18.00
 Z990 7 MISCELLANEOUS REPAIR 0.10 180.00 18.00
 Z990 8 MISCELLANEOUS REPAIR 0.10 180.00 18.00
 Z990 9 MISCELLANEOUS REPAIR 0.20 180.00 36.00
 Z990 10 MISCELLANEOUS REPAIR 0.20 180.00 36.00
 Z990 12 MISCELLANEOUS REPAIR 0.10 180.00 18.00
 Z990 13 MISCELLANEOUS REPAIR 0.10 180.00 18.00
 Z990 13 MISCELLANEOUS REPAIR 0.10 180.00 18.00

 Excode Job# Description EXTRAS Qty Price Total

 FRT 11 UPS-FASCIA 1.00 77.30 77.30

Parts Total: 14.97
 Labour Total: 522.00
 Sublet Total: 0.00
 Extras Total: 77.30

>>>> Claim Total: 614.27

Customer Signature: _____

Date: _____