



600 E. Baseline Rd.
Evansville, IN 47725

www.AmericanRVCenter.com

812.867.5200
FAX 812.868.1012

W/O: 77166
Promised Date:
07 JUL 25



Customer #: 55965
HAWKINS, DANA



CUSTOMER WORK ORDER

WO #: 77166

Customer: 55965 - HAWKINS, DANA -
618-599-8220

Tag:

Author: BH

Location: DELIVERY 0707

Stock #: 11451

Stock Desc: 2025 TT KEYSTONE

SPRINGDALE 260BHC

Chassis #: 4YDTSG22S7100685

Serial #: 4YDTSG22S7100685

Mileage:

Licence:

Invoice #:

Date In: 28 JUN 25

Promised: 07 JUL 25

Date Sched:

Completed: 23 JUL 25

Warr. Date: 07 JUL 25

Job #FPDINTT - Internal

FINAL PDI ON NEW TRAVEL TRAILERS

Labor

Code	Description	Mechanic	Total
PDINTT	PDI - NEW TRAVEL TRAILER	JTW	N/C
PDINTT	PDI - NEW TRAVEL TRAILER	JTW	N/C

Parts

Part #	Description	Qty	Price	Total
DC-24	ADVANCE GROUP 24 DEEP CYCLE BATTERY	1.00	N/C	N/C
55364	55364 REPLACEMENT BATTERY BOX STRAP	1.00	N/C	N/C

Subtotal for Job #FPDINTT: 0.00

Job #ICSH - Internal

INSTALL CUSTOMER SUPPLIED HITCHWORK

Labor

Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	SAR	N/C
Z990	MISC LABOUR CODE (EXTERNAL)	SAR	N/C

Parts

Part #	Description	Qty	Price	Total
H410	H410 2-pk WD HITCH REPLACEMENT PIN 3/16"	1.00	N/C	N/C
J-30P	3/8" THREADED LINK	2.00	N/C	N/C

Other Services

Code	Description	Qty	Price	Total
SS	SHOP SUPPLIES	0.00	N/C	N/C

Subtotal for Job #ICSH: 0.00

Job #DELUXE - Internal

DELUXE STARTER KIT





Parts				
Part #	Description	Qty	Price	Total
44722	DELUXE STARTER KIT	1.00	N/C	N/C
Subtotal for Job #DELUXE:				0.00

Job #1 - Warranty

COMPLAINT: UNIT NEEDS TO BE RESEALED SEE PICS

CAUSE: Spots needed to be sealed

CORRECTION: Roof inspection found some voids in the sealer on the roof. I filled them with Dicor self-leveling. The grab handle needed sealed back light and fresh water inlet needed sealed. I sealed them with silicone all sealed up now

Labor				
Code	Description		Mechanic	Total
Z990	MISCELLANEOUS REPAIR		JTW	54.00
Parts				
Part #	Description	Qty	Price	Total
13-1320	PW HAPS FREE SELF-LEVELING DICOR	1.00	8.26	8.26
500627	CLEAR SIKASIL PLUS	1.00	9.17	9.17
Subtotal for Job #1:				71.43

Job #2 - Warranty

COMPLAINT: THE MEATL J WRAP IS COMING OFF OF THE REAR OF FDOOR SIDE

CAUSE: Lower trim coming out of vertical trim

CORRECTION: Staple was coming out. So I set it back in and got the lower panel back behind the vertical trim piece. And ran a bead of silicone on the joint.

Labor				
Code	Description	Mechanic	Total	
Z990	MISCELLANEOUS REPAIR	JTW	36.00	
Subtotal for Job #2:				36.00

Job #3 - Warranty

COMPLAINT: THE VENT IN THE A/C BROKEN AND FELL OFF

CAUSE: VFENT BROKEN

CORRECTION: VENT REPLACED

Labor				
Code	Description		Mechanic	Total
Z990	MISCELLANEOUS REPAIR		JTW	36.00
Parts				
Part #	Description	Qty	Price	Total
3315333001	KIT,SVC VENTS	1.00	27.76	27.76
Subtotal for Job #3:				63.76

Job #4 - Internal

COMPLAINT: STOVE WONT LIGHT

CAUSE: Human error

CORRECTION: Have to hold in the button when ignition

Labor				
--------------	--	--	--	--



Code Description
Z990 MISCELLANEOUS REPAIR

Mechanic
SAR

Total
N/C

Subtotal for Job #4: 0.00

Parts Total: 45.19
Labour Total: 126.00
Sublet Total: 0.00
Extras Total: 0.00
WORK ORDER TOTAL: 171.19

Thank you for being a valued customer. We appreciate your business.

All labor is guaranteed for 90 days from invoice date. Guarantee is limited to work performed. Consequential damages are not covered. All guaranteed work must be completed in our service department.

Customer Signature : _____

Date: 23 Jul 2025

W/O: 77166
Promised Date: 07 JUL 25



Customer #: 55965
HAWKINS, DANA

