

**Pre-Authorization**

Pre-Authorization number PA03884674 Reference no: 77190 Status: Approved Approved by parke Approved date 7/17/2025  
 Servicing Name Address VIN Retail sold on Dealer

1194 Basden's American RV Basden's American RV 4YDTCGN25SV506157 7/3/2025  
 600 E Baseline Rd  
 Evansville, IN 47725

Nu mbe r of	Root operation	Description	Sublet	Sub hours	Approved hours	Actual hours	Qty	Base hours	Complaint / Cause / Correction
1	6101315A	Fresh Water Pres	0.00	2.00	2.00		1	0.10	Complaint:UNDER BELLY IS FULL OF WATER Cause:Water line to the black tank flush had a kink that it was leaking at the kink and leaking into to the underbelly. Correction:When pulling the camper from the sales lot had noticed front underbelly was leaking water. Set the camper outside of the service bay. Lower the front of the camper and unscrewed some of the self tappers to drain out the water. Connected the garden hose to the winterizing port and checked for leaks. Disconnected the hose and connected to the city water connection and checked for leaks. Disconnected the hose and connected to the black tank flush connection. Turned on the water but didn't hear it flowing. Went inside the camper and checked the black tank flush and it was quiet. Got a job to fix the backwards vacuum breaker. After checking those connections never found a leak yet. After looking into the underbelly found the water line to the black tank flush was leaking at the kink. Cut the underbelly to get closer to the kinked water line. Cut out the kink in the water line and got a elbow fitting from the parts department to fix the problem. Crimped in the elbow fitting then turned on the water to the black tank flush to check for any more leaks. No leaks occurred. Put a backer in the underbelly to screw the underbelly together then covered with black roof tape.
2	6109514A	Holding Tank Flus	0.00	1.00	0.30		1	0.30	Complaint:VACUM BREAKER IS BACKWARDS Cause:Vacuum breaker Correction:When the hose, is connected to the black tank,could not hear the water flow, and the black tank was dry. Went to the vacuum breaker and couldn't hear any water flowing. Disconnected the vacuum breaker. Switched the fittings, that didn't help fix the issue. The vacuum breaker was bad because of being backwards, got a new vacuum breaker from the parts department. Put in a new vacuum breaker and tested the black tank flush again. Disconnected the vacuum breaker and blew air

For paper claims only use one pre-authorization number per warranty claim for

Staple a copy of this pre-authorization to a warranty claim form. Fill out the header information and the parts section on the claim form. The labor section does not need to be filled out on the claim form. Fill in the amount of hours used for the repair - up to the amount authorized on the pre-authorization form and return toKeystone RV Company

**Pre-Authorization**

Nu mber of	Root operation	Description	Sublet	Sub hours	Approved hours	Actual hours	Qty	Base hours	Complaint / Cause / Correction
3	3201808B	Decorative Wood	0.00	0.20	0.20		1	0.20	threw the lines and the water line coming from the black tank KRV – Labor time approved and adjusted in accordance with Keystone RV's flat rate manual.  Complaint:AREA NEAR THE BACK SPLASH IS TORN AND NEEDS TO BE FIXED Cause:FOUND AREA DAMAGED Correction:INSTALL SEAM TAPE OVER AREA
					2.50				

Pre-Authorization number PA03884674

For paper claims only use one pre-authorization number per warranty claim for

Staple a copy of this pre-authorization to a warranty claim form. Fill out the header information and the parts section on the claim form. The labor section does not need to be filled out on the claim form. Fill in the amount of hours used for the repair - up to the amount authorized on the pre-authorization form and return to Keystone RV Company