

FOREST RIVER WARRANTY CLAIM FORM

DEALER ACCOUNT #	0005106	CLAIM STATUS	Authorized
BASDEN RV CENTER INC		CLAIM	2353713
DBA AMERICAN RV CENTER		CLAIM ORIGIN	WEB
600 E BASELINE ROAD		ORIGINAL CLAIM ID	
EVANSVILLE, IN 47725		VIN	4X4TCKB28TX167016
USA		CHASSIS VIN	
		MILEAGE	0
Labor rate:	\$185.00	SITE/WAREHOUSE	017 / 017A
OWNER INFORMATION		ITEM #	ACKT26KF
HEATHER R SCHOENBAECHLER		DEALER RO #	77200
912 BLACKFOOT DR		CLAIM START DATE	07/02/2025
Fort Branch, IN 47648		CLAIM END DATE	01/01/1900
USA			
Retail Date of Purchase	06/28/2025	WARRANTY EXPIRATION DATE	06/28/2026

Claim Line Details

Labor

Line# 1	Operation Code	Operational Description		
	20-43-19-00-001109	Gutter Rail - Exterior/Exterior Miscellaneous/Reseal/No Tread Code		
	Complaint, Cause, Correction			
	Original Note : bhoffman@americanrvcenter.com, 2025-07-02 10:24:31 :: GUTTER FELL OFF AND NEEDS REINSTALLED Gutter spout falling off Removed screw and old sealer. Put gutter back on like it was supposed to be. Shot screws back in and then sealed everything back up.			
Model#	Dlr Sub Hrs	0.20	Sub Labor Amt	\$37.00
Serial#	Appr Hrs	0.20	Appr Labor Amt	\$37.00
Notes				

Labor

Line# 2	Operation Code	Operational Description		
	30-92-01-00-001146	MTI LP & CO Detector Combo - Interior/Interior Miscellaneous/Replace/No Tread Code		
	Complaint, Cause, Correction			
	Original Note : bhoffman@americanrvcenter.com, 2025-07-02 10:39:27 :: LP AND CO KEEPS GOING OFF Lp and co detector kept going off After inspection of lp and co detector. Found that it was bad. I replaced it with a new one and it works properly now.			
Model# NA	Dlr Sub Hrs	0.20	Sub Labor Amt	\$37.00
Serial# NA	Appr Hrs	0.20	Appr Labor Amt	\$37.00
Notes				

Submitted	Labor Amt	\$74.00	Approved	Labor Amt	\$74.00
	Parts & Freight	\$0.00		Parts & Freight	\$0.00
	Total	\$74.00		Total	\$74.00

DEALER _____ DATE _____
SIGNATURE _____
I certify that I have performed these repairs consistent with Forest River Policies.

CUSTOMER _____ DATE _____
SIGNATURE _____
All repairs described have been inspected and are satisfactory.