



600 E. Baseline Rd.
Evansville, IN 47725

www.AmericanRVCenter.com

812.867.5200
FAX 812.868.1012

W/O: 77239
Promised Date:
24 1111 25

CUSTOMER WORK ORDER

WO #: 77239

Customer: 55985 - HELMS, ABIGAIL -
812-589-5361

Tag:

Author: GA

Location: 1117 CHECK PREAUTH

Stock #: 11552

Stock Desc: 2025 TT COACHMEN
CATALINA SUMMIT SERIES 184BHS

Chassis #: 5ZT2CAGC9SU045440

Serial #: 5ZT2CAGC9SU045440

Mileage: 0

Licence:

Invoice #:

Date In: 07 JUL 25

Promised: 31 JUL 25

Date Sched:

Completed: 14 NOV 25

Warr. Date: 17 JUL 25

Job #FPDINTT - Internal

Transferred to BAS*77426 on 30 JUL 25

Estimate amount was 0.00

FINAL PDI ON NEW TRAVEL TRAILERS

Labor

Code	Description	Mechanic	Total
PDINTT	PDI - NEW TRAVEL TRAILER	JTW	N/C
PDINTT	PDI - NEW TRAVEL TRAILER	JTW	N/C
PDINTT	PDI - NEW TRAVEL TRAILER	JTW	N/C

Subtotal for Job #FPDINTT: 0.00

Job #1 - Internal

Transferred to BAS*77426 on 30 JUL 25

Estimate amount was 0.00

CUSTOMER WILL INSTALL OWN HITCH WORK AND NO TRUCK LISTED 7-7

Subtotal for Job #1: 0.00

Job #2 - Warranty

COMPLAINT: FRONT MARKER LIGHT DOOR SIDE FULL OF WATER AND NOT WORKING

CAUSE: Door side front clearance lights don't work

CORRECTION: After inspection of the light it was full of water. Put a new light on and it works properly now

Labor

Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	JTW	37.00

Parts

Part #	Description	Qty	Price	Total
11073	LIGHT, CLEARANCE AMBER SURFACE MOUNT	1.00	1.99	1.99

Subtotal for Job #2: 38.99

Job #3 - Warranty

COMPLAINT: LATCH FOR THE BED IS BROKEN AND NEEDS REPLAED

CAUSE: Front bedroom latch missing slide bar

CORRECTION: Took off broken latch and installed the new latch that has the slide bar in it. And it works properly now



Customer #: 55985
HELMS, ABIGAIL



Labor			
Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	JTW	55.50

Parts				
Part #	Description	Qty	Price	Total
11537	LATCH, BARREL FLAT STRIKE PLATE PLAI	1.00	0.30	0.30

Subtotal for Job #3: 55.80

Job #4 - Internal

Transferred to BAS*77426 on 30 JUL 25
 Estimate amount was 0.00
 INSTALL CUSTOMER SUPLIED ELECTRIC TOUNG JACK

Labor			
Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	ZMS	N/C

Subtotal for Job #4: 0.00

Job #5 - Warranty

COMPLAINT: Seal on the outside kitchen
 CAUSE: bad seal outside kitchen
 CORRECTION: replaced seal on outside kitchen door

Labor			
Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	CCV	55.50

Other Services				
Code	Description	Qty	Price	Total
SS	SHOP SUPPLIES	1.00	0.00	0.00

Subtotal for Job #5: 55.50


Job #6 - Warranty

COMPLAINT: Decals on the entire unit are bubbling and peeling
 CAUSE: FOUND ALMOST ALL DEALS ARE NEEDING TO BE REPLACED DUE TO INSTALL ISSUES
 CORRECTION: REPALCE ALL DECALS THAT HAVE BLUE TAPE MARKEDE

Labor			
Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	JTW	0.00
Z990	MISC LABOUR CODE (EXTERNAL)	JTW	814.00
Z990	MISC LABOUR CODE (EXTERNAL)	JTW	0.00

Parts				
Part #	Description	Qty	Price	Total
F100418579	GRAPHIC, #14 ODS "CATALINA" LOGO 202	1.00	11.54	11.54
F100418468	GRAPHIC	1.00	5.81	5.81
F100597137	GRAPHIC, #44 "SUMMIT SERIES" SIDE MI	1.00	11.95	11.95
F100644727	DECAL, 27.5" "A FOREST RIVER BRAND"	1.00	4.88	4.88
F100597135	GRAPHIC, #27 REAR DIG "SUMMIT SERIES	1.00	7.68	7.68
F100418584	GRAPHIC, #24 REAR "CATALINA" CATALIN	1.00	10.86	10.86





Code	Description	Qty	Price	Total
F100588123	DECAL, REAR COACHMEN W/ DOG #90	1.00	41.42	41.42
F100418569	GRAPHIC	1.00	1.31	1.31
F100418566	GRAPHIC	1.00	4.38	4.38
F100597116	GRAPHIC, #11A SIDE FRONT LOWER WHITE	1.00	5.34	5.34
F100418578	GRAPHIC, #13 DS "CATALINA" LOGO 202	1.00	11.54	11.54
F100597136	GRAPHIC, #43 "SUMMIT SERIES" SIDE MI	1.00	11.95	11.95
F100418467	GRAPHIC	1.00	5.81	5.81

Other Services

Code	Description	Qty	Price	Total
FRT	UPS-DECALS	1.00	15.68	15.68

Subtotal for Job #6: 964.15

Job #7 - Warranty

COMPLAINT: CUSTOMER STATES HE GETS NO RECEPTION FROM THE TV ANTENNA

CAUSE: Antenna not getting channels

CORRECTION: Inspection of the customer supplied tv and antenna. First they had the cable from tv in the wrong port on the wall. It needs to be connected to the tv port. When i did that still no reception. So i put the tester on the cable and it was showin open. So i took antenna off roof and hooked to the cable at antenna and at the wall and it still showed open. So i looked and the cable connector and it looked like it was pull out of the cable. So i put two new ends on the cable and tested it and it showed good then. So i put everything back together and did a channels serch and i found tv channels. So tv antenna works properly now

Labor

Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	JTW	38.85
Z990	MISC LABOUR CODE (EXTERNAL)	JTW	1.85
Z990	MISC LABOUR CODE (EXTERNAL)	JTW	181.30

Subtotal for Job #7: 222.00

Job #8 - External

CUSTOMER WOULD LIKE ESTIMATE TO FIX DAMAGE ON INSIDE OF CAMPER. AREAS ARE MARKED WITH BLUE TAPE.

Labor

Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)		N/C
Z990	MISC LABOUR CODE (EXTERNAL)	JTW	N/C

Subtotal for Job #8: 0.00

Parts Total: 136.76
 Labour Total: 1,184.00
 Sublet Total: 0.00
 Extras Total: 15.68
WORK ORDER TOTAL: 1,336.44

Thank you for being a valued customer. We appreciate your business.


All labor is guaranteed for 90 days from invoice date. Guarantee is limited to work performed. Consequential damages are not covered. All guaranteed work must be completed in our service department.



Customer Signature : _____

Date: 17 Nov 2025

W/O: 77239
Promised Date: 31 JUL 25



Customer #: 55985
HELMs, ABIGAIL



Customer Work
Order

