

BASDEN RV CENTER, INC dba AMERICAN RV  
600 E. Baseline Rd.  
Evansville, IN  
US  
47725  
812-867-5200

WARRANTY CLAIM # 77245  
MANUFACTURER'S CLAIM #:

Manufacturer: 10024 - FOREST RIVER TRAVEL TRAILER  
Customer: 55254 - LARRY ENNIS  
Address: 2500 MCOW RD  
EVANSVILLE, IN  
47712  
Phone: 812-550-8241  
Stock Number: 2025 CATALINA 293TQBS  
VIN: HIN: SER#: 5ZT2CAUB1SX032479  
Mileage: Work Order Comp: 12 JUL 25  
Auth. No: Dealer #:  
Warr. Date: Work Order Date: 07 JUL 25 Inv #: 419856

\*\*\*\*\*  
WO # Job # Description JOB INFORMATION  
\*\*\*\*\*  
77245 8 USB JACK BY ENTRANCE DOOR DOES NOT WORK  
USB port not working  
After inspection of the USB port. I found that the USB port is  
working properly it is the C type port that's not working.  
Replaced part and it works properly now  
  
77245 1 VENT FAN IN CEILING OF KITCHEN NOT WORKING  
Exhaust fan doesn't work  
After inspection of the exhaust fan. Found that the fan motor is  
bad. Replaced the motor and fan works properly now  
  
77245 5 CHECK SINK CAUCKING, STATES IT APPEARS IT IS SINKING  
Sink may be dropping  
After inspection I found sink is secure. And checked no open  
recalls on the sink. Cleaned and re chalked. Sink looks good  
  
77245 3 CHECK HINGES ON DOORS OF DINETTE BROKEN DOOR CLOSEST TO THE  
BUNKHOUSE  
Dinette cabinet door hinges loose  
Inspect the dinette cabinet door and found top hi g screws were  
missing. So t painted new longer screws and it works properly  
now. After fixing this one I noticed the other cabinet under  
dinette was not staying closed. So I adjusted the latch and it  
works properly now  
  
77245 4 THE BLIND WILL NOT OPEN AND IT IS ON THE SAME WINDOW WITH THE

Claim : 77245

```

*****
WO #      Job #   Description      JOB INFORMATION
*****
          SEAL
          Blind won't stay up
          After inspection of the blind. It was just out of adjustment. So
          I tightened up both strings. And it works properly now

77245      6      GASKET ON SLIDE WILL NOT FLIP IN WHEN SLIDE COMES IN, SAME SIDE
          AS WINDOW GASKET ISSUE
          Gasket on slide room
          Customer stated gasket on slide room won't go in when room goes
          in. The gasket on the bottom is supposed to be like that to keep
          the water from the tires out

77245      7      BLACK TANK FLUSH CHECK VALVE IS LEAKING UNDER THE BATHROOM SINK
          Black tank flush valve
          After inspection of it is found that the line was loose. I
          pointed to the line that was loose in my picture. After I
          tightened it up and it ran water through it I couldn't is
          replicate the leak. It works properly now.

```

```

*****
Part No      Job#   Description      PARTS      Qty      Price      Total
*****
F100324093    8      USB, 12V USB/C-PORT COMBO CHARGER  1.00      5.31      5.31
VENBVD0218-00 1      BVD0218-00 VENTLINE FAN MOTOR      1.00     29.83     29.83
500629        5      SIKASIL N PLUS WHITE                1.00      8.89      8.89

```

```

*****
Lab Code Job#   Description      LABOUR      Hrs      Rate      Total
*****
Z990      8      MISC LABOUR CODE (EXTERNAL)          0.15     185.00     27.75
Z990      8      MISC LABOUR CODE (EXTERNAL)          0.15     185.00     27.75
Z990      1      MISC LABOUR CODE (EXTERNAL)          0.00     185.00      0.00
Z990      1      MISC LABOUR CODE (EXTERNAL)          0.30     185.00     55.50
Z990      5      MISC LABOUR CODE (EXTERNAL)          0.20     185.00     37.00
Z990      3      MISC LABOUR CODE (EXTERNAL)          0.10     185.00     18.50
Z990      4      MISC LABOUR CODE (EXTERNAL)          0.00     185.00      0.00
Z990      4      MISC LABOUR CODE (EXTERNAL)          0.05     185.00      9.25
Z990      6      MISC LABOUR CODE (EXTERNAL)          0.30     185.00     55.50
Z990      7      MISC LABOUR CODE (EXTERNAL)          0.30     185.00     55.50

```

```

*****
Excode      Job#   Description      EXTRAS      Qty      Price      Total
*****
SS          1      SHOP SUPPLIES                1.00     12.68     12.68

```

```

Parts Total:      44.03
Labour Total:     286.75
Sublet Total:      0.00
Extras Total:     12.68

```

```
>>>>> Claim Total:      343.46
```

Customer Signature: \_\_\_\_\_

Date: \_\_\_\_\_