



600 E. Baseline Rd.
Evansville, IN 47725

www.AmericanRVCenter.com

812.867.5200
FAX 812.868.1012

W/O: 77245
Promised Date:
24 JUL 25

CUSTOMER WORK ORDER

WO #: 77245 (Appointment Date: 07 JUL 2025 - Time: 04:30pm)

Customer: 55254 - ENNIS, LARRY -
812-550-8241

Tag:

Author: GA

Location: 0711 BH TO CLOSE

Stock #:

Stock Desc: 2025 TT FOREST RIVER

CATALINA 293TQBS

Chassis #:

Serial #: 5ZT2CAUB1SX032479

Mileage:

Licence:

Invoice #: 419855

Date In: 07 JUL 25

Promised: 31 JUL 25

Date Sched:

Completed: 12 JUL 25

Warr. Date:

Job #1 - Warranty

COMPLAINT: VENT FAN IN CEILING OF KITCHEN NOT WORKING

CAUSE: Exhaust fan doesn't work

CORRECTION: After inspection of the exhaust fan. Found that the fan motor is bad. Replaced the motor and fan works properly now

Labor

Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	JTW	0.00
Z990	MISC LABOUR CODE (EXTERNAL)	JTW	55.50

Parts

Part #	Description	Qty	Price	Total
47-0229	BVD0218-00 VENTLINE FAN MOTOR	1.00	29.83	29.83

Other Services

Code	Description	Qty	Price	Total
SS	SHOP SUPPLIES	1.00	12.68	12.68

Subtotal for Job #1: 98.01

Job #2 - External

COMPLAINT: WINDOW GASKETS IN SLIDEOUT KEEP COMING OUT ON THE RIGHT FROM INSIDE THE CAMPER

CAUSE: Window gasket keeps coming out.

CORRECTION: After inspection of gasket i found that the gasket was not installed correctly. I installed it correctly and it works properly. And the inside gasket that runs down the side on the inside was out of its track and causing the gasket around the window to come off because it was going out with the slideroom. But I ran it in and out several times and both gaskets stayed where they should

Labor

Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	JTW	N/C

Subtotal for Job #2: 0.00

Job #3 - Warranty

COMPLAINT: CHECK HINGES ON DOORS OF DINETTE BROKEN DOOR CLOSEST TO THE BUNKHOUSE

CAUSE: Dinette cabinet door hinges loose

Customer #: 55254
ENNIS, LARRY





CORRECTION: Inspect the dinette cabinet door and found top hi g screws were missing. So t painted new longer screws and it works properly now. After fixing this one I noticed the other cabinet under dinette was not staying closed. So I adjusted the latch and it works properly now

Labor

Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	JTW	18.50
Subtotal for Job #3:			18.50

Job #4 - Warranty

COMPLAINT: THE BLIND WILL NOT OPEN AND IT IS ON THE SAME WINDOW WITH THE SEAL

CAUSE: Blind won't stay up

CORRECTION: After inspection of the blind. It was just out of adjustment. So I tightened up both strings. And it works properly now

Labor

Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	JTW	0.00
Z990	MISC LABOUR CODE (EXTERNAL)	JTW	9.25
Subtotal for Job #4:			9.25

Job #5 - Warranty

COMPLAINT: CHECK SINK CAUCKING, STATES IT APPEARS IT IS SINKING

CAUSE: Sink may be dropping

CORRECTION: After inspection I found sink is secure. And checked no open recalls on the sink. Cleaned and re chalked. Sink looks good

Labor

Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	JTW	37.00

Parts

Part #	Description	Qty	Price	Total
500629	SIKASIL N PLUS WHITE	1.00	8.89	8.89
Subtotal for Job #5:				45.89

Job #6 - Warranty

COMPLAINT: GASKET ON SLIDE WILL NOT FLIP IN WHEN SLIDE COMES IN, SAME SIDE AS WINDOW GASKET ISSUE

CAUSE: Gasket on slide room

CORRECTION: Customer stated gasket on slide room won't go in when room goes in. The gasket on the bottom is supposed to be like that to keep the water from the tires out

Labor

Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	JTW	55.50
Subtotal for Job #6:			55.50

Job #7 - Warranty

COMPLAINT: BLACK TANK FLUSH CHECK VALVE IS LEAKING UNDER THE BATHROOM SINK

CAUSE: Black tank flush valve

CORRECTION: After inspection of it is found that the line was loose. I pointed to the line that was loose in my picture. After I tightened it up and it ran water through it I couldn't is replicate the leak. It works properly now.





Labor			
Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	JTW	55.50
Subtotal for Job #7:			55.50

Job #8 - Warranty

COMPLAINT: USB JACK BY ENTRANCE DOOR DOES NOT WORK

CAUSE: USB port not working

CORRECTION: After inspection of the USB port. I found that the USB port is working properly it is the C type port that's not working. Replaced part and it works properly now

Labor				
Code	Description	Mechanic		Total
Z990	MISC LABOUR CODE (EXTERNAL)	JTW		27.75
Z990	MISC LABOUR CODE (EXTERNAL)	JTW		27.75
Parts				
Part #	Description	Qty	Price	Total
F100324093	USB, 12V USB/C-PORT COMBO CHARGER BL	1.00	5.31	5.31
Subtotal for Job #8:				60.81

Job #9 - External

COMPLAINT: CHECK ODOR IN OUTDOOR KITCHEN, STATES IT IS LIKE A PAINT FUME

CAUSE: Check outdoor kitchen area

CORRECTION: Customer stated that outdoor kitchen area smells like paint fumes. After inspection i don't smell paint fumes more like new linoleum or a new smell.

Labor				
Code	Description	Mechanic		Total
Z990	MISC LABOUR CODE (EXTERNAL)	JTW		N/C
Subtotal for Job #9:				0.00

Job #10 - External

COMPLAINT: ENTRY DOOR NEEDS ADJUSTED HAS A GAP THE BOTTOM LEFT CORNER

CAUSE: Adjust the entry

CORRECTION: Inspection of the entry door. It was hitting at the bottom left and on the striker. I adjusted the door and the striker. And painted the marks the door left in the frame. The door works properly now.

Labor				
Code	Description	Mechanic		Total
Z990	MISC LABOUR CODE (EXTERNAL)	JTW		N/C
Subtotal for Job #10:				0.00

Parts Total:	44.03
Labour Total:	286.75
Sublet Total:	0.00
Extras Total:	12.68
WORK ORDER TOTAL:	343.46



Thank you for being a valued customer. We appreciate your business.

All labor is guaranteed for 90 days from invoice date. Guarantee is limited to work performed. Consequential damages are not covered. All guaranteed work must be completed in our service department.

Customer Signature : _____

Date: 12 Jul 2025

W/O: 77245
Promised Date: 31 JUL 25



Customer #: 55254
ENNIS, LARRY

