

BASDEN RV CENTER, INC dba AMERICAN RV
600 E. Baseline Rd.
Evansville, IN
US
47725
812-867-5200

WARRANTY CLAIM # 77252
MANUFACTURER'S CLAIM #:

Manufacturer: 10024 - FOREST RIVER TRAVEL TRAILER
Customer: 1000 - BASDEN'S AMERICAN RV
Address: 600 E. BASELINE RD. EVANSVILLE, IN
USA
47725

Phone:

Stock Number: 11638 - 2026 CHEROKEE WOLF PUP 17SC 5ZT2CKFC7TY039024

VIN: 5ZT2CKFC7TY039024 HIN: SER#: 5ZT2CKFC7TY039024

Mileage: 0

Work Order Comp: 18 JUL 25

Auth. No:

Dealer #:

Warr. Date:

Work Order Date: 08 JUL 25

Inv #: 420053

WO # Job # Description JOB INFORMATION

77252 1 THE ENTRY DOOR NEEDS ADJUST.
Entry door
The sliding door was needing adjustments so I moved the black
striker over now the door will shut properly and smoother

77252 2 THE ENTRY DOOR FRAME IS COMING APART
Frame on front door
The frame of the front entry was coming off so I took it off
completely and took out all the nails and then I took the trim
and took some wood putty and filled in the spots where i shot in
new nails up and also used a touch up pin to blend in the color
and the frame is now in the correct spot and not pushed out

77252 3 THE KITCHEN CABINET WOOD IS BROKEN.
Broken door
Fixed the door that was broken inside the cabnet took the screw
that caused the board to warp and split

77252 4 TOILET SEAT IS BROKEN
Toilet seat
The toilet seat is loose from the factory and so I snapped it
back down into place and pushed it together so the seat would not
be loose and be broken

77252 5 THE SLIDE ROOM RAIL IS BENT
Slide room

Claim : 77252

 WO # Job # Description JOB INFORMATION

Ran slide room in and also took a small amount of tape off of the slide room slide and also held in slide room after room came in for 5 seconds for motors to sync then I also checked it from outside and didn't see or noticed anything that would make the room bow or bend so I had another tech push slide out button and the bend or bow isn't on the camper so it shuts properly now

77252 7 THERE ARE SPOTS ON THE CEILING THAT NEED TO BE TOUCHED UP
 Ceiling marks
 Took some white putty to cover up marks in ceiling that were noticed by technician

77252 8 THE SIDE CABINET ON THE OFF DOOR SIDE OF THE BEDROOM IS BROKEN.
 Front door
 Front door was needing adjustments so I moved the striker and also moved the screws now door will shut properly

77252 10 THERE IS TRIM ON BOTH SIDES OF THE BATHROOM THAT ARE BROKEN.
 Bathroom door frame
 Got 5 staples and added to frame as well as added 3m adhesive tape to the back of the trim to insure that it wouldn't come loose and added screws back into the correct position now the trim is in correctly

 Lab Code Job# Description LABOUR Hrs Rate Total

Z990	1	MISC LABOUR CODE (EXTERNAL)		0.20	185.00	37.00
Z990	2	MISC LABOUR CODE (EXTERNAL)		0.30	185.00	55.50
Z990	2	MISC LABOUR CODE (EXTERNAL)		0.00	185.00	0.00
Z990	3	MISC LABOUR CODE (EXTERNAL)		0.30	185.00	55.50
Z990	4	MISC LABOUR CODE (EXTERNAL)		0.10	185.00	18.50
Z990	5	MISC LABOUR CODE (EXTERNAL)		0.00	185.00	0.00
Z990	5	MISC LABOUR CODE (EXTERNAL)		0.20	185.00	37.00
Z990	7	MISC LABOUR CODE (EXTERNAL)		0.10	185.00	18.50
Z990	8	MISC LABOUR CODE (EXTERNAL)		0.30	185.00	55.50
Z990	10	MISC LABOUR CODE (EXTERNAL)		0.00	185.00	0.00
Z990	10	MISC LABOUR CODE (EXTERNAL)		0.10	185.00	18.50

Parts Total: 0.00
 Labour Total: 296.00
 Sublet Total: 0.00
 Extras Total: 0.00

>>>> Claim Total: 296.00

Customer Signature: _____

Date: _____