



600 E. Baseline Rd.
Evansville, IN 47725

www.AmericanRVCenter.com

812.867.5200
FAX 812.868.1012

W/O: 77252
Promised Date:
24 JUL 25

CUSTOMER WORK ORDER

WO #: 77252

Customer: 1000 - BASDEN'S AMERICAN
RV -
Tag:
Author: BH
Location: 0721 CHECK PREAUTH

Stock #: 11638
Stock Desc: 2026 TT FOREST RIVER
CHEROKEE WOLF PUP 17SC
Chassis #: 5ZT2CKFC7TY039024
Serial #: 5ZT2CKFC7TY039024
Mileage: 0
Licence:

Invoice #:
Date In: 08 JUL 25
Promised: 31 JUL 25
Date Sched:
Completed: 18 JUL 25
Warr. Date:

Job #PDINTT - Internal

PDI - NEW TRAVEL TRAILER

Labor

Code	Description	Mechanic	Total
Z991	MISC LABOUR CODE (INTERNAL)	JLC	N/C
Z991	MISC LABOUR CODE (INTERNAL)	JLC	N/C
Z991	MISC LABOUR CODE (INTERNAL)	JLC	N/C
Z991	MISC LABOUR CODE (INTERNAL)	JLC	N/C
Z991	MISC LABOUR CODE (INTERNAL)	JLC	N/C

Parts

Part #	Description	Qty	Price	Total
13034	55362 STD BATTERY BOX	1.00	N/C	N/C

Other Services

Code	Description	Qty	Price	Total
SS	SHOP SUPPLIES	1.00	N/C	N/C
LPGI	LP - UNIT SALES	4.00	N/C	N/C

Subtotal for Job #PDINTT: 0.00

Job #1 - Warranty

COMPLAINT: THE ENTRY DOOR NEEDS ADJUST.

CAUSE: Entry door

CORRECTION: The sliding door was needing adjustments so I moved the black striker over now the door will shut properly and smoother

Labor

Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	JLC	37.00

Subtotal for Job #1: 37.00

Job #2 - Warranty

COMPLAINT: THE ENTRY DOOR FRAME IS COMING APART

CAUSE: Frame on front door

CORRECTION: The frame of the front entry was coming off so I took it off completely and took out all the nails and then I took the trim and took some wood putty and filled in the spots where i shot in new nails up and also used a touch up pin to blend in the color and the frame is now in the correct spot and not pushed out



Customer #: 1000
BASDEN'S AMERICAN RV,





Labor			
Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	JLC	55.50
Z990	MISC LABOUR CODE (EXTERNAL)	JLC	0.00
Subtotal for Job #2:			55.50

Job #3 - Warranty

COMPLAINT: THE KITCHEN CABINET WOOD IS BROKEN.

CAUSE: Broken door

CORRECTION: Fixed the door that was broken inside the cabinet took the screw that caused the board to warp and split

Labor			
Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	JLC	55.50
Subtotal for Job #3:			55.50

Job #4 - Warranty

COMPLAINT: TOILET SEAT IS BROKEN

CAUSE: Toilet seat

CORRECTION: The toilet seat is loose from the factory and so I snapped it back down into place and pushed it together so the seat would not be loose and be broken

Labor			
Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	JLC	18.50
Subtotal for Job #4:			18.50

Job #5 - Warranty

COMPLAINT: THE SLIDE ROOM RAIL IS BENT

CAUSE: Slide room

CORRECTION: Ran slide room in and also took a small amount of tape off of the slide room slide and also held in slide room after room came in for 5 seconds for motors to sync then I also checked it from outside and didn't see or noticed anything that would make the room bow or bend so I had another tech push slide out button and the bend or bow isn't on the camper so it shuts properly now

Labor			
Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	JLC	0.00
Z990	MISC LABOUR CODE (EXTERNAL)	JLC	37.00
Subtotal for Job #5:			37.00

Job #6 - Internal

COMPLAINT: THE FREEZER ISN'T GETTING COLD

CAUSE: Freezer

CORRECTION: Freezer wasn't getting cold due to the switch inside being changed from off to on and also it was on off grid which wasn't getting refrigerator cold when shore power wasn't hooked up so I put on a battery and left it on all night and now the refrigerator is cold with me without shore power hooked up

Labor			
Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	JLC	N/C
Z990	MISC LABOUR CODE (EXTERNAL)	JLC	N/C





Subtotal for Job #6: 0.00

Job #7 - Warranty

COMPLAINT: THERE ARE SPOTS ON THE CEILING THAT NEED TO BE TOUCHED UP

CAUSE: Ceiling marks

CORRECTION: Took some white putty to cover up marks in ceiling that were noticed by technician

Labor Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	JLC	18.50

Subtotal for Job #7: 18.50

Job #8 - Warranty

COMPLAINT: THE SIDE CABINET ON THE OFF DOOR SIDE OF THE BEDROOM IS BROKEN.

CAUSE: Front door

CORRECTION: Front door was needing adjustments so I moved the striker and also moved the screws now door will shut properly

Labor Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	JLC	55.50

Subtotal for Job #8: 55.50

Job #9 - Internal

COMPLAINT: THE BEDROOM WALL HAS SOME IMPERFECTIONS THAT CAN BE CORRECTED WITH PUTTY.

CAUSE: Bedroom blemishes

CORRECTION: Technician found some scratches and blemishes in wall so I took some putty and filled in scratches the best I could with some putty

Labor Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	JLC	N/C

Subtotal for Job #9: 0.00

Job #10 - Warranty

COMPLAINT: THERE IS TRIM ON BOTH SIDES OF THE BATHROOM THAT ARE BROKEN.

CAUSE: Bathroom door frame

CORRECTION: Got 5 staples and added to frame as well as added 3m adhesive tape to the back of the trim to insure that it wouldn't come loose and added screws back into the correct position now the trim is in correctly

Labor Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	JLC	0.00
Z990	MISC LABOUR CODE (EXTERNAL)	JLC	18.50

Subtotal for Job #10: 18.50

Job #11 - Internal

COMPLAINT: THERE ARE AREAS IN THE SHOWER THAT NEED SILICONE ADDED

CAUSE: Silicone sealer in bathroom





CORRECTION: Added silicone to spots in the bathroom in shower where the factory didn't get to to prevent water damage to the shower fixed it by adding sealer in open grooves

Labor

Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	JLC	N/C
Subtotal for Job #11:			0.00

Job #12 - Internal

COMPLAINT: THERE ARE IMPERFECTIONS ON THE LIVING ROOM TRIM THAT NEED TO HAVE PUTTY ADDED

CAUSE: Scratches

CORRECTION: There were areas on trim that were needing to be covered up by staple holes so I took some wood putty and also touch up pens and matched the best I could and covered up spots

Labor

Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	JLC	N/C
Z990	MISC LABOUR CODE (EXTERNAL)	JLC	N/C
Z990	MISC LABOUR CODE (EXTERNAL)	JLC	N/C
Subtotal for Job #12:			0.00

Parts Total:	0.00
Labour Total:	296.00
Sublet Total:	0.00
Extras Total:	0.00
WORK ORDER TOTAL:	296.00

Thank you for being a valued customer. We appreciate your business.

All labor is guaranteed for 90 days from invoice date. Guarantee is limited to work performed. Consequential damages are not covered. All guaranteed work must be completed in our service department.

Customer Signature : _____

Date: 18 Jul 2025

