

FOREST RIVER WARRANTY CLAIM FORM

DEALER ACCOUNT #	0005106	CLAIM STATUS	Authorized
BASDEN RV CENTER INC		CLAIM	2363560
DBA AMERICAN RV CENTER		CLAIM ORIGIN	WEB
600 E BASELINE ROAD		ORIGINAL CLAIM ID	
EVANSVILLE, IN 47725		VIN	5ZT2CARB1SU045761
USA		CHASSIS VIN	
		MILEAGE	0
Labor rate:	\$185.00	SITE/WAREHOUSE	103 / 103
OWNER INFORMATION		ITEM #	CAT261BHS-8
ALLEN R DUKE		DEALER RO #	77266
7954 LYDDANE BRIDGE RD S		CLAIM START DATE	07/11/2025
Owensboro, KY 42301		CLAIM END DATE	01/01/1900
USA			
Retail Date of Purchase	04/12/2025	WARRANTY EXPIRATION DATE	04/12/2026

Claim Line Details

Labor

Line# 1	Operation Code	Operational Description		
	30-95-01-00-000961	Free Standing Dinette Table - Drop Leaf Only - Interior/Dinette/Replace/No Tread Code		
	Complaint, Cause, Correction			
	Original Note : bhoffman@americanrvcenter.com, 2025-07-11 11:31:16 :: SCREWS CAME OUT OF TABLE screws out of dining table went inside camper found under the table top that it had 6 screws missing out of it. took one screw out to find correct screw for size. found screws and repalces all screws that had fallen out.			
Model#	Dlr Sub Hrs	0.20	Sub Labor Amt	\$37.00
Serial#	Appr Hrs	0.20	Appr Labor Amt	\$37.00
	Notes			

Labor

Line# 2	Operation Code	Operational Description		
	30-99-24-00-001015	Mini-Blind - Interior/Soft Goods/Repair/No Tread Code		
	Complaint, Cause, Correction			
	Original Note : bhoffman@americanrvcenter.com, 2025-07-11 11:32:45 :: MINI BLIND BEHIND THE COUCH WILL NOT STAY UP mini binds behind couch won't stay up went to mini blind behind couch and saw that the strings were not wrapped around cicrle hold for tension string for mini blind. moved the blinds up and wrapped strings around the pice on the bottom of blinds for tension. blinds stay open.			
Model#	Dlr Sub Hrs	0.15	Sub Labor Amt	\$27.75
Serial#	Appr Hrs	0.15	Appr Labor Amt	\$27.75
	Notes			
	AUTHORIZED AS REQUESTED.			

Labor

Line# 3	Operation Code	Operational Description		
	20-69-01-00-000703	Hold Back Latch, Catch, or Magnet - Exterior/Compartment Doors/Replace/No Tread Code		
	Complaint, Cause, Correction			
	Original Note : bhoffman@americanrvcenter.com, 2025-07-11 11:33:23 :: CUSTOMER ADVISES THAT WHEN OPENING THE STORAGE COMPARTMENT/DRAWER UNDER THE COUCH, ONE OF THE MAGNETIC KEEPERS COMES OUT WITH THE DRAWER AND IT SHOULD STAY ATTACHED TO THE COUCH SIDE. magent not staying on storage door under couch. took door off storage compartment under couch and three of the four stayed on door while one would stay on couch. took the magent and found that the screw holes had been stripped from the orginal placement. moved magent over to cover old spots and drilled screws into new placement. tested to make sure the magent would latch on to spot and stay on door when moved. magnet stayed on door and stuck to spot under couch.			
Model#	Dlr Sub Hrs	0.20	Sub Labor Amt	\$37.00

Serial#

Appr Hrs

0.20

Appr Labor Amt \$37.00

Notes

AUTHORIZED AS REQUESTED.

Submitted

Labor Amt	\$101.75
Parts & Freight	\$0.00
Total	\$101.75

Approved

Labor Amt	\$101.75
Parts & Freight	\$0.00
Total	\$101.75

DEALER

DATE

SIGNATURE

I certify that I have performed these repairs consistent with Forest River Policies.

CUSTOMER

DATE

SIGNATURE

All repairs described have been inspected and are satisfactory.