



600 E. Baseline Rd.
Evansville, IN 47725

www.AmericanRVCenter.com

812.867.5200
FAX 812.868.1012

W/O: 77273
Promised Date: 17 JUL 25

CUSTOMER WORK ORDER

WO #: 77273

Customer: 56006 - FAULKENBURG,
JAMES - 812-686-5246

Tag:

Author: BH

Location: 0802 CHECK PREAUTH

Stock #: 11565

Stock Desc: 2025 TT COACHMEN

CATALINA SUMMIT SERIES 164BHX

Chassis #: 5ZT2CAEC5SK010358

Serial #: 5ZT2CAEC5SK010358

Mileage:

Licence:

Invoice #:

Date In: 11 JUL 25

Promised: 17 JUL 25

Date Sched:

Completed: 31 JUL 25

Warr. Date: 17 JUL 25

Job #FPDINTT - Internal

COMPLAINT: FINAL PDI ON NEW TRAVEL TRAILERS

CAUSE: Final pdi

CORRECTION: Lug nuts torqued to spec. Air pressure correct in 2 tires. Running lights and tail lights work properly brakes and Emergency Brakes work properly. Installed new battery. Exterior inspection good. Roof inspection i only found one void the i filled with dicor self-leveling. But I had to touch up 3 of the 4 corners with black dicor non sag. Roof good now. Interior inspection hooked to city water to flush the water lines. Kitchen sink shower and toilet. All good on city water. Antenna works properly ac and furnace works properly refrigerator and stove and microwave works properly did my lp drop test on stove with furnace and water heater running. Had to make slite adjustment to regulator lp system works properly now. Protective flim still on refrigerator going to remove it. And bathroom door trim need a screw in it. Fresh tank was full already and the water was still in winterize mode and pink water is coming out on water pump but not when hooked to city water. After gluing the drain line it held good.

Labor

Code	Description	Mechanic	Total
PDINTT	PDI - NEW TRAVEL TRAILER	JTW	N/C
PDINTT	PDI - NEW TRAVEL TRAILER	JTW	N/C
PDINTT	PDI - NEW TRAVEL TRAILER	JTW	N/C

Parts

Part #	Description	Qty	Price	Total
DC-24	ADVANCE GROUP 24 DEEP CYCLE BATTERY	1.00	N/C	N/C

Subtotal for Job #FPDINTT: 0.00

Job #1 - Warranty

COMPLAINT: SEWER PLUMIMG IS LEAKING

CAUSE: Black pipe leaking by sewer connection

CORRECTION: After inspection of the dump pipe I found that there wasn't any glue on that joint. So I took the support strap off to get it to move and pulled it apart to put primer and glue on it a d re shot the strap. All good now

Labor

Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	JTW	55.50

Customer #: 56006
FAULKENBURG, JAMES



Subtotal for Job #1: 55.50

Job #2 - Internal

COMPLAINT: INSTALL CUSTOMER PROVIDED HITCH WORK

CAUSE: Install the customer supplied hitchwork.

CORRECTION: Installed customer supplied hitchwork.

Labor

Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	GAH	N/C

Subtotal for Job #2: 0.00

Job #3 - Internal

INSTALL CUSTOMER PROVIDED ECHO BRAKE CONTROL

Labor

Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	GAH	N/C

Subtotal for Job #3: 0.00

Parts Total: 0.00

Labour Total: 55.50

Sublet Total: 0.00

Extras Total: 0.00

WORK ORDER TOTAL: 55.50

Thank you for being a valued customer. We appreciate your business.

All labor is guaranteed for 90 days from invoice date. Guarantee is limited to work performed. Consequential damages are not covered. All guaranteed work must be completed in our service department.

Customer Signature : _____

Date: 31 Jul 2025

W/O: 77273
Promised Date: 17 JUL 25



Customer #: 56006
FAULKENBURG, JAMES

