

# FOREST RIVER WARRANTY CLAIM FORM

<b>DEALER ACCOUNT #</b>	0005106	<b>CLAIM STATUS</b>	Authorized
<b>BASDEN RV CENTER INC</b>		<b>CLAIM</b>	2378885
<b>DBA AMERICAN RV CENTER</b>		<b>CLAIM ORIGIN</b>	WEB
<b>600 E BASELINE ROAD</b>		<b>ORIGINAL CLAIM ID</b>	
<b>EVANSVILLE, IN 47725</b>		<b>VIN</b>	5ZT2CARB3TU046573
<b>USA</b>		<b>CHASSIS VIN</b>	
		<b>MILEAGE</b>	0
<b>Labor rate:</b>	\$185.00	<b>SITE/WAREHOUSE</b>	103 / 103
<b>OWNER INFORMATION</b>		<b>ITEM #</b>	CAT261BH-8
		<b>DEALER RO #</b>	77276
		<b>CLAIM START DATE</b>	07/24/2025
		<b>CLAIM END DATE</b>	01/01/1900

Retail Date of Purchase

WARRANTY EXPIRATION DATE

## Claim Line Details

### Labor

**Line# 1**

<b>Operation Code</b>	20-66-24-00-000658	<b>Operational Description</b>
<b>Complaint, Cause, Correction</b>	Entry Door - Exterior/Entry Doors/Repair/No Tread Code	
Original Note : bhoffman@americanrvcenter.com, 2025-07-24 16:32:14 :: ENTRY DOOR NEEDS ADJUSTED Front door Needing the front door readjusted and so I moved the handle over as well as the striker now the door will shut properly		
<b>Model#</b>	<b>Dlr Sub Hrs</b>	<b>Sub Labor Amt</b>
	0.30	\$55.50
<b>Serial#</b>	<b>Appr Hrs</b>	<b>Appr Labor Amt</b>
	0.30	\$55.50
<b>Notes</b>		
AUTHORIZED AS REQUESTED		

### Labor

**Line# 2**

<b>Operation Code</b>	30-103-24-00-001125	<b>Operational Description</b>
<b>Complaint, Cause, Correction</b>	Linoleum - Interior/Flooring/Repair/No Tread Code	
Original Note : bhoffman@americanrvcenter.com, 2025-07-24 16:44:07 :: SCRATCH UNDER STOVE AREA ON FLOORING Scratch on floor There was a scratch on the floor so I took some floor cleaner as well as took some putty and then rubbed it in and now scratch is barely to be seen		
<b>Model#</b>	<b>Dlr Sub Hrs</b>	<b>Sub Labor Amt</b>
	0.15	\$27.75
<b>Serial#</b>	<b>Appr Hrs</b>	<b>Appr Labor Amt</b>
	0.15	\$27.75
<b>Notes</b>		
AUTHORIZED AS REQUESTED		

### Labor

**Line# 3**

<b>Operation Code</b>	30-102-24-00-003061	<b>Operational Description</b>
<b>Complaint, Cause, Correction</b>	Ceiling Panel - Touchup - Interior/Panels, Ceilings, & Interior Moldings/Repair/No Tread Code	
Original Note : bhoffman@americanrvcenter.com, 2025-07-24 16:44:53 :: STAIN ON CEILING Stain on ceiling Took a cloth with some cleaner on it and rubbed on ceiling where stain was now the stain isn't there an the area is clean		
<b>Model#</b>	<b>Dlr Sub Hrs</b>	<b>Sub Labor Amt</b>
	0.10	\$18.50
<b>Serial#</b>	<b>Appr Hrs</b>	<b>Appr Labor Amt</b>
	0.10	\$18.50
<b>Notes</b>		

### Labor

**Line# 4**

<b>Operation Code</b>	20-43-01-00-000589	<b>Operational Description</b>
<b>Complaint, Cause, Correction</b>	Die Cut, Stripe, Decal, Graphic - Exterior/Exterior Miscellaneous/Replace/No Tread Code	
Original Note : bhoffman@americanrvcenter.com, 2025-07-24 16:45:51 :: NEW FRONT DECAL CATALINA TORN		

AND BUBBLED FOUND DECAL TORN AND NEEDS REPLACED

<b>Model#</b>	<b>Dlr Sub Hrs</b>	0.60	<b>Sub Labor Amt</b>	\$111.00
<b>Serial#</b>	<b>Appr Hrs</b>	0.50	<b>Appr Labor Amt</b>	\$92.50

**Notes**

EXCESSIVE AMOUNT REQUESTED. CHANGED TO SIMILAR REPAIR TIME FOR SIMILAR REPAIRS  
THE REQUESTED REPAIR CAN BE COMPLETED IN THE TIME ALLOTTED

**Labor**

Line# 5

<b>Operation Code</b>	<b>Operational Description</b>
20-46-19-00-000721	Window - Exterior/Windows/Reseal/No Tread Code

**Complaint, Cause, Correction**

Original Note : bhoffman@americanrvcenter.com, 2025-07-24 16:46:48 :: SILICONE ON WINDOWS OUTSIDE Add silicone Added silicone to all the windows that were needing it in spots that were bare or exposed

<b>Model#</b>	<b>Dlr Sub Hrs</b>	0.20	<b>Sub Labor Amt</b>	\$37.00
<b>Serial#</b>	<b>Appr Hrs</b>	0.20	<b>Appr Labor Amt</b>	\$37.00

**Notes**

<b>Submitted</b>	Labor Amt	\$249.75	<b>Approved</b>	Labor Amt	\$231.25
	Parts & Freight	\$0.00		Parts & Freight	\$0.00
	Total	\$249.75		Total	\$231.25

DEALER \_\_\_\_\_ DATE \_\_\_\_\_

SIGNATURE

I certify that I have performed these repairs consistent with Forest River Policies.

CUSTOMER \_\_\_\_\_ DATE \_\_\_\_\_

SIGNATURE

All repairs described have been inspected and are satisfactory.