



600 E. Baseline Rd.
Evansville, IN 47725

www.AmericanRVCenter.com

812.867.5200
FAX 812.868.1012

W/O: 77294
Promised Date: 47 III 25



Customer #: 56015
FONSECA PEREZ, YELINA



CUSTOMER WORK ORDER

WO #: 77294

Customer: 56015 - FONSECA PEREZ,
YELINA - 786-230-0750

Tag:

Author: BH

Location: 0730 BH TO CLOSE

Stock #: 11619

Stock Desc: 2026 TT FOREST RIVER

CHEROKEE WOLF DEN 304SR

Chassis #: 4X4TCKF27TX166952

Serial #: 4X4TCKF27TX166952

Mileage:

Licence:

Invoice #:

Date In: 14 JUL 25

Promised: 17 JUL 25

Date Sched:

Completed: 30 JUL 25

Warr. Date: 17 JUL 25

Job #FPDINTT - Internal

COMPLAINT: FINAL PDI ON NEW TRAVEL TRAILERS

CAUSE: Final pdi

CORRECTION: Lug nuts torqued to spec running lights and tail lights work properly brakes and Emergency Brakes work properly. Installed a new battery. Exterior inspection found a couple voids around some lights that I'm am going to fill with silicone. Exterior inspection looks good now. Roof inspection found a couple voids in the sealer and I filled with dicor self-leveling roof inspection completed. Interior inspection stove and microwave works properly refrigerator works properly ac works properly. Hooked to city water and flushed out all the lines. Added 1/3 to fresh tank and it keeps blowingthe fuse at the water pump when water heater is switchedback to cold. . Removed packing tape and foam from microwave refrigerator and outside refrigerator and ice maker and put paperwork in drawer. Did my lp drop test on the stove with the water heater and furnace running. Water pump issue is fixed we ran a separate power wire to water heater because water pump and water heater was running off the same hot wire they both are working properly now. Trim pannel on the back of the sink is bowed out. Took board off and cut it shorter. Looks better now

Labor

Code	Description	Mechanic	Total
PDINTT	PDI - NEW TRAVEL TRAILER	JTW	N/C
PDINTT	PDI - NEW TRAVEL TRAILER	JTW	N/C
PDINTT	PDI - NEW TRAVEL TRAILER	JTW	N/C
PDINTT	PDI - NEW TRAVEL TRAILER	JTW	N/C

Parts

Part #	Description	Qty	Price	Total
DC-24	ADVANCE GROUP 24 DEEP CYCLE BATTERY	1.00	N/C	N/C
5516	A10-3050FHVP 30M-50F PIGTAIL	1.00	N/C	N/C

Subtotal for Job #FPDINTT: 0.00

Job #DELUXE - Internal

DELUXE STARTER KIT





Parts				
Part #	Description	Qty	Price	Total
44722	DELUXE STARTER KIT	1.00	N/C	N/C
Subtotal for Job #DELUXE:				0.00

Job #EQUALIZER1000 - Internal

COMPLAINT: INSTALL 1000# EQUALIZER HITCH

CAUSE: Install hitch
Setup hitchwork for delivery

CORRECTION: Installed brackets to the camper and put the rest of the hitch in front compartment
Installed hitch on truck and setup the hitch hight. I hooked up to the trailer and adjusted the hitch as needed.

Labor			
Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	GAH	N/C
Z990	MISC LABOUR CODE (EXTERNAL)	JTW	N/C

Parts				
Part #	Description	Qty	Price	Total
710831	EQUALIZER 1000#/10000# ADJ. HITCH	1.00	N/C	N/C

Other Services				
Code	Description	Qty	Price	Total
SS	SHOP SUPPLIES	0.00	N/C	N/C

Subtotal for Job #EQUALIZER1000: 0.00

Job #1 - Warranty

COMPLAINT: FUSE GOING TO WATER PUMP IS BLOWING

CAUSE: Water pump and water heater on same power source

CORRECTION: We traced the wires down and found that the water pump and water heater was running off the same power wire. And it was causing the water pump to blow the 10 amp fuse at the water pump after going from hot water to cold. So we installed a designated hot wire for the water heater. So to do that we had to run wires from the breaker box down through the floor through the under belly of the camera and connect them to the water heater. Then we had to disconnect the hot wire that ran from the water heater to the control board on the wall in the camper for safety purposes. Then I had to put up the under belly and re foam the holes to seal it back like it was. Water pump and water heater is working properly now.

Labor			
Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	JTW	370.00
Z990	MISC LABOUR CODE (EXTERNAL)	JTW	92.50

Subtotal for Job #1: 462.50

Job #WALK - Internal

COMPLAINT: WALK THRU

CAUSE: walk through

CORRECTION: shower customer all features on unit. shower customer how to use and connect to the hitch to the truck. set brake controller up and pulled unit out front.

Labor			
Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	ZMS	N/C
Z990	MISC LABOUR CODE (EXTERNAL)	ZMS	N/C



Subtotal for Job #WALK: 0.00

Job #2 - Internal

COMPLAINT: THE SHOWER SURROUND NEEDS TO BE SEALED.

CAUSE: Seal shower surround.

CORRECTION: Touched up silicone on shower surround.

Labor

Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	ZMS	N/C

Subtotal for Job #2: 0.00

Parts Total: 0.00

Labour Total: 462.50

Sublet Total: 0.00

Extras Total: 0.00

WORK ORDER TOTAL: 462.50

Thank you for being a valued customer. We appreciate your business.

All labor is guaranteed for 90 days from invoice date. Guarantee is limited to work performed. Consequential damages are not covered. All guaranteed work must be completed in our service department.

Customer Signature : _____

Date: 30 Jul 2025

W/O: 77294
Promised Date: 17 JUL 25



Customer #: 56015
FONSECA PEREZ, YELINA

