

BASDEN RV CENTER, INC dba AMERICAN RV  
600 E. Baseline Rd.  
Evansville, IN  
US  
47725  
812-867-5200

WARRANTY CLAIM # 77309  
MANUFACTURER'S CLAIM #:

Manufacturer: 10024 - FOREST RIVER TRAVEL TRAILER  
Customer: 55472 - JASON EADS  
Address: 1202 MEADLY CT  
LAWRENCEBURG, KY  
40342

Phone:

Stock Number: 2022 CATALINA

VIN:

HIN:

SER#: 5ZT2CATB7NX026014

Mileage:

Work Order Comp: 21 JUL 25

Auth. No:

Dealer #:

Warr. Date:

Work Order Date: 16 JUL 25      Inv #: 420148

\*\*\*\*\*

WO #      Job #      Description      JOB INFORMATION

\*\*\*\*\*

77309      2      CEILING VENT IN BATHROOM IS LEAKING.REPLACE BOTH VENT COVERS  
Replacement of the damaged vent lids  
Went to each vent and opened then unthe trim ring. When tongue  
the roof and pulled off the vent lids and matched with new from  
parts department. Clipped on the new vent lids and assembled the  
inside ofnthe vent.

77309      5      INSTALL ROOF VENT COVERS  
New vent lid covers  
Received vent lid covers from the parts department. Opened the  
vent lids. Went on the roof then mounted the brackets to hold the  
covers. Bolted down the vent covers and went inside the camper to  
check for clearance.

77309      1      CAMPER HAS LEAK IN BATHROOM AND RUNS INTO LIVING ROOM WHEN ON  
CITY WATER.  
Vacuum breaker for the black tank flush = stink bugs  
Went into the bedroom and removed the drawers from the wall. Back  
behind the drawers is the vacuum breaker to the black tank flush.  
Connected the garden hose to the black tank flush. Had another  
tech turn on the water while inspecting and checked for a leak.  
Found the vacuum breaker was leaking. Unscrewed the vacuum  
breaker and found the stink bugs inside the vacuum breaker.  
Cleaned out the vacuum breaker and screwed it back on the water  
lines. Had another tech turn on the water, and no leaks occurred  
after this fix. Disconnected the hose from the black tank flush.

Claim : 77309

\*\*\*\*\*  
 WO #      Job #      Description      JOB INFORMATION  
 \*\*\*\*\*

Connected the garden hose to the city water and checked for leaks, no leaks occurred.

77309      3      KITCHEN BLINDS ARE FALLING DOWN.  
 Dinette blinds  
 Checked all the blinds. Found only the dinette blinds that wouldn't stay up. Tightened the tension strings, now the blind stays up.

77309      4      CHECK FRESH WATER TANK  
 Fresh tank  
 Checked the fresh tank found it had water. Opened the drain to the fresh tank.

\*\*\*\*\*

Part No	Job#	Description	PARTS	Qty	Price	Total
CMC40182	2	40182 PW VENT LID VENTLINE '08 UP		2.00	14.88	29.76
CMC40431	5	CAMCO VENT COVER - WHITE		0.00	29.76	0.00

\*\*\*\*\*

\*\*\*\*\*

Lab Code	Job#	Description	LABOUR	Hrs	Rate	Total
Z990	2	MISC LABOUR CODE (EXTERNAL)		0.50	185.00	92.50
Z990	5	MISC LABOUR CODE (EXTERNAL)		0.50	185.00	92.50
Z990	1	MISC LABOUR CODE (EXTERNAL)		0.64	185.00	118.40
Z990	3	MISC LABOUR CODE (EXTERNAL)		0.00	185.00	0.00
Z990	3	MISC LABOUR CODE (EXTERNAL)		0.20	185.00	37.00
Z990	4	MISC LABOUR CODE (EXTERNAL)		0.30	185.00	55.50

\*\*\*\*\*

\*\*\*\*\*

Excode	Job#	Description	EXTRAS	Qty	Price	Total
SS	1	SHOP SUPPLIES		1.00	0.00	0.00

\*\*\*\*\*

Parts Total:            29.76  
 Labour Total:         395.90  
 Sublet Total:         0.00  
 Extras Total:         0.00

>>>> Claim Total:         425.66

Customer Signature: \_\_\_\_\_

Date: \_\_\_\_\_