

FOREST RIVER WARRANTY CLAIM FORM

DEALER ACCOUNT # 0005106
 BASDEN RV CENTER INC
 DBA AMERICAN RV CENTER
 600 E BASELINE ROAD
 EVANSVILLE, IN 47725
 USA

CLAIM STATUS Authorized
 CLAIM 2373335
 CLAIM ORIGIN WEB
 ORIGINAL CLAIM ID
 VIN 5ZT2CATB7NX026014
 CHASSIS VIN
 MILEAGE 0
 SITE/WAREHOUSE 205 / 205
 ITEM # ACAT283RKSLE
 DEALER RO # 77309
 CLAIM START DATE 07/21/2025
 CLAIM END DATE 01/01/1900

Labor rate: \$185.00

OWNER INFORMATION

JASON EADS
 1202 MELANIE COURT
 Lawrenceburg, KY 40342
 USA

Retail Date of Purchase 05/03/2023

WARRANTY EXPIRATION DATE 05/03/2024

Claim Line Details

Labor

Line# 1 **Operation Code** **Operational Description**
 60-138-01-00-001537 Black Tank No Fuss Flush Valve - Plumbing/Drainage System/Replace/No Tread Code

Complaint, Cause, Correction
 Original Note : bhoffman@americanrvcenter.com, 2025-07-21 11:32:04 :: CAMPER HAS LEAK IN BATHROOM AND RUNS INTO LIVING ROOM WHEN ON CITY WATER. Vacuum breaker for the black tank flush = stink bugs Went into the bedroom and removed the drawers from the wall. Back behind the drawers is the vacuum breaker to the black tank flush. Connected the garden hose to the black tank flush. Had another tech turn on the water while inspecting and checked for a leak. Found the vacuum breaker was leaking. Unscrewed the vacuum breaker and found the stink bugs inside the vacuum breaker. Cleaned out the vacuum breaker and screwed it back on the water lines. Had another tech turn on the water, and no leaks occurred after this fix. Disconnected the hose from the black tank flush. Connected the garden hose to the city water and checked for leaks, no leaks occurred.

Model# **Dir Sub Hrs** 0.64 **Sub Labor Amt** \$118.40
Serial# **Appr Hrs** 0.64 **Appr Labor Amt** \$118.40

Notes
 AUTHORIZED AS REQUESTED. GOODWILL

Labor

Line# 2 **Operation Code** **Operational Description**
 20-89-01-00-000881 MaxxAir Lid - Exterior/Power Roof Vent (MaxxAir)/Replace/No Tread Code

Complaint, Cause, Correction
 Original Note : bhoffman@americanrvcenter.com, 2025-07-21 11:33:33 :: CEILING VENT IN BATHROOM IS LEAKING.REPLACE BOTH VENT COVERS Replacement of the damaged vent lids Went to each vent and opened then unthe trim ring. When tongue the roof and pulled off the vent lids and matched with new from parts department. Clipped on the new vent lids and assembled the inside ofnthe vent. Additional Note : bhoffman@americanrvcenter.com, 2025-07-21 11:34:55 :: WE REPLACED 2

Model# #2 **Dir Sub Hrs** 0.50 **Sub Labor Amt** \$92.50
Serial# REPLACED **Appr Hrs** 0.50 **Appr Labor Amt** \$92.50

Notes
 AUTHORIZED AS REQUESTED. GOODWILL

Labor

Line# 3 **Operation Code** **Operational Description**
 30-99-24-00-001015 Mini-Blind - Interior/Soft Goods/Repair/No Tread Code

Complaint, Cause, Correction
 Original Note : bhoffman@americanrvcenter.com, 2025-07-21 11:35:09 :: KITCHEN BLINDS ARE FALLING DOWN. Dinette blinds Checked all the blinds. Found only the dinette blinds that wouldn't stay up. Tightened the tension strings, now the blind stays up.

Model#	Dlr Sub Hrs	0.20	Sub Labor Amt	\$37.00
Serial#	Appr Hrs	0.20	Appr Labor Amt	\$37.00

Notes
 AUTHORIZED AS REQUESTED. GOODWILL

Labor

Line# 4

Operation Code	Operational Description
60-136-24-00-001497	Fresh Water Tank - Plumbing/Fresh Water Supply/Repair/No Tread Code
Complaint, Cause, Correction	
Original Note : bhoffman@americanrvcenter.com, 2025-07-21 11:35:38 :: CHECK FRESH WATER TANK Fresh tank Checked the fresh tank found it had water. Opened the drain to the fresh tank. Additional Note : bhoffman@americanrvcenter.com, 2025-07-21 11:35:56 :: DIAG	

Model#	Dlr Sub Hrs	0.30	Sub Labor Amt	\$55.50
Serial#	Appr Hrs	0.30	Appr Labor Amt	\$55.50

Notes
 AUTHORIZED AS REQUESTED. GOODWILL

Labor

Line# 5

Operation Code	Operational Description
20-89-01-00-000881	MaxxAir Lid - Exterior/Power Roof Vent (MaxxAir)/Replace/No Tread Code
Complaint, Cause, Correction	
Original Note : bhoffman@americanrvcenter.com, 2025-07-21 11:36:15 :: INSTALL ROOF VENT COVERS New vent lid covers Received vent lid covers from the parts department. Opened the vent lids. Went on the roof then mounted the brackets to hold the covers. Bolted down the vent covers and went inside the camper to check for clearance.	

Model# #2	Dlr Sub Hrs	0.50	Sub Labor Amt	\$92.50
Serial# REPLACED	Appr Hrs	0.50	Appr Labor Amt	\$92.50

Notes
 AUTHORIZED AS REQUESTED. GOODWILL

Submitted	Labor Amt	\$395.90
	Parts & Freight	\$0.00
	Total	\$395.90

Approved	Labor Amt	\$395.90
	Parts & Freight	\$0.00
	Total	\$395.90

DEALER **DATE**

SIGNATURE
 I certify that I have performed these repairs consistent with Forest River Policies.

CUSTOMER **DATE**

SIGNATURE
 All repairs described have been inspected and are satisfactory.