

BASDEN RV CENTER, INC dba AMERICAN RV  
600 E. Baseline Rd.  
Evansville, IN  
US  
47725  
812-867-5200

WARRANTY CLAIM # 77342  
MANUFACTURER'S CLAIM #:

Manufacturer: 10024 - FOREST RIVER TRAVEL TRAILER  
Customer: 53420 - KERRY A. KUEHN  
Address: 2900 OAK VIEW CT EVANSVILLE, IN

47711

Phone: 812-306-5091

Stock Number: 11522 - 2025 CATALINA 263BHCKLE 5ZT2CARB2SN300959

VIN: 5ZT2CARB2SN300959 HIN: SER#: 5ZT2CARB2SN300959

Mileage: 0 Work Order Comp: 26 AUG 25

Auth. No: Dealer #:

Warr. Date: 17 FEB 25 Work Order Date: 21 JUL 25 Inv #: 421515

\*\*\*\*\*

WO # Job # Description JOB INFORMATION

\*\*\*\*\*

77342 1 LEFT REAR WHEEL CENTER CAP BROKEN AND HUB CENTER IS DAMAGED  
\*\*UNIT IS IN "NO SPOT" STORAGE\*\*

Damaged center cap

Took pictures and put in po for a new center cap.

77342 5 SOMETHING FELL OFF THE TOP OF THE CAMPER AND CUSTOMER DOES NOT  
KNOW WHAT IT WAS

Antenna missing

Went to up the roof and took pictures. Found the antenna was  
missing. Checked for damage to the roof and the surrounding area  
but no damages was found.

77342 5V264 INCORRECT OVER CURRENT PROTECTION

Recall service

Took a picture of the front cap and checked for a vent lamps,  
none on the front cap. Only clearance lights. Camper has auto  
leveling-BAL LS 5.3. Unscrewed the 3/8 self tappers from the  
front underbelly as noted. Went inside the underbelly and took  
pictures of the setup for the circuit breaker. Got a new circuit  
breaker from parts department and a inline fuse for the awning.  
Added another circuit breaker to the front and tested the  
leveling jacks. Screwed up the underbelly and added spray foam to  
seal up as it was. Went to the front side of the panel for the  
awning switch. Pulled off the awning wire that twas yellow.  
Pulled off the wire and cut off the terminal and crimped in the  
inline fuse. Ran the awning out and in after repair. Screwed the

Claim : 77342

\*\*\*\*\*  
 WO # Job # Description JOB INFORMATION  
 \*\*\*\*\*

panel back to the cabinet.

77342 2 THE LOCK ON THE MAIN ENTRY DOOR WILL NOT DEAD BOLT LOCK  
 Latch plate was upside down  
 Unlocked the entry door but not the deadbolt. Opened the entry door and flipped the deadbolt latch out, then pushed against the latch plate and marked where it was hitting. Noticed the latch plate was upside-down. Unscrewed the latch plate and flipped over and screwed in place. Checked the deadbolt alignment again and it cleared. Went inside the the camper to make sure the deadbolt would latch.

77342 4 CHECK A/C MAKING A FUNNY NOISE  
 Loose duct tape  
 Plugged in the shore power then went inside the camper. Turned the ac on to cool and you could hear a noise coming from the discharge side of the ac. Pulled down the cover and took a picture of the duct tape flapping while the ac was running. Got more duct tape and taped up the other tape. Ran the ac again and the tape had stayed in place.

\*\*\*\*\*

Part No	Job#	Description	PARTS	Qty	Price	Total
APP014-122067	1	#014-122067-2	DUST PLUG 2K & 3.5K	1.00	2.23	2.23
F100424284	1	CENTER CAP, 6 LUG	3.75 SS AMERICA	1.00	9.79	9.79
7974	5	OMNI-DIRECTIONAL TV	ANTENNA	1.00	56.93	56.93
BDR31820	V264	Fuse Holder; ATO/ ATC	Blade Fuses	1.00	5.27	5.27
CUR58361	V264	16-3030 30A	CIRCUIT BREAKER	1.00	3.85	3.85

\*\*\*\*\*

Lab Code	Job#	Description	LABOUR	Hrs	Rate	Total
Z990	1	MISC LABOUR CODE	(EXTERNAL)	0.00	185.00	0.00
Z990	1	MISC LABOUR CODE	(EXTERNAL)	0.00	185.00	0.00
Z990	1	MISC LABOUR CODE	(EXTERNAL)	0.10	185.00	18.50
Z990	5	MISC LABOUR CODE	(EXTERNAL)	0.20	185.00	37.00
Z990	5	MISC LABOUR CODE	(EXTERNAL)	0.30	185.00	55.50
Z990	V264	MISC LABOUR CODE	(EXTERNAL)	0.00	185.00	0.00
Z990	V264	MISC LABOUR CODE	(EXTERNAL)	0.75	185.00	138.75
Z990	2	MISC LABOUR CODE	(EXTERNAL)	0.20	185.00	37.00
Z990	4	MISC LABOUR CODE	(EXTERNAL)	0.30	185.00	55.50

Parts Total: 78.07  
 Labour Total: 342.25  
 Sublet Total: 0.00  
 Extras Total: 0.00

>>>> Claim Total: 420.32

Customer Signature: \_\_\_\_\_

Date: \_\_\_\_\_

