



W/O: 77388
Promised Date: 24 JUL 25
600 E. Baseline Rd.
Evansville, IN 47725
www.AmericanRVCenter.com
812.867.5200
FAX 812.868.1012

CUSTOMER WORK ORDER

WO #: 77388

Customer: 50981 - COOMES, LARRY -
812-484-9361

Tag:

Author: BH

Location: 0806 CHECK PREAUTH

Stock #: 11571

Stock Desc: 2025 TT ALLIANCE RV

DELTA 294RK

Chassis #: 7M5TD3322SC305724

Serial #: 7M5TD3322SC305724

Mileage:

Licence:

Invoice #:

Date In: 25 JUL 25

Promised: 31 JUL 25

Date Sched:

Completed: 31 JUL 25

Warr. Date: 29 JUL 25

Job #FPDINTT - Internal

COMPLAINT: FINAL PDI ON NEW TRAVEL TRAILERS

CAUSE: Final pdi

CORRECTION: Lug nuts torqued to spec running lights and tail lights work properly brakes and Emergency Brakes work properly installed a new battery. Air pressure correct in all 5 tires. Exterior inspection looks good. Roof inspection found a couple voids in the sealer that I filled with dicor self-leveling and door side front corner the gutter was bent a little i fixed it and put some black dicor on a void there and some white dicor non sag on one spot there as well. Roof looks good now. Interior inspection put some white silicone in the two back corners of the shower it looked like there was a gag there for the customer. After running the shower I had a leak and looking into it further the shower drain was not connected so I had to remove the faucet and the shower surround and the shower pan. Got the pipe repaired and then put everything back. Hooked to city water and flushed out all the lines. Put 1/3 in the fresh tank for demonstration. Emptied black and both grey tanks. Stove and microwave works properly refrigerator works properly both ac works properly. Both tvs work and fireplace works properly remotes are in cabinet under TV. When running the water pump the lights flicker. It was a bad ground. Fixed it and the don't flicker. And i fixed the negative battery cables that went to the frame then connector was about to come off the screw. Grey tank #2 is missing the dump cap. So I got a new one installed. Had to adjust the awning arm so it would close properly.

Labor

Code	Description	Mechanic	Total
PDINTT	PDI - NEW TRAVEL TRAILER	JTW	N/C
Z990	MISC LABOUR CODE (EXTERNAL)	JTW	N/C
Z990	MISC LABOUR CODE (EXTERNAL)	JTW	N/C
Z990	MISC LABOUR CODE (EXTERNAL)	JTW	N/C
Z990	MISC LABOUR CODE (EXTERNAL)	JTW	N/C
Z990	MISC LABOUR CODE (EXTERNAL)	JTW	N/C

Parts

Part #	Description	Qty	Price	Total
DC-24	ADVANCE GROUP 24 DEEP CYCLE BATTERY	1.00	N/C	N/C
5516	A10-3050FHVP 30M-50F PIGTAIL	1.00	N/C	N/C
11-0429	39463 SEWER CAP W/HOSE CONNECTION	1.00	N/C	N/C

Subtotal for Job #FPDINTT: 0.00

Job #DELUXE - Internal

DELUXE STARTER KIT



Customer #: 50981
COOMES, LARRY



Parts				
Part #	Description	Qty	Price	Total
44722	DELUXE STARTER KIT	1.00	N/C	N/C
Subtotal for Job #DELUXE:				0.00

Job #1 - Warranty

COMPLAINT: THE SHOWER DRAIN IS LEAKING

CAUSE: Shower drain pipe was not attached and leaking

CORRECTION: On doing my flushing the water lines found a leak coming from under the shower. And I found that the pipe was not attached. So I had to remove the shower surround and the shower tub to cut the pipe off. Add new pipe and connect it properly.let the glue set up over night. And the silicone around the shower curtain. Tested it this morning and no leaks. Works properly now

Labor			
Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	JTW	0.00
Z990	MISC LABOUR CODE (EXTERNAL)	JTW	92.50
Z990	MISC LABOUR CODE (EXTERNAL)	JTW	370.00

Parts				
Part #	Description	Qty	Price	Total
428004	1.5" PIPE COUPLER	2.00	2.99	5.98
Subtotal for Job #1:				468.48

Job #2 - Warranty

COMPLAINT: WHEN RUNNING WATER PUMP THE LIGHTS FLICKER

CAUSE: Lights flicker when running the water pump

CORRECTION: I went straight to the ground wire on the water pump. Disconnect the ground wire and ran it straight to a ground by it self the lights did not flicker. So I checked the connector where it was at and put the wire back in the same connector and ran the water pump and lights did not flicker. So it was a bad connection. So they system works properly now.

Labor			
Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	JTW	33.30
Z990	MISC LABOUR CODE (EXTERNAL)	JTW	3.70
Subtotal for Job #2:			37.00

Job #3 - Warranty

COMPLAINT: REAR AWNING ARM HEAD IS HITTING ARM AND NOT LETTING IT CLOSE

CAUSE: Rear awning arm not closing properly

CORRECTION: Loosened the awning arm and shifted the arm just a bit so the awning would close properly. It now works properly

Labor Code	Description	Mechanic	Total
Z990	MISC LABOUR CODE (EXTERNAL)	JTW	55.50
Subtotal for Job #3:			55.50



W/O: 77388
Promised Date: 31 JUL 25

Parts Total:	5.98
Labour Total:	555.00
Sublet Total:	0.00
Extras Total:	0.00
WORK ORDER TOTAL:	560.98

Thank you for being a valued customer. We appreciate your business.

All labor is guaranteed for 90 days from invoice date. Guarantee is limited to work performed. Consequential damages are not covered. All guaranteed work must be completed in our service department.

Date: 06 Aug 2025

Customer Signature : _____

Customer Work
Order



Customer #: 50981
COOMES, LARRY

